



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNF 8166E

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	MTG CRACKED	\$755.00	\$520.80
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	\$36.90	\$36.90
1	REAR BUMPER REVERSE SENSOR	SERVICEABLE	\$202.00	\$0.00
1	REAR LAMP RH	MTG CRACKED	\$788.00	\$590.80
	LESS 10.00 / 20.00% DISCOUNT		(\$178.19)	(\$229.70)
			\$1,603.71	\$918.80

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER CLIP (SN)	NECESSARY	\$40.00	\$40.00
			\$40.00	\$40.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT DAMAGED PARTS		\$300.00	\$200.00
	REMOVE & REFIX/REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING		\$70.00	\$50.00
	WIRING /BULB CHECKING/FOCUSING		\$30.00	\$15.00
	TO PUTTY & SPRAY PAINT ACCIDENT DAMAGED PARTS AND ADJACENT PANELS		\$400.00	\$220.00
			\$800.00	\$485.00

GRAND TOTAL			\$2,443.71	\$1,443.80
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,150.00
--	---	--	--	-------------------

Report Ref No: CS/FCI24080358/Kqp3m4

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.