



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080358/Kqp3m4
16 RAFFLES QUAY	Date:	12/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2080U	Veh. Inspected	SNF 8166E
Policy No.	-	Coverage	0
Claim No.	D24007353MFCT	Excess	\$0.00
Assign From	SERENE	Assign Date	21/08/2024

2. Vehicle Details

Make & Model	HYUNDAI CN7 AVANTE 1.6 DOHC CVT S	C.C	1598
Engine No.	G4FMMU081722	Year of Reg.	24/06/2022
Chassis No.	KMHLN41ETNU240360	Colour	METALLIC BLACK
Odometer	32570 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	HANKOOK	7
L/H Front Tyre	205/55R16	HANKOOK	7
R/H Rear Tyre	205/55R16	HANKOOK	7
L/H Rear Tyre	205/55R16	HANKOOK	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2024	Inspection Date	28/08/2024
Survey held at	S & H MOTOR PTE LTD - 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days