

REF: CS/CTI24080359/Avh3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MVTo In Vehicle No: _____at W/O _____

of _____

Insured: **GBL 5421Z**

Policy No: _____

Claim's No: **SNM24D204713**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: They had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **GBD1401** Yr Regn: **2014, April**Type: M.Car / M.Cycle / Bus / Van Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Mit Canter** C.D. **2998**Colour: **Silver** A/C: Insured / Std / NI / NASp. Reading: **237609** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **FEA01BA00197**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: **195 R15C**R: **195 R15C**BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
TOYO / YOKO or **Duratur**

Front

Rear

R/Bal. **06** mm R/Bal. **06** mmL/Bal. **06** mm L/Bal. **06** mmD.O.A. **20/8/2024** D.O.I. **22/08/24**Survey held at **A-Tec**Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chms**13/11/24** Adrian confirmed LS \$4900 (Red 24,550.10, 83%)COE Expiry: **27/04/2029**Estimate given during: Yes ☒1st Survey: No ☐MV: **48K**PV: **33.2K**Nett: **14.8K****118W.**

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **7**

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)

Survey Fee:

Transportation:

3 + RS \$1

Photos

Others

Report Format:

Report Form / L.P. / C.

A-Tec Automotive Pte Ltd

8 Kaki Bukit Ave 4

#04-20 Premier

Singapore 415875

22 Aug 2024

GBD 140 J MITSUBISHI CANTER

No	Qty	Parts Description	Estimated Parts Price
1	1	Front wiper panel garnish	\$ 532.43
2	1	Front headlamp <i>auled</i>	\$ 2,666.00 ✓
3	1	Front headlamp bracket <i>neu</i>	\$ 141.22 +
4	1	Front headlamp lower seal <i>neu</i>	\$ 28.11 +
5	1	Front side cover <i>auled</i>	\$ 240.37 ✓
6	1	Front signal lamp <i>auled</i>	\$ 277.89 ✓
7	1	Front panel <i>Repr</i>	\$ 2,820.00 +
8	1	Front corner panel -RH <i>auled</i>	\$ 549.75 ✓
9	1	Front grille assy <i>auled</i>	\$ 1,178.08 ✓
10	1	Front grille logo <i>neu</i>	\$ 89.66 ✓
11	1	Front bumper <i>Replaced</i>	\$ 1,040.06 ✓
12	1	Front bumper stay <i>But</i>	\$ 211.93 ✓
13	1	Front bumper side -RH <i>missing</i>	\$ 368.94 ✓
14	1	Front door -RH <i>Repr</i>	\$ 1,686.91 +
15	1	Front door outer pillar <i>Repr</i>	\$ 1,045.86 +
16	1	Step panel garnish -RH <i>neu</i>	\$ 152.62 +
17	1	Rear tailgate lower member <i>neu</i>	\$ 891.55 +
18	1	Rear tailgate "70 KM/H" sticker	\$ 28.00 +
19	2	Rear taillamps <i>RH auled</i>	\$ 763.26 -380-
20	2	Rear taillamp panels <i>neu</i>	\$ 521.90 +
21	1	Rear number plate bracket <i>But</i>	\$ 120.65 ✓
22	1	Rear number plate lamp <i>neu</i>	\$ 118.28 +
			\$ 15,473.47
			less 25%
			\$ 3,868.37
			\$ 11,605.10

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1	Front grille clip <i>new</i>	\$ 40.00 <i>30</i>
2	1	Front number plate <i>new</i>	\$ 50.00 <i>+</i>
3	1	Front door lettering sticker <i>1</i>	\$ 45.00
4	1	Rear company sticker (1 set) <i>new</i>	\$ 300.00 <i>+</i>
5	1	Rear rubber stopper (1 set) <i>ut</i>	\$ 350.00 <i>200</i>
6	1	Rear step panel -wooden <i>could</i>	\$ 450.00 <i>250</i>
7	1	Rear number plate <i>But</i>	\$ 50.00 <i>30</i>
8	1	Rear reverse sensor (1 set) <i>new</i>	\$ 280.00 <i>+</i>
9	1	Rear wooden chassis plank <i>new</i>	\$ 1,800.00 <i>+</i>
10	2	Rear tailboard assy	\$ 7,000.00 <i>+</i>
11	1	Rear tailboard pillar frame assy <i>new</i>	\$ 2,400.00 <i>+</i>
12	1	Rear tailboard lock bar	\$ 950.00 <i>+</i>
			<u>\$ 13,715.00</u>

Total parts : \$ 25,320.10

No	Description	Labour Charges
1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00 <i>30</i>
2	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00 <i>30</i>
3	To remove and refit inner garnishes, inner trim to assist repair.	\$ 120.00 <i>+</i>
4	To remove and refit rear reverse sensor.	\$ 150.00 <i>+</i>
5	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 150.00 <i>+</i>
6	To apply undercoating on repaired and replaced panel.	\$ 150.00 <i>40</i>
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,800.00 <i>80</i>
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,600.00 <i>1000</i>

Total labour :

\$ 4,130.00

Total parts :

\$ 25,320.10

Total labour :

\$ 4,130.00

Total repair cost :

\$ 29,450.10

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
x/s 22/08/24
072p