9/11/24, 2:13 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24080360/RNP3M4

Date: 11/09/2024

REFERENCE

Handling Insurer: **ECICS Limited**

Policy No:

Claimant Vehicle No:

SMK3781Y

Insured Vehicle No:

SLH1172X

Odometer:

Date of Loss:

Colour:

Price:

20/08/2024

Nature of Claim:

ΤP

Claim No: DMPC2401093H/02/CT

G4FGKU126702

65300 km

KMHD841CMKU893824

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMK3781Y Reg No:

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS (A) Engine No: Reg. Date: 08/04/2019 (Man. Year: 2019) Chassis No:

> White 1591 cc

Engine Capacity: Market Value/New Car

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,448.00	959.20	488.80	33.76
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,420.00	1,220.00	2,200.00	64.33
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,868.00	2,179.20	2,688.80	55.23
	+ GST 9.00/9.00% (S\$)	438.12	196.13	241.99	55.23
	Nett Amount (S\$)	5,306.12	2,375.33	2,930.79	55.23

INSPECTION

Date of Assignment: 22/08/2024

KOMOCO MOTORS PTE LTD (HQ) Date Inspected: 27/08/2024 Inspected At:

253 ALEXANDRA ROAD, #01-01

SINGAPORE 159936

Estimated Period of Repair: 3.0 days

MOHD RASUL **HUEY YON** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Sep 2024)

Parts: 143 HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK3781Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part	No. Particulars	Condition	Repairer's	Amount
1	10	*BUMPER CLIP	Not Necessary	20.00 FL	*- FL
2	1	*COVER ASSY-RR BUMPER UPR	Cracked	598.00 FL	*598.00 FL
3	1	*REFLECTOR/REFLEX ASSY-RR RH	Scratched	222.00 FL	*222.00 FL
4	1	*COVER-RR BUMPER LWR	Deformed	354.00 FL	*354.00 FL
5	1	*GUARD-BUMPER REAR,RH	Not Necessary	15.00 FL	*- FL
6	1	*BRACKET-RR BUMPER SIDE MTG,RH	Not Necessary	30.00 FL	*- FL
7	1	*LAMP ASSY-LICENSE PLATE, LH	Not Necessary	44.00 FL	*- FL
8	1	*BEAM-RR BUMPER	Not Necessary	295.00 FL	*- FL
9	1	*BRACKET-RR RAIL LWR MTG	Not Necessary	4.00 FL	*- FL
10	1	*BRACKET-RR BEAM UPR MTG	Not Necessary	3.00 FL	*- FL
11	1	*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
12	1	*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
13	1	*SUNDRIES	Necessary	40.00 FS	*20.00 FS
F=Fr	anchise part. S	=SpcNett. L=ListItemDisc.	_		
			Sub Total (S\$)	1,765.00	1,194.00
		- List Item Disco	ount on L Items 20.00/20.00% (S\$)	317.00	234.80
			Total Parts (S\$)	1,448.00	959.20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			,
1	TO CARRY OUT ACCIDENT BODY REPAIR - RR BUMPER / LOWER SKID (\$460 PER DAY)	New	1,380.00	460.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS - FRT BUMPER/ LOWER SKID RR (\$380 PER DAY)	New	1,140.00	760.00
3	TO REFOCUS BOTH REAR HEAD LAMP (S.NETT)	New	40.00	0.00
4	TO PUT ON BENCH ALLIGNER TO FACILITATE REPAIR	New	480.00	0.00
5	TO RENEW RADAR ASSY & REPROGRAM (S.NETT)	New	380.00	0.00
	Gross Labou	ur Cost (S\$)	3,420.00	1,220.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >