

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBR 2111G

	REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	STEERING CONE	NOT NECESSARY	\$180.00	\$0.00	
1	FRONT PANEL COVER	CUT	\$200.00	\$200.00	
1	MIRROR LEFT	MISSING	\$150.00	\$90.00	
1	FRONT SIGNAL LIGHT	CUT	\$120.00	\$80.00	
1	HANDLE BAR LEFT	SERVICEABLE	\$280.00	\$0.00	
1	HANDLE BALANCER	CUT	\$80.00	\$35.00	
1	CLUTCH LEVER	CUT	\$120.00	\$118.00	
1	IU UNIT	NOT NECESSARY	\$155.80	\$0.00	
1	FUEL TANK COVER LEFT	CUT	\$250.00	\$250.00	
1	FUEL TANK COVER RIGHT	TO REPAIR SEE LABOUR	\$250.00	\$0.00	
1	GEAR PEDAL	CUT	\$180.00	\$148.00	
1	SEAT	TORN	\$200.00	\$166.00	
1	SEAT UNDER COVER LEFT	CUT	\$180.00	\$180.00	
1	REAR FAIRING COVER LEFT	CUT	\$220.00	\$220.00	
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$148.70)	
			\$2,565.80	\$1,338.30	

Labou	Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (
SPRAY COVERSET		\$500.00	\$350.0	
LABOUR. INCLUSIVE OF THE REPAIR OF FUEL TANK COVER RIGHT		\$500.00	\$320.0	
FORK ALIGNMENT	NOT NECESSARY	\$250.00	\$0.0	
		\$1,250.00	\$670.0	
GRAND TOTAL		\$3,815.80	\$2,008.3	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,600.0	
Report Ref No: CS/F0	Cl24060119/Unh3	1		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

CKS

MARCUS CHUA KANG SENG Licensed Appraiser