

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En A	utomobile
MS	MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI24060119/Unh3e2
	16 RAFFLES QUA		Date:	18/06/2024
	#42-01 HONG LEC	NG BUILDING	Code:	FCI2
1.		Policy Particula	ars :- THIRD PARTY CLAIN	
••	Insured Veh.	SHD 7169K	Veh. Inspected	" FBR 2111G
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24005264MFCT	Excess	\$0.00
	Assign From	AINI	Assign Date	18/06/2024
2.	Assign From		ehicle Details	10/00/2024
	Make & Model	YAMAHA R15	C.C	155
	Engine No.	G3K5E0153793	Year of Reg.	10/03/2020
	Chassis No.	ME1RG525BK0062091	Colour	RED
	Odometer	32452 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	Conditions of Tyres			
<u> </u>	I	Size	Make	Balance (mm)
	R/H Front Tyre	110-70-17	BRIDGESTONE	7
	L/H Front Tyre			
	R/H Rear Tyre	140-70-17	BRIDGESTONE	7
	L/H Rear Tyre			
4.	Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
DAM	AGES SEE DETAIL	S.		
5.	General Information			
	Accident Date	12/06/2024	Inspection Date	18/06/2024
	Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		
5a.			Remarks	
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	,			
		PERIOD FOR REPAIR: 3 Working Da	•	