

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

Not Authorised
 m/a/s
 28/8/24
 L/S \$5000
 3 days

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl
 #03-03 Singapore Land Tower,
 Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Estimate No: ES1602141
Date: 22 Apr 2024
Policy No: DMPG23006775
Veh Reg No: SMZ9824P
Make/Model: MAZDA CX-5 2.0 AT
 ELEGANCE 2WD I4
Chassis No: JM6KF2W7AM0676690
Engine No: PE31686659
Reg. Date: 27/05/2021

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 Lift Gate Tailgate Body 2D	1,850.50	1 PC	1,850.50 ✓	
2 Lift Gate Drain Plug	64.00	1 PC	64.00 X	
3 Lift Gate Bumper Rear windscreen molding	399.00	1 PC	399.00 ✓	
4 Bumper Cover Protector Tailgate outer garnish	453.20	1 PC	453.20 ✓	
5 Bumper Fastener	12.60	1 PC	12.60 X	
6 Lift Gate Hinge	463.10	1 PC	463.10 X	
7 Lift Gate Weather Strip	398.20	1 PC	398.20 X	
8 Upper Weather Strip	539.50	1 PC	539.50 X	
9 Upper Weather Strip Tailgate inner trim board	524.10	1 PC	524.10 ✓	
10 Lift Gate Windscreen	2,351.00	1 PC	2,351.00 X	
11 Lift Gate Power Cylinder Tailgate inner lock	693.50	1 PC	693.50 ✓	
12 Lift Gate Support Strut	315.90	1 PC	315.90 X	
13 Lift Gate Switch	219.30	1 PC	219.30 X	
14 Lock Actuator	374.50	1 PC	374.50 X	
15 Warning Buzzer	264.10	1 PC	264.10 X	
16 Control Module	1,365.00	1 PC	1,365.00 X	
17 Pinch Sensor -LH/RH Rear bumper release sensor	411.90	2 PC	823.80 200 S/N	
18 Rear Bumper	1,243.00	1 PC	1,243.00 ✓	1242.88
19 Rear Bumper Cover Cap	198.50	1 PC	198.50 ✓	
20 Rear Bumper Cover Protector	693.00	1 PC	693.00 X	
21 Rear Bumper Cover Centre Bracket	553.90	1 PC	553.90 X	
22 Tow Eye Cap	95.30	1 PC	95.30 X	
23 Retainer Bracket -LH/RH	385.10	2 PC	770.20 X	
24 Splash Shield -LH/RH	559.50	2 PC	1,119.00 X	
25 Rear Impact Bar bumper beam	1,025.00	1 PC	1,025.00 ✓	
26 Rear Bumper Stay -LH/RH	213.50	2 PC	427.00 X	
27 Reflector -LH/RH	399.80	2 PC	799.60 1 PC	
28 Filler	159.40	1 PC	159.40 X	
29 Under Cover	559.50	1 PC	559.50 X	
30 Bumper Cover Centre Bracket	859.30	1 PC	859.30 X	
31 Lift Gate Upper Molding	550.00	1 PC	550.00 X	
32 Lift Gate Upper Protector	735.50	1 PC	735.50 X	
33 Lift Gate Lower Molding	550.00	1 PC	550.00 X	
34 Lift Gate Lower Molding Protector	735.50	1 PC	735.50 X	
35 Mount Bracket	219.50	1 PC	219.50 X	
36 Trunk Mat	938.40	1 PC	938.40 X	
37 Support Lower -LH/RH	615.50	2 PC	1,231.00 X	

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl
 #03-03 Singapore Land Tower,
 Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Estimate No: ES1602141

Date: 22 Apr 2024

Policy No: DMPG23006775

Veh Reg No: SMZ9824P

Make/Model: MAZDA CX-5 2.0 AT
 ELEGANCE 2WD I4

Chassis No: JM6KF2W7AM0676690

Engine No: PE31686659

Reg. Date: 27/05/2021

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
38 Side Trim -LH/RH	^ ^ 1,650.10	2 PC	3,300.20 X	
39 Sill Plate	^ ^ 773.40	1 PC	773.40 X	
40 Tail Lamp Assy -LH/RH	^ ^ 930.40	2 PC	1,860.80 X	
41 Tail Lamp Protector -LH/RH	^ ^ 511.50	2 PC	1,023.00 X	
42 Support Bracket -LH/RH	^ ^ 1,300.50	2 PC	2,601.00 X	
43 Support Bracket Cap -LH/RH	^ ^ 899.50	2 PC	1,799.00 X	
44 Trunk Cover End Trim	^ ^ 657.10	1 PC	657.10 X	
45 Lift Gate Side Trim	^ ^ 1,565.00	2 PC	3,130.00 X	
46 Lift Gate Lower Trim	^ ^ 1,610.50	1 PC	1,610.50 X	
47 Lift Gate Upper Trim	^ ^ 1,600.40	1 PC	1,600.40 X	
48 Trim Clips	^ ^ 8.00	7 PC	56.00 X	
		(202	43,384.30	43,384.30
Net Price				
49 Rear Number Plate	scr 80.00	1 PC	80.00 35 s/n	
50 Rear Number Plate Bracket	NS 50.00	1 PC	50.00 X	
			130.00	130.00
Labour				
51 Labour to dismantle lift gate & renew lift gate .	580.00	1 -	580.00 60	
52 Labour to renew & refit bumper .	480.00	1 -	480.00 X	
53 Labour to reconnect & renew tail lamp .	200.00	1 -	200.00 20	
54 Labour to reconnect reverse buzzer & all sensors .	380.00	1 -	380.00 30	
55 Labour to renew lift gate hydraulic lift gate .	580.00	1 -	580.00 X	
56 Labour to knock ,weld & renew all accident affected area .	1,800.00	1 -	1,800.00 500	
57 Labour to renew & dismantle lift gate windscreen .	480.00	1 -	480.00 120	
58 To rust proofing on all affected area .	480.00	1 -	480.00 30	
59 To spray & painting on affected area .	1,200.00	1 -	1,200.00 800	
			6,180.00	6,180.00

P-544266
 202
 4434.13
 235
 1640
 6219.13
 202
 5047

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl

#03-03 Singapore Land Tower,

Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate No: ES1602141

Date: 22 Apr 2024

Policy No: DMPG23006775

Veh Reg No: SMZ9824P

Make/Model: MAZDA CX-5 2.0 AT
ELEGANCE 2WD I4

Chassis No: JM6KF2W7AM0676690

Engine No: PE31686659

Reg. Date: 27/05/2021

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 49,694.30
			Add GST @ 9%	4,472.49
			Total Amount Payable	<u>S\$ 54,166.79</u>

TOTAL: SINGAPORE DOLLAR FIFTY FOUR THOUSAND ONE HUNDRED SIXTY SIX AND CENTS SEVENTY NINE ONLY

**For HUP LIAN HUAT ENGINEERING
WORKS**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: