

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080365/UPA3Q2
Date: 18/11/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MPC0002340
Claimant Vehicle No :	FBQ624L	Insured Vehicle No :	SNP7592L
Date of Loss:	27/07/2024	Nature of Claim:	TP
		Claim No:	MPC2024D0009666

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ624L	Engine No:	G3J8E0120522
Make & Model:	YAMAHA GDR155A (AEROX), 155cc	Chassis No:	MH3SG4640KJ060028
Reg. Date:	22/07/2019 (Man. Year: 2019)	Odometer:	78208 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-80-14	Rear Tyre Size:	140-70-14
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,694.50	4,090.70	3,603.80	46.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	300.00	610.00	67.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,604.50	4,390.70	4,213.80	48.97
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	8,604.50	3,500.00	5,104.50	59.32
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
+ Other Costs (S\$)		40.00		
Nett Liability (S\$)		3,620.00		
Global Sum Settlement (S\$)		3,600.00		

INSPECTION

Date of Assignment:	22/08/2024	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	22/08/2024 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Oct 2024)	
Parts:	N/A	YAMAHA GDR155A (AEROX) 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ624L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Bent	980.00 FL	*780.00 FL
2	1		*FORK UNDER BRACKET	Bent	250.00 FL	*250.00 FL
3	1		*FRONT SPORT RIM	Serviceable	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	220.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	105.00 FL	*- FL
6	1		*SET SIDE MIRROR	Cracked	140.00 FL	*140.00 FL
7	1		*HANDLE -BAR	Bent	250.00 FL	*175.00 FL
8	1		*HANDLE -BAR COVER	Cracked	320.00 FL	*190.00 FL
9	1		*SET HANDLE -BAR BALANCER	Cut	130.00 FL	*60.00 FL
10	1		*SET HAND GRIP	Torn	95.00 FL	*95.00 FL
11	1		*BRAKE & CLUTCH LEVERS	O/S Cut / Bent	220.00 FL	*110.00 FL
12	1		*HEADLAMP (LED)	Cut	880.00 FL	*700.00 FL
13	1		*HEADLAMP COVER	Not Necessary	165.00 FL	*- FL
14	1		*SET FRONT SIGNALS	Not Necessary	180.00 FL	*- FL
15	1		*FOOTSTEP PANEL	Cut	255.00 FL	*175.00 FL
16	1		*FOOTSTEP LOWER PANEL	Cut	340.00 FL	*180.00 FL
17	1		*EXHAUST ASSY	Repair	680.00 FL	*- FL
18	1		*EXHAUST PROTECTOR	Cut	168.00 FL	*168.00 FL
19	1		*RADIATOR COVER	Not Necessary	167.00 FL	*- FL
20	1		*SET FAIRING COVER	Cracked	1,450.00 FL	*900.00 FL
21	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
22	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
23	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
24	1		*SET STEERING CONE	Necessary	120.00 FS	*60.00 FS
25	1		*REAR BOX	Cut	480.00 FS	*350.00 FS
26	1		*REAR BOX BRACKET	Cracked	180.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,449.00	4,483.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	754.50	392.30
Total Parts (\$\$)	7,694.50	4,090.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO REPAIR BODY FRAME	New	380.00	0.00
3	TO PROVIDE LABOUR	New	450.00	300.00
Gross Labour Cost (\$\$)			910.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >