

ASS. REC. BY:

REF:

SMR/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of 160 05-02 9051

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1.3.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SNJ 1932K Yr Regn: 05, 22

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

New E200 c.c. 1991

Colour:

m. Grey

A/C: Insured / Std / Nil / NA

Sp. Reading:

9061

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

WIK 21308023044282

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/45R18

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUH / I

TOYO / YOKO or

Hankook

Front

R/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

5/6/24

Rear

R/Bal.

9 6 mm

L/Bal.

9 6 mm

D.O.I.

11/6/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S FA

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

: Prel. Report

: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

) \$ + RS. SI

) Extras

) Others

Report Format:

mp Sum / I.B.I: (\$

TOTAL

Khmerh Clkle)
11/6/24

Not Arhain
Runny B4 pain
3 days



Estimation

Date 7/6/2024
Vehicle SNJ 1932K
Make/Model MERCEDES BENZ E200
Chassis No. W1K2130802B044282

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET	1	\$ 2,846.20	\$ 2,846.20
2	FRON FENDER LH	1	\$ 1,466.50	\$ 1,466.50
3	FRONT DOOR LH	1	\$ 1,988.20	\$ 1,988.20
4	FRONT DOOR HINGE LH	2	\$ 145.00	\$ 290.00
5	FRONT VIEW MIRROR ASSEMBLY LH	1	\$ 4,163.00	\$ 4,163.00
				\$ 10,753.90
			Less 10%	\$ 1,075.39
			Total	\$ 9,678.51

	S/Nett Items			
1	REAR FENDER CLIPS	1	\$ 80.00	\$ 80.00
2	REAR FENDER COWLING CLIPS	1	\$ 80.00	\$ 80.00
3	REAR FENDER INNER GARNISH CLIPS LH	1	\$ 80.00	\$ 80.00
4	REAR DOOR INNER TRIM CLIPS LH	1	\$ 80.00	\$ 80.00
			Total	\$ 320.00

	LABOUR			
1	SPRAY PAINT ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
3	TO PERFORM RUST PROOFING	1	\$ 180.00	\$ 180.00
4	TO TRANSFER FRONT DOOR MECHANISM	1	\$ 80.00	\$ 80.00
			Total	\$ 2,860.00

Parts Replacement Amount \$ 9,998.51
Total Amount For Labour \$ 2,860.00

Total Amount \$ 12,858.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from insurance Company

AP AUTOMOTIVE SERVICES PTE LTD

56 Loyang Way #04-04 Loyang Enterprise Building S508755 | UEN : 202022890H

Acknowledged by Repairer

Signature:

Date: