

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080371/UMA3Q2  
Date: 19/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747\_03  
Claimant Vehicle No : PC4415E Insured Vehicle No : SNL2687B  
Date of Loss: 19/08/2024 Nature of Claim: TP Claim No: MFL2024D0009689

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC4415E  
Make & Model: TOYOTA HIACE, 3.0 L SUPER GL DARK PRIME (A) Engine No: 1KD2563854  
Reg. Date: 02/02/2016 (Man. Year: 2015) Chassis No: KDH2118006550  
Colour: Silver Odometer: 309714 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
Front Left Side: Touring 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Touring 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,813.25	3,033.87	4,779.38	61.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,490.00	1,880.00	55.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,183.25	4,523.87	6,659.38	59.55
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	11,183.25	3,600.00	7,583.25	67.81
+ GST 9.00/9.00% (S\$)	1,006.49	324.00	682.49	67.81
Nett Amount (S\$)	12,189.74	3,924.00	8,265.74	67.81
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,351.25		
Global Sum Settlement (S\$)		4,350.00		

INSPECTION

Date of Assignment: 09/09/2024  
Date Inspected: 09/09/2024 Inspected At: Carsmith Private Limited (HQ)  
8 Kaki Bukit Ave 4, #04-35 Premier  
Singapore 415875  
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Oct 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 L SUPER GL DARK PRIME (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC4415E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*RAILING BARING	Not Necessary	320.00 FL	*- FL
2	1		*REAR FENDER RH	Badly Dented / Cracked	2,745.00 FL	*2,745.00 FL
3	1		*REAR FENDER INNER RH	Repair	3,210.00 FL	*- FL
4	1		*REAR BUMPER	Torn	625.00 FL	*625.00 FL
5	1		*TAILGATE	Not Necessary	1,365.00 FL	*- FL
6	1		*TAILGATE LOCK	Not Necessary	280.00 FL	*- FL
7	1		*TAIL LAMP RH	Cracked	640.00 FL	*428.00 FL
8	1		*TAIL LAMP LOWER GARNISH RH	Cut	270.00 FL	*180.50 FL
9	1		*REAR RIM RH	Not Necessary	500.00 FS	*- FS
10	1		*SIDE DOOR CLIP	Not Necessary	50.00 FS	*- FS
11	1		*TAILGATE CLIP	Not Necessary	52.00 FS	*- FS
12	1		*SEALANT REAR FENDER GLASS RH	Necessary	120.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	10,177.00 4,028.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,363.75 994.63
					Total Parts (\$\$)	7,813.25 3,033.87
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	New	300.00	20.00
2	REMOVE AND REFIX REAR REVERSE SENSOR	New	120.00	30.00
3	REMOVE AND REFIT AND RENEW REAR EXHAUST	New	150.00	0.00
4	REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING TRIM AND GARNISH ,SEAT CUSHION	New	300.00	100.00
5	PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1,200.00	800.00
6	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	1,200.00	500.00
7	APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	New	100.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,370.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >