

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080373/KMA3Q2**Date:** 26/09/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070026360
Claimant Vehicle No : GBJ1441C **Insured Vehicle No :** SMS2516L
 Date of Loss: 19/08/2024 Nature of Claim: TP Claim No: 7310624892SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1441C**
 Make & Model: KIA K2500 6M/T, 2.5 D (M) Engine No: D4CBJ699428
 Reg. Date: 04/01/2019 (Man. Year: 2018) Chassis No: KNCSJX76LK7327544
 Colour: White Odometer: 261022 km
 Engine Capacity: 2497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm
 Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 2,261.40 | 1,419.00 | 842.40 | 37.25 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,610.00 | 1,290.00 | 320.00 | 19.88 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 3,871.40 | 2,709.00 | 1,162.40 | 30.03 |
| Approved Total (Overridden) (S\$) | | 2,150.00 | | |
| (S\$) | 3,871.40 | 2,150.00 | 1,721.40 | 44.46 |
| + GST 9.00/9.00% (S\$) | 348.43 | 193.50 | 154.93 | 44.47 |
| Nett Amount (S\$) | 4,219.83 | 2,343.50 | 1,876.33 | 44.46 |
| + Loss of Use (4.0 x S\$60.00/day) (S\$) | | 240.00 | | |
| + Doc/Search Fee (S\$) | | 2.18 | | |
| Nett Liability (S\$) | | 2,585.68 | | |
| Global Sum Settlement (S\$) | | 2,580.00 | | |

INSPECTION

Date of Assignment: 23/08/2024
 Date Inspected: 23/08/2024 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Estimated Period of Repair: 4.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------|-------------|------------|------------|
| 1 | 1 | | *REAR STEP BAR | Bent | 326.00 FL | *326.00 FL |
| 2 | 1 | | *REAR NUMBER PLATE LAMP | Cracked | 29.00 FL | *29.00 FL |
| 3 | 1 | | *TAILLAMP | O/S Cracked | 392.00 FL | *196.00 FL |
| 4 | 1 | | *TAILLAMP HOUSING | O/S Bent | 290.00 FL | *145.00 FL |
| 5 | 1 | | *REAR EXHAUST PIPE | Bent | 464.00 FL | *464.00 FL |
| 6 | 1 | | *REAR TAILGATE | Repair | 595.00 FL | *- FL |
| 7 | 1 | | *REAR STEP CENTRE BEAM | Bent | 120.00 FS | *120.00 FS |
| 8 | 1 | | *STICKER 70KM/HR | Necessary | 10.00 FS | *10.00 FS |
| 9 | 1 | | *STICKER 13 PAX | Necessary | 10.00 FS | *10.00 FS |
| 10 | 1 | | *REAR NUMBER PLATE | Bent | 35.00 FS | *35.00 FS |
| 11 | 1 | | *SET REVERSE SENSOR | Cut | 200.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 2,471.00 | 1,535.00 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 209.60 | 116.00 |
| Total Parts (\$\$) | 2,261.40 | 1,419.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REAR NO PLATE LAMPS .TO KNOCKING & REPAIR TAILGATE ,TAILGATE LOWER MEMBER & REALIGN THE SAME | New | 700.00 | 550.00 |
| 2 | REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM | New | 60.00 | 60.00 |
| 3 | PUTTY & RESPRAY ON REAR BUMPER ,TAILGATE ,TAILGATE LOWER MEMBER & REAR BUMPER | New | 600.00 | 500.00 |
| 4 | TO REWRITE ADVERTISEMENT | New | 250.00 | 180.00 |
| Gross Labour Cost (\$\$) | | | 1,610.00 | 1,290.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >