

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080378/APA3Q2**Date:** 07/02/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900256603
Claimant Vehicle No :	SNG1660K	Insured Vehicle No :	SCE812L
Date of Loss:	15/08/2024	Nature of Claim:	TP
		Claim No:	7379927744SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG1660K	Engine No:	L13B1452615
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK31344167
Reg. Date:	11/04/2019 (Man. Year: 2018)	Odometer:	56119 km
Colour:	Black		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,519.04	5,214.40	4,304.64	45.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,240.00	2,080.00	3,160.00	60.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,759.04	7,294.40	7,464.64	50.58
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	14,759.04	5,800.00	8,959.04	60.70
+ GST 9.00/9.00% (S\$)	1,328.31	522.00	806.31	60.70
Nett Amount (S\$)	16,087.35	6,322.00	9,765.35	60.70
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		6,992.00		

INSPECTION

Date of Assignment:	16/08/2024	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Date Inspected:	16/08/2024		
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	715.20 FL	*525.00 FL
2	2		*REAR BUMPER SIDE GARNISH	Cracked	151.60 FL	*151.60 FL
3	1		*REAR BUMPER CENTER GARNISH	Cracked	192.10 FL	*192.10 FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	131.60 FL	*- FL
5	1		*TAIL GATE	Dented	905.80 FL	*905.80 FL
6	2		*TAIL GATE LAMP	Not Necessary	411.60 FL	*- FL
7	1		*TAIL GATE OUTER MOULDING	Not Necessary	254.80 FL	*- FL
8	1		*TAIL GATE LOGO	Not Necessary	80.90 FL	*- FL
9	1		*TAIL GATE EMBLEM FIT	Necessary	78.50 FL	*78.50 FL
10	2		*TAIL GATE DAMPER	Not Necessary	208.40 FL	*- FL
11	1		*TAIL GATE INNER HOLDER	Not Necessary	49.80 FL	*- FL
12	2		*TAIL GATE STOPPER	Not Necessary	24.00 FL	*- FL
13	1		*TAIL GATE INNER LOCK	Damaged	198.50 FL	*198.50 FL
14	1		*TAIL GATE LOCK CATCH	Not Necessary	25.00 FL	*- FL
15	1		*TAIL GATE WEATHERSTRIP	Cut	175.20 FL	*175.20 FL
16	1		*TAIL GATE INNER TRIM	Cracked	245.90 FL	*245.90 FL
17	2		*TAIL GATE HINGE	Not Necessary	131.60 FL	*- FL
18	1		*TAIL GATE DETECTOR	Cracked	265.90 FL	*265.90 FL
19	1		*TAIL GATE BUZZER	Not Necessary	135.70 FL	*- FL
20	2		*TAIL GATE WINDSCREEN MOULDING	Necessary	197.20 FL	*197.20 FL
21	1		*TAIL LAMP	O/S Cracked	657.00 FL	*328.50 FL
22	2		*TAIL LAMP LOWER PANEL (OUTER)	Repair	235.80 FL	*- FL
23	2		*TAIL LAMP LOWER PANEL (LOWER)	Repair	295.40 FL	*- FL
24	2		*REAR FENDER INNER COWLING	Not Necessary	251.20 FL	*- FL
25	1		*REAR FENDER INNER TRIM	O/S Deformed	610.40 FL	*305.20 FL
26	1		*REAR END PANEL	Dented	408.50 FL	*408.50 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	175.80 FL	*175.80 FL
28	1		*REAR FLOOR PANEL	Not Necessary	796.10 FL	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Deformed	205.90 FL	*205.90 FL
30	1		*REAR TOOLS COMPARTMENT SPONGE	Cracked	212.30 FL	*212.30 FL
31	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*SET REAR BUMPER CENTER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
34	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	30.00 FS	*30.00 FS
35	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
36	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
37	1		*SET TAIL LAMP CLIP	Not Necessary	50.00 FS	*- FS
38	1		*TAIL LAMP LOWER PANEL (OUTER) SEALANT	Not Necessary	60.00 FS	*- FS
39	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
42	1		*REAR FLOOR PANEL SEALANT	Not Necessary	250.00 FS	*- FS
43	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
44	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
45	1		*REAR FENDER RH	Buckled	897.50 FL	*897.50 FL
46	1		*REAR SILENCER BOX	Dented	523.60 FL	*523.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,488.80	6,413.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,969.76	1,198.60
Total Parts (\$)	9,519.04	5,214.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	800.00
3	TUFF COAT	New	200.00	60.00
4	WIRING CHECK ON TAILAMP	New	80.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY TO FACILITATE REPAIR	New	200.00	60.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	50.00
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	100.00	50.00
9	REMOVE AND VIDEO FOOTAGE AND DISTANCE SETTING	New	80.00	50.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	200.00	0.00
			Gross Labour Cost (\$\$)	5,240.00
				2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >