

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24060121/UPA3Q2**Date:** 06/09/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210108195
<b>Claimant Vehicle No :</b>	SGV68G	<b>Insured Vehicle No :</b>	SNB7281H
Date of Loss:	16/06/2024	Nature of Claim:	TP
		Claim No:	7261793114SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGV68G</b>	Engine No:	27492030316125
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R18) (A)	Chassis No:	WDD2120362B099792
Reg. Date:	27/01/2015 (Man. Year: 2014)	Odometer:	140581 km
Colour:	White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/35Z R19	Rear Tyre Size:	275/30Z R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	21,517.42	7,115.60	14,401.82	66.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	830.00	1,530.00	64.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>23,877.42</b>	<b>7,945.60</b>	<b>15,931.82</b>	<b>66.72</b>
<b>+ GST 9.00/9.00% (S\$)</b>	2,148.97	715.10	1,433.87	66.72
<b>Nett Amount (S\$)</b>	<b>26,026.39</b>	<b>8,660.70</b>	<b>17,365.69</b>	<b>66.72</b>
<b>+ Car Rental (5.0 x S\$150.00/day) (S\$)</b>		750.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>9,412.88</b>		
<b>Global Sum Settlement (S\$)</b>		<b>9,400.00</b>		

**INSPECTION**

Date of Assignment:	18/06/2024		
Date Inspected:	18/06/2024	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	2,850.00 F	*1,874.00 FL
2	1		*FRONT BUMPER CENTRE LOWER CHROME MOULDING	Serviceable	355.00 F	*- FL
3	1		*FRONT BUMPER PDC SENSOR O/S	Malfunction	365.00 F	*201.00 FL
4	1		*FRONT BUMPER BEAM	Not Necessary	815.00 F	*- FL
5	1		*FRONT BUMPER SIDE RETAINER O/S	Serviceable	108.00 F	*- FL
6	1		*SET FRONT BUMPER CLIPS & RIVET	Necessary	60.00 F	*60.00 FL
7	1		*HEADLAMP ASSY O/S	Scratched / Cracked	9,800.00 F	*5,771.22 FL
8	1		*FRONT FENDER O/S	Repair	1,599.00 F	*- FL
9	1		*FRONT FENDER INNER SHIELD O/S	Not Necessary	365.00 F	*- FL
10	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Not Necessary	60.00 F	*- FL
11	1		*FRONT SPORT RIM 19 INCH O/S	Not Necessary	1,800.00 F	*- FL
12	1		*FRONT KNUCKLE ARM O/S	Not Necessary	1,815.42 F	*- FL
13	1		*FRONT KNUCKLE ARM BEARING O/S	Not Necessary	680.00 F	*- FL
14	1		*FRONT LOWER ARM O/S	Not Necessary	845.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>21,517.42</b>	<b>7,906.22</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	790.62
<b>Total Parts (\$)</b>	<b>21,517.42</b>	<b>7,115.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	30.00
3	TO SPRAY RUST PROOFING	New	100.00	0.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	280.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
6	TO RESET & REPROGRAMME SYSTEM	New	100.00	80.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	300.00
8	TO PUTTY & SPRAY PAINTING	New	800.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,360.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >