



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMH 4988C

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER (N)	CUT/TORN	\$683.60	\$683.60
1	FRONT BUMPER SIDE COVER (N)	NOT NECESSARY	\$130.10	\$0.00
1	FRONT BUMPER SPONGE (N)	NOT NECESSARY	\$140.60	\$0.00
1	FRONT BUMPER REINFORCEMENT (N)	NOT NECESSARY	\$571.60	\$0.00
2	FRONT BUMPER SIDE RETAINERS -R/L @\$45.50 (N)	N/S NOT NECESSARY/ O/S CRACKED	\$91.00	\$45.50
1	FRONT FENDER -RH (N)	TO REPAIR SEE LABOUR	\$752.80	\$0.00
1	FRONT FENDER INNER SHIELD (N)	TORN	\$142.70	\$142.70
1	FRONT HEADLAMP -RH (N)	SCRATCHED	\$913.60	\$913.60
1	WIPER TANK (N)	NOT NECESSARY	\$162.80	\$0.00
	LESS 10.00%		(\$358.88)	(\$178.54)
			\$3,229.92	\$1,606.86
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$60.00	\$30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FRONT SPORT WHEEL (SN)	NOT NECESSARY	\$650.00	\$0.00
			\$770.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK FRONT ELECTRICAL WIRING	NOT NECESSARY	\$40.00	\$20.00
	TO CONDUCT WHEEL ALIGNMENT		\$120.00	\$0.00
	TO TUFF KOTE		\$60.00	\$30.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$800.00	\$400.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER -RH		\$700.00	\$300.00
			\$1,720.00	\$750.00
GRAND TOTAL			\$5,719.92	\$2,386.86
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,800.00
Report Ref No: CS/INC24080383/Uvh3				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

TOTAL FOR SPARE PARTS: \$ 3,999.92 \$ 1,636.86
TOTAL FOR LABOUR : \$ 1,720.00 \$ 750.00
TOTAL REPAIR COST: \$ 5,719.92 \$ 2,386.86

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.