

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24080388/EQP3M4
Date: 09/09/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZC00161
Claimant Vehicle No :	SHA9807E	Insured Vehicle No :	SCV7979D
Date of Loss:	21/08/2024	Nature of Claim:	TP
		Claim No:	M2404786

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9807E	Engine No:	G4LEKU389512
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU184468
Reg. Date:	27/08/2020 (Man. Year: 2019)	Odometer:	648459 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,409.04	1,908.48	500.56	20.78
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	820.00	680.00	140.00	17.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,241.04	2,600.48	640.56	19.76
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	3,241.04	2,100.00	1,141.04	35.21
+ GST 9.00/9.00% (S\$)	291.69	189.00	102.69	35.21
Nett Amount (S\$)	3,532.73	2,289.00	1,243.73	35.21

INSPECTION

Date of Assignment:	22/08/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	23/08/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2024)
Parts: 143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHA9807E)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL	
2	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL	
3	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH	Not Necessary	276.20 FL	*- FL	
4	1		*REAR BUMPER CTR MOULDING	Broken	451.25 FL	*451.25 FL	
5	1		*REAR BUMPER LWR MOULDING	Not Necessary	155.00 FL	*- FL	
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL	
7	2		*REAR BUMPER REFLECTOR RH / LH	Not Necessary	82.90 FL	*- FL	
8	2		*REAR BUMPER SIDE BRKT RH / LH	Not Necessary	111.60 FL	*- FL	
9	1		*REAR BUMPER FOGLAMP	Broken	204.50 FL	*204.50 FL	
10	1		*REAR SMART KEY ANTENNA	Broken	40.50 FL	*40.50 FL	
11	2		*LICENCE PLATE LAMP RH /LH	Broken/Missing	170.60 FL	*170.60 FL	
12	1		*REVERSE SENSORS	Broken	180.00 F	*180.00 F	
13	2		*REAR FENDER ADV.STICKER RH /LH	Necessary	200.00 F	*200.00 F	
14	1		*REAR NO.PLATE WITH TRIM COVER	Broken	55.00 F	*55.00 F	
15	1		*REAR BUMPER TOW COVER	Broken	98.80 FL	*98.80 FL	
					Sub Total (\$\$)	2,902.55	2,276.85
					- List Item Discount on L Items 20.00/20.00% (\$\$)	493.51	368.37
					Total Parts (\$\$)	2,409.04	1,908.48

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING	New	300.00	280.00
3	R/I REVERSE SNSORS	New	120.00	20.00
Gross Labour Cost (\$)			820.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >