

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24080390/RQP3E2**Date:** 13/12/2024REFERENCEInsured/Claimant: CYCLE & CARRIAGE LEASING PTE LTD
Date of Loss: 08/08/2024Policy No: MCF24B00000800
Nature of Claim: OD

Claim No: DMCF2400043H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM3167K	Engine No:	G4FGKH738449
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5045442
Reg. Date:	26/06/2019 (Man. Year: 2018)	Odometer:	132914 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,817.04	6,146.58	1,670.46	21.37
Miscellaneous Items	235.00	215.00	20.00	8.51
Labour	1,840.00	1,370.00	470.00	25.54
Paintwork Labour	1,000.00	1,000.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,892.04	8,731.58	2,160.46	19.84
Approved Total (Overridden) (S\$)		8,731.47		
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	10,892.04	7,731.47	3,160.57	29.02
+ GST 9.00/9.00% (S\$)	980.28	695.83	284.45	29.02
Nett Amount (S\$)	11,872.32	8,427.30	3,445.02	29.02

INSPECTION

Date of Assignment:	22/08/2024	Present Location:	Diplomat Parts Pte Ltd (HQ)
Date Inspected:	23/08/2024	Inspected At:	Diplomat Parts Pte Ltd (HQ) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2024)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3167K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-HOOD (WCP)	Bent	1,311.00 F	*1,311.00 F
2	1		*PAD-HOOD INSULATING (WCP)	Deformed	111.00 F	*111.00 F
3	13		*CLIP-HOOD INSULATING PAD (WCP)	Necessary	15.60 F	*15.60 F
4	1		*LATCH ASSY-HOOD (WCP)	Serviceable	61.80 F	*- F
5	1		*COVER-FR BUMPER (WCP)	Torn	399.00 F	*399.00 F
6	1		*GRILLE ASSY-RADIATOR (WCP)	Cracked	205.80 F	*205.80 F
7	1		*GARNISH-RADIATOR GRILLE (WCP)	Cracked	30.00 F	*30.00 F
8	1		*GRILLE-FRONT BUMPER (WCP)	Cracked	157.20 F	*157.20 F
9	1		*MOULDING-FRONT BUMPER,RH (WCP)	Serviceable	21.60 F	*- F
10	1		*ABSORBER-FRONT BUMPER ENERGY (WCP)	Cracked	50.40 F	*50.40 F
11	1		*ORNAMENT-KIA NO.115 (WCP)	Necessary	27.60 F	*27.60 F
12	1		*STIFFNER-FR BPR LWR (WCP)	Serviceable	68.40 F	*- F
13	1		*BEAM COMPLETE-FR BUMPER (WCP)	Bent	298.20 F	*298.20 F
14	1		*CARRIER ASSY-FRONT END MODULE (WCP)	Serviceable	405.00 F	*- F
15	1		*PANEL-FENDER,RH (WCP)	Bent	391.20 F	*391.20 F
16	1		*LAMP ASSY-HEAD,LH (WCP)	Cracked	748.20 F	*748.20 F
17	1		*LAMP ASSY-HEAD,RH (WCP)	Cracked	748.20 F	*748.20 F
18	1		*CONDENSER ASSY-COOLER (WCP)	Bent	405.00 F	*405.00 F
19	1		*RADIATOR ASSY (WCP)	Serviceable	448.80 F	*- F
20	1		*BLOWER ASSY (WCP)	Serviceable	425.40 F	*- F
21	1		*RESERVOIR & PUMP ASSY-WASHER (WCP)	Serviceable	87.60 F	*- F
<u>Supplementary #1</u>						
22	1		*HINGE ASSY-HOOD,RH (WCP)	Bent	25.80 F	*25.80 F
23	1		*HINGE ASSY-HOOD,LH (WCP)	Bent	25.80 F	*25.80 F
24	1		*GUARD-AIR,RH (WCP)	Cracked	16.80 F	*16.80 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*HORN ASSY-LOW PITCH (WCP)	Cracked	44.40 F	*44.40 F
26	1		*CAP-FRONT HOOK (WCP)	Necessary	5.40 F	*5.40 F
27	1		*CARRIER ASSY-FRONT END MODULE (WCP)	Cracked	405.00 F	*405.00 F
28	1		*COVER ASSY-COWL TOP (WCP)	Cracked	148.20 F	*148.20 F
29	10		*CLIP (WCP)	Necessary	6.00 F	*6.00 F
30	10		*RETAINER-COWL TOP COVER MTG (WCP)	Necessary	12.00 F	*12.00 F

F=Franchise part.

Sub Total (\$\$)	7,106.40	5,587.80
+ Margin on L,N Items 10.00/10.00% (\$\$)	710.64	558.78
Total Parts (\$\$)	7,817.04	6,146.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ANTI-RUST PROOFING BONNET, FRT LHS FENDER, FRT RHS FENDER, FRT RHS DOOR	100.00	100.00
2	1	APPLY BODY SEALANT ON AFFECTED AREA	100.00	80.00
3	1	SUPPLY FRONT LICENSE PLATE WITH CASING (BENT)	35.00	35.00
Sub Total (S\$)			235.00	215.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	FRT BUMPER	New	200.00	200.00
2	BONNET	New	200.00	200.00
3	FRT LHS FENDER	New	200.00	200.00
4	FRT RHS FENDER	New	200.00	200.00
5	FRT RHS DOOR	New	200.00	200.00
Labour Items				
6	FRT BUMPER	New	220.00	220.00
7	BONNET	New	220.00	220.00
8	FRT RHS FENDER	New	220.00	220.00
9	FRT SUPPORT PANEL	New	220.00	220.00
10	FRT LHS FENDER	Repair	220.00	110.00
11	FRT RHS DOOR	Repair	220.00	110.00
12	TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	50.00	50.00
13	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	250.00	0.00
Supplementary #2				
Labour Items				
14	TO REPLACE, AND VACUUM & TOP UP A/CON GAS	New	220.00	220.00
Gross Labour Cost (S\$)			2,840.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >