



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLS 1424L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOT LID	DENTED	\$1,860.00	\$1,307.00
2	REAR BOOT LID HINGES @\$187.70	NOT NECESSARY	\$375.40	\$0.00
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	\$95.00	\$95.00
1	REAR BOOT LID RH LOGO	NECESSARY	\$60.00	\$60.00
1	BOOT LID CENTRE GARNISH -WISH	CRACKED	\$288.00	\$288.00
1	REAR BOOT LID INNER LOCK	DAMAGED	\$388.00	\$388.00
1	REAR BOOT LID INNER RUBBER	CUT	\$276.10	\$276.10
1	BOOT LID KEYLESS SENSOR	CRACKED	\$450.00	\$162.00
1	REAR BOOT LID CAMERA	NOT NECESSARY	\$550.00	\$0.00
1	REAR BOOT LID TOP CENTER MOULDING	REPEATED	\$388.00	\$0.00
1	SET REAR BOOT LID TOP CENTER MOULDING CLIPS	NOT NECESSARY	\$50.00	\$0.00
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	\$50.00	\$0.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$135.10	NOT NECESSARY	\$270.20	\$0.00
1	REAR BOOT LID INNER TRIM BOARD	CRACKED	\$780.00	\$486.00
2	REAR BOOT LID SIDE REFLECTOR @\$580.00	CUT	\$1,160.00	\$555.00
4	TAIL LAMP CLIPS @\$8.50	NOT NECESSARY	\$34.00	\$0.00
2	TAIL LAMP @\$680.00	NOT NECESSARY	\$1,360.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$880.00	\$0.00
1	REAR END PANEL TOP GARNISH	DEFORMED	\$288.00	\$288.00
1	REAR BUMPER	DEFORMED	\$1,377.00	\$597.00
2	REAR BUMPER SIDE REFLECTOR @\$83.10	NOT NECESSARY	\$166.20	\$0.00
2	REAR BUMPER SIDE BRACKET @\$112.00	NOT NECESSARY	\$224.00	\$0.00
2	REAR BUMPER SIDE RETAINER @\$188.00	NOT NECESSARY	\$376.00	\$0.00
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$1,125.53)
			\$11,745.90	\$3,376.57
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	\$350.00	\$200.00
8	REAR BUMPER CLIPS @\$6.50 (SN)	NECESSARY	\$52.00	\$30.00
			\$402.00	\$230.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX CUSHION		\$120.00	\$40.00
	TO REMOVE & REFIX REVERSE SENSOR		\$120.00	\$50.00
	TUFF KOTE		\$120.00	\$30.00
	TO CHECK WIRING SYSTEM		\$80.00	\$30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$800.00	\$500.00
	SPRAY PAINTING		\$800.00	\$500.00
			\$2,040.00	\$1,150.00
GRAND TOTAL			\$14,187.90	\$4,756.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$3,800.00
Report Ref No: CS/GAI24080391/Anp3				

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.