



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMW 9831J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET BRAKE MASTER PUMP WITH BREAK SERVO	* CHECK	\$2,780.50	\$0.00
1	SET FLOORING COVERING WITH FLOORMAT	STAINED	\$4,287.00	\$4,287.00
1	WIRING SET FOR FAN MOTOR, AIR CON REGULATED	* CHECK	\$2,190.00	\$0.00
1	WIRING HARNESS FOR SEAT FRAME AND BACKREST ADJUSTMENT	* CHECK	\$1,890.00	\$0.00
1	WIPER MOTOR	MALFUNCTION	\$1,950.00	\$1,950.00
1	WIRING SET FOR DASH PANEL, BATTERY WIRING SET	* CHECK	\$16,280.00	\$0.00
1	ENGINE CONTROL UNIT	* CHECK	\$4,650.00	\$0.00
1	ONBOARD SUPPLY UNIT	* CHECK	\$4,850.00	\$0.00
1	DRIVER ASSIST UNIT	* CHECK	\$10,980.00	\$0.00
1	CONTROL UNIT FOR CHASSIS	* CHECK	\$4,250.00	\$0.00
1	48VOLT CAR BATTERY	* CHECK	\$3,048.00	\$0.00
1	CAR BATTERY	* CHECK	\$550.00	\$0.00
			\$57,705.50	\$6,237.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	DIAGNOSTIC FEE		\$150.00	\$150.00
	ESTIMATE LABOUR COST		\$6,325.00	\$600.00
			\$6,475.00	\$750.00

GRAND TOTAL			\$64,180.50	\$6,987.00
RECOMMENDED COST OF REPAIRS				\$6,987.00

Report Ref No: CS/TP24080392/Enp3e2

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.