

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24080396/UNP3M4**Date:** 02/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001741852
Claimant Vehicle No :	SLV1771T	Insured Vehicle No :	YN8279R
Date of Loss:	22/08/2024	Nature of Claim:	TP
		Claim No:	371184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV1771T		
Make & Model:	MERCEDES-BENZ GLC200, 2.0 (R18 LED) (A)	Engine No:	26492030236230
Reg. Date:	16/03/2020 (Man. Year: 2019)	Chassis No:	WDC2539802F755241
Colour:	White	Odometer:	59942 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60R18	Rear Tyre Size:	235/60R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,262.04	7,079.48	12,182.56	63.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	1,680.00	4,170.00	71.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,112.04	8,759.48	16,352.56	65.12
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	25,112.04	7,000.00	18,112.04	72.12
+ GST 9.00/9.00% (S\$)	2,260.08	630.00	1,630.08	72.12
Nett Amount (S\$)	27,372.12	7,630.00	19,742.12	72.12

INSPECTION

Date of Assignment:	26/08/2024	
Date Inspected:	23/08/2024	Inspected At:
Estimated Period of Repair:	4.0 days	

SPEEDWERKZ PTE LTD (Autobay) (HQ)
1 KAKI BUKIT AVENUE 6
#01-73 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2024)
Parts:	M1-SUV	MERCEDES-BENZ GLC200 2.0 (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1771T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	2,788.60 FL	*2,788.60 FL
2	1		*TAILGATE LOGO	Necessary	61.06 FL	*61.06 FL
3	1		*TAILGATE GLC200 EMBLEM (KIV)	Necessary	98.30 FL	*- FL
4	1		*TAILGATE LAMP L/R	N/S Cracked/O/S Not Necessary	1,316.80 FL	*511.43 FL
5	1		*TAILGATE WEATHERSTRIPE	Not Necessary	486.10 FL	*- FL
6	1		*TAILGATE INNER LOCK	Damaged	322.10 FL	*322.10 FL
7	1		*TAILGATE LOCK STRIKER	Not Necessary	48.90 FL	*- FL
8	2		*TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	322.60 FL	*- FL
9	1		*TAILGATE WIPER MOTOR	Not Necessary	711.30 FL	*- FL
10	1		*TAILGATE WIPER ARM	Not Necessary	135.60 FL	*- FL
11	1		*TAILGATE OUTER LOCK SWITCH	Not Necessary	265.80 FL	*- FL
12	1		*TAILGATE INNER TRIMBOARD	Cut/Twisted	857.30 FL	*645.31 FL
13	1		*REAR WINDSCREEN GLASS	Broken	1,512.70 FL	*1,322.51 FL
14	1		*TAIL LAMP N/S	Cracked	1,388.60 FL	*822.00 FL
15	1		*REAR BUMPER	Repair	1,455.20 FL	*- FL
16	1		*REAR BUMPER LOWER BLACK	Grazed	655.10 FL	*545.21 FL
17	1		*REAR BUMPER LOWER CHROME	Cracked	513.70 FL	*481.20 FL
18	2		*REAR BUMPER LOWER EXHAUST CHROME L/R	Not Necessary	886.80 FL	*- FL
19	1		*REAR BUMPER TOW COVER	Not Necessary	87.02 FL	*- FL
20	1		*REAR BUMPER UNDER COVER	Not Necessary	373.30 FL	*- FL
21	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	196.80 FL	*- FL
22	2		*REAR BUMPER SIDE BRACKET L/R	Not Necessary	294.60 FL	*- FL
23	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	96.80 FL	*- FL
24	1		*REAR BUMPER SWITCH MODULE	Not Necessary	386.66 FL	*- FL
25	1		*REAR BUMPER SWITCH MODULE BRACKET	Not Necessary	88.10 FL	*- FL
26	1		*REAR BUMPER SWITCH MODULE CODE-A	Not Necessary	189.60 FL	*- FL
27	1		*REAR BUMPER SWITCH MODULE CODE-B	Not Necessary	189.60 FL	*- FL
28	1		*REAR BUMPER REINFORCEMENT	Repair	810.50 FL	*- FL
29	1		*REAR BUMPER CENTRE MOUNT BRACKET	Not Necessary	201.30 FL	*- FL
30	4		*REAR BUMPER REVERSE SENSOR	Serviceable	1,010.40 FL	*- FL
31	1		*SET REAR BUMPER REVERSE SENSOR BRACKET	Not Necessary	48.00 FL	*- FL
32	1		*END PANEL	Repair	1,625.70 FL	*- FL
33	1		*END PANEL GARNISH	Not Necessary	585.10 FL	*- FL
34	1		*REAR BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*REAR BUMPER RIVET	Not Necessary	80.00 FS	*- FS
36	1		*TAILGATE INNER TRIMBOARD CLIPS	Necessary	65.00 FS	*50.00 FS
37	1		*TAILGATE WIPER BLADE	Not Necessary	140.00 FS	*- FS
38	1		*TAILGATE C&C LOGO (KIV)	Necessary	88.00 FS	*- FS
39	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*REAR WINDSCREEN GLASS SPONGE	Necessary	60.00 FS	*20.00 FS
41	1		*REAR WINDSCREEN GLASS TINT FILM	Necessary	450.00 FS	*180.00 FS
42	1		*END PANEL GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*REAR NUMBER PLATE WITH GARNISH	Bent	60.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	21,263.04
					- List Item Discount on L Items 10.00/10.00% (\$)	2,001.00
					Total Parts (\$)	19,262.04

7,829.42

749.94

7,079.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING	New	50.00	20.00
2	TO REFIX REAR REVERSE SENSOR	New	120.00	30.00
3	TO REPLACE REAR REVERSE CAMERA	New	150.00	0.00
4	TO REMOVE AND TRANSFER TAILGATE FITTINGS TO NEW	New	250.00	60.00
5	TO REMOVE AND REFIT REAR INTERIOR TRIMS	New	200.00	0.00
6	TO PROVIDE LABOUR,WORKMANSHIP	New	2,000.00	540.00
7	TO SPRAY PAINT ON AFFECTED PANELS	New	2,000.00	800.00
8	TO REPROGRAMME AND CALIBRATE PARKING SENSORS & CAMERA }	New	300.00	80.00
9	TO REPROGRAMME AND CALIBRATE TAILGATE FUNCTION }	New	150.00	0.00
10	TO REPLACE REAR WINDSCREEN GLASS	New	200.00	120.00
11	TO VACUUM AND CLEAN INTERIOR FOR GLASS SHARDS	New	250.00	0.00
12	RUST PROOFING	New	180.00	30.00
Gross Labour Cost (\$\$)			5,850.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >