

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24080397/UNP3M4
Date: 19/09/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002202784
Claimant Vehicle No :	SLB7613H	Insured Vehicle No :	SMN5608L
Date of Loss:	22/08/2024	Nature of Claim:	TP
		Claim No:	371019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB7613H		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2260868A
Reg. Date:	21/04/2016 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1634998
Colour:	Purple	Odometer:	125165 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,839.57	9,651.80	22,187.77	69.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	2,660.00	2,890.00	52.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,389.57	12,311.80	25,077.77	67.07
Approved Total (Overridden) (S\$)		9,800.00		
(S\$)	37,389.57	9,800.00	27,589.57	73.79
+ GST 9.00/9.00% (S\$)	3,365.06	882.00	2,483.06	73.79
Nett Amount (S\$)	40,754.63	10,682.00	30,072.63	73.79

INSPECTION

Date of Assignment:	23/08/2024		
Date Inspected:	23/08/2024	Inspected At:	FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2024)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB7613H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,288.20 FN	*- FN
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	145.80 FN	*- FN
3	1		*TAILGATE	Not Necessary	3,466.20 FN	*- FN
4	1		*TAILGATE OUTER HANDLE	Not Necessary	450.00 FN	*- FN
5	1		*TAILGATE REAR LOGO	Not Necessary	65.00 FN	*- FN
6	1		*TAILGATE QASHQAI EMBLEM	Not Necessary	85.00 FN	*- FN
7	2		*TAILGATE REFLECTORS	Not Necessary	960.00 FN	*- FN
8	1		*TAILGATE INNER LOCK	Not Necessary	292.00 FN	*- FN
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	595.60 FN	*- FN
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	45.00 FN	*- FN
11	1		*TAILGATE WEATHERSTRIP	Twisted	265.00 FN	*240.80 FN
12	1		*REAR BUMPER	Distorted	991.00 FN	*975.80 FN
13	1		*REAR BUMPER TOW COVER	Not Necessary	85.00 FN	*- FN
14	2		*REAR BUMPER REFLECTORS	Cracked	170.00 FN	*132.00 FN
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 FN	*- FN
16	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FN	*45.00 FN
17	1		*REAR BUMPER SPONGE	Torn	225.00 FN	*180.40 FN
18	1		*REAR BUMPER BEAM	Repair	721.00 FN	*- FN
19	2		*REAR BUMPER BEAM BRACKETS	Serviceable	300.00 FN	*- FN
20	1		*REAR END PANEL	Dented/Bent	720.00 FN	*591.60 FN
21	1		*REAR END PANEL LOCK SENSOR	Not Necessary	122.00 FN	*- FN
22	1		*REAR END PANEL TOP GARNISH	Twisted	480.00 FN	*216.80 FN
23	1		*REAR FLOOR PANEL	Repair	1,280.00 FN	*- FN
24	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	650.00 FN	*- FN
25	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	610.00 FN	*- FN
26	2		*REAR FENDERS	Repair	2,230.00 FN	*- FN
27	2		*REAR FENDER OUTER PROTECTORS	Deformed/Torn	1,082.00 FN	*1,082.00 FN
28	2		*TAILLAMPS	Not Necessary	1,360.00 FN	*- FN
29	1		*REAR EXHAUST	Repair	1,122.20 FN	*- FN
30	1		*FRONT BUMPER	Deformed/Torn	981.00 FN	*981.00 FN
31	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	130.00 FN	*- FN
32	1		*FRONT BUMPER SPONGE	Torn	185.30 FN	*185.30 FN
33	1		*FRONT BUMPER REINFORCEMENT	Repair	715.00 FN	*- FN
34	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FN	*45.00 FN
35	1		*FRONT GRILLE	Cracked	850.00 FN	*643.90 FN
36	1		*FRONT GRILLE CHROME		335.00 FN	*- FN
37	1		*SET FRONT GRILLE CLIPS	Not Necessary	20.00 FN	*- FN
38	2		*HEADLAMPS	Cracked	5,000.00 FN	*1,497.40 FN
39	1		*FRONT BONNET	Dented/Bent	1,455.00 FN	*1,455.00 FN
40	2		*FRONT FENDER OUTER PROTECTORS	Deformed/Torn	1,080.00 FN	*1,080.00 FN
41	1		*CONDENSER	Bent/Punctured	1,080.00 FN	*1,050.00 FN
42	1		*RADIATOR	Not Necessary	1,100.00 FN	*- FN
43	1		*OIL COOLER	Not Necessary	820.00 FN	*- FN
44	1		*SET REAR BUMPER REVERSE SENSOR	Malfunction	280.00 FS	*200.00 FS
45	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
47	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	250.00 FS	*- FS
48	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
49	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
50	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
51	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
52	1		*FRONT LICENCE PLATE	Cracked	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	35,217.30	10,692.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	3,377.73	1,040.20
Total Parts (\$\$)	31,839.57	9,651.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	30.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	New	120.00	60.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
8	TO REFILL AIR CON GAS	New	120.00	100.00
9	TO SPRAY RUST PROOFING	New	150.00	40.00
10	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,200.00	1,200.00
12	TO PUTTY & SPRAY PAINTING	New	2,200.00	1,200.00
Gross Labour Cost (\$\$)			5,550.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >