



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKT 8613T

| REPLACEMENT OF PARTS | | | | |
|---|--|----------------------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | BONNET | TO REPAIR SEE LABOUR | \$1,014.10 | \$0.00 |
| 1 | FRONT BUMPER | CUT | \$822.90 | \$822.90 |
| 2 | FRONT BUMPER SIDE RETAINERS @\$45.00 | NOT NECESSARY | \$90.00 | \$0.00 |
| 1 | FRONT BUMPER SPONGE | NOT NECESSARY | \$166.60 | \$0.00 |
| 1 | FRONT BUMPER REINFORCEMENT | NOT NECESSARY | \$422.10 | \$0.00 |
| 1 | SET FRONT BUMPER CLIPS | NOT NECESSARY | \$35.00 | \$0.00 |
| 1 | FRONT GRILLE | SCRATCHED | \$322.80 | \$322.80 |
| 1 | FRONT LICENCE PLATE W/HOLDER | SCRATCHED | \$42.00 | \$42.00 |
| 1 | HEADLAMP O/S | SCRATCHED | \$905.00 | \$905.00 |
| 1 | FRONT FENDER O/S | NOT NECESSARY | \$711.20 | \$0.00 |
| | LESS 10.00% DISCOUNT | | (\$453.17) | (\$209.27) |
| | | | \$4,078.53 | \$1,883.43 |
| Labour | | | | |
| | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| | TO CHECK WIRING | | \$50.00 | \$20.00 |
| | TO SPRAY RUST PROOFING | | \$50.00 | \$0.00 |
| | TO REFILL AIR CON GAS | | \$100.00 | \$0.00 |
| | LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF BONNET | | \$680.00 | \$300.00 |
| | TO PUTTY & SPRAY PAINTING | | \$1,080.00 | \$400.00 |
| | | | \$1,960.00 | \$720.00 |
| GRAND TOTAL | | | \$6,038.53 | \$2,603.43 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | | \$2,050.00 |
| Report Ref No: CS/INC24060123/Unh3e2 | | | | |

TOTAL FOR SPARE PARTS: \$ 4,078.53 \$ 1,883.43
TOTAL FOR LABOUR : \$ 1,960.00 \$ 720.00
TOTAL REPAIR COST: \$ 6,038.53 \$ 2,603.43

CKS

MARCUS CHUA KANG SENG
Licensed Appraiser