

Your Ref: 2023 - 99

Date: 03rd September 2024

Our Ref: CS1/SCD24080404/Eqp3m4

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLJ 223D**INSURED VEHICLE: GBM 1086D****ACCIDENT DATE: 28/09/2023**

We thank you for your instruction on 23/08/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLJ 223D from M/s AIG Asia Pacific Insurance Pte Ltd.
- b) Singapore Accident Statement of Vehicle SLJ 223D.
- c) Police Report of Vehicle SLJ 223D.
- d) Colour damaged vehicle photographs of SLJ 223D.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLJ 223D
Make & Model	: Mercedes Benz Glc300 Coupe
Chassis Number	: W1N2539842G078928
Year of Registration	: 2023
Engine Capacity	: 1991 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLJ 223D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RH/FRONT FENDER	DENTED	\$993.47	\$993.47
1	RH/FRONT FENDER BLACK TRIM	CUT	\$292.46	\$292.46
1	FRONT BUMPER	BROKEN	\$1,468.51	\$1,468.51
1	FRONT BUMPER LOWER BLACK TRIM	NOT NECESSARY	\$346.72	\$0.00
1	FRONT BUMPER LOWER CHROME COVER	NOT NECESSARY	\$1,094.68	\$0.00
1	RH/COVER, BUMPER AREA	BROKEN	\$36.69	\$36.69
1	RH/FRONT BUMPER MOUNTING RAIL	NECESSARY	\$20.14	\$20.14
1	RH/BASIC CARRIER FOR BUMPER	BROKEN	\$71.34	\$71.34
1	RH/HEADLAMP UNIT	BROKEN	\$3,384.20	\$3,384.20
10	CUPPED BLIND RIVET	NECESSARY	\$55.00	\$55.00
1	RH/HEADLAMP BOTTOM BRACKET	NOT NECESSARY	\$36.60	\$0.00
1	RH/HEADLAMP CONSOLE	BROKEN	\$81.61	\$81.61
1	TRIM CLIP	NECESSARY	\$8.07	\$8.07
1	CROSS MEMBER	DENTED	\$515.94	\$515.94
	LESS 10.00% DISCOUNT		(\$840.54)	(\$692.74)
			\$7,564.89	\$6,234.69
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$15.00	\$15.00
			\$15.00	\$15.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	DISASSEMBLE & REPLACE ATTACHED DAMAGED PARTS & REFINISH		\$1,344.00	\$960.00
	RESPRAY FRONT BUMPER & RH/FRT FENDER		\$1,800.00	\$1,600.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT, RESET MEMORY TO IDEN. STD. NETT		\$380.00	\$380.00
	TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT		\$96.00	\$96.00
	TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT	NOT NECESSARY	\$540.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM		\$180.00	\$180.00
			\$4,340.00	\$3,216.00
GRAND TOTAL			\$11,919.89	\$9,465.69
	RECOMMENDED COST OF REPAIRS			\$9,465.69
Report Ref No: CS1/SCD24080404/Eqp3m4				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.