

VEHICLE DAMAGE INSPECTION REPORT

Our File No: AVS2023-35537/NC
Date: 14/06/2023

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	DMPC2300343H/02/CT
Claimant Vehicle No :	SMD1344B	Insured Vehicle No :	SLP6062E
Date of Loss:	07/05/2023	Nature of Claim:	TP
			Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD1344B		
Make & Model:	LEXUS IS, 250 (A)	Engine No:	4GR0515909
Reg. Date:	05/11/2008 (Man. Year: 2008)	Chassis No:	JTHBK262305087062
Colour:	White	Odometer:	153038 km
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40R18	Rear Tyre Size:	235/40R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	10/05/2023		
Date Inspected:	10/05/2023	Inspected At:	Nexwave Auto (HQ) 160, Sin Ming Drive, #05-15, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	6.0 days		

Adjuster: Nic Chia

Manager: Bernard Ong
Director

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



AJAX Inspection Services Pte Ltd

2 Alexandra Road, #03-01B Delta House, Singapore 159919. Tel: +65 6271 2520 Fax: +65 6271 2526
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

MARKET VALUE

The present market value of the subject vehicle is in the region of S\$68,000.00.

REMARKS

Third Party Repairer did not provide any repair estimate to us and is only requesting for us to conduct a PRE-REPAIR INSPECTION.

Based on visual inspection of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than S\$3,100.00 and could take approximately six (6) working days to complete.

The survey was conducted strictly on a "Without Prejudice" basis.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2023)
Parts:	143	LEXUS IS 250 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	AJAX Inspection Services Pte Ltd/SMD1344B/14/06/2023 12:25	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

AJAX Inspection Services Pte Ltd/SMD1344B/14/06/2023 12:25. Not valid without Reference section.
--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

AJAX Inspection Services Pte Ltd/SMD1344B/14/06/2023 12:25. Not valid without Reference section.

< END OF ESTIMATES >