

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080408/AUA3Q2**Date:** 16/04/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220077441-01
Claimant Vehicle No : SMY3348S **Insured Vehicle No :** SNG2099A
 Date of Loss: 04/08/2024 Nature of Claim: TP Claim No: 6461269518SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY3348S**
 Make & Model: HONDA SHUTTLE, 1.5 G CVT SENSING (A) Engine No: L15B6024494
 Reg. Date: 26/02/2021 (Man. Year: 2019) Chassis No: GK82103874
 Colour: Green Odometer: 48345 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,652.16	1,064.00	3,588.16	77.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	430.00	1,450.00	77.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,532.16	1,494.00	5,038.16	77.13
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	6,532.16	1,200.00	5,332.16	81.63
+ GST 9.00/9.00% (S\$)	587.89	108.00	479.89	81.63
Nett Amount (S\$)	7,120.05	1,308.00	5,812.05	81.63
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,515.25		
Global Sum Settlement (S\$)		1,515.00		

INSPECTION

Date of Assignment: 12/09/2024
 Date Inspected: 12/09/2024 Inspected At: MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM
 Inspection Centre
 Singapore 415933
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,152.50 FL	*985.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	62.40 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	410.00 FL	*- FL
4	1		*FRONT BUMPER DAYLIGHT	Cracked	620.00 FL	*320.00 FL
5	1		*FRONT BUMPER DAYLIGHT HOUSING	Not Necessary	260.00 FL	*- FL
6	1		*HEADLAMP	Not Necessary	2,550.30 FL	*- FL
7	1		*FRONT FENDER	Not Necessary	520.00 FL	*- FL
8	1		*FRONT FENDER INNER COWLING	Not Necessary	190.00 FL	*- FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
10	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,805.20	1,325.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,153.04	261.00
Total Parts (\$)	4,652.16	1,064.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	800.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	800.00	200.00
3	TUFF COAT	New	200.00	0.00
4	WIRING CHECK	New	80.00	30.00
Gross Labour Cost (\$\$)			1,880.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >