

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24060124/DVH3E2
Date: 05/11/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003110026
Claimant Vehicle No :	SHC3299A	Insured Vehicle No :	SLX8673L
Date of Loss:	16/06/2024	Nature of Claim:	TP
		Claim No:	363329

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3299A		
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Engine No:	G4LEJU191395
Reg. Date:	01/03/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU141426
Colour:	Blue	Odometer:	715125 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,442.88	22,771.00	18,671.88	45.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,740.00	2,130.00	8,610.00	80.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	52,182.88	24,901.00	27,281.88	52.28
Approved Total (Overridden) (\$\$)		17,000.00		
(\$\$)	52,182.88	17,000.00	35,182.88	67.42
+ GST 9.00/9.00% (\$\$)	4,696.46	1,530.00	3,166.46	67.42
Nett Amount (\$\$)	56,879.34	18,530.00	38,349.34	67.42

INSPECTION

Date of Assignment:	19/06/2024	
Date Inspected:	19/06/2024	Inspected At: 59 Loyang Drive Level 4 Room 7 Singapore 508969 Repairer: Bifrost Auto Pte Ltd - Loyang (HQ)
Estimated Period of Repair:	12.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2024)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3299A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,253.80 FL	*2,253.80 FL
2	1		*BONNET HINGE (RH)	Bent	118.70 FL	*118.70 FL
3	1		*BONNET MOULDING	Not Necessary	41.40 FL	*- FL
4	1		*BONNET LOCK	Bent	127.30 FL	*127.30 FL
5	1		*BONNET INSULATOR	Not Necessary	230.10 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
7	1		*BONNET CABLE	Not Necessary	135.60 FL	*- FL
8	1		*RADIATOR GRILLE EMBLEM	Necessary	88.00 FL	*88.00 FL
9	1		*RADIATOR GRILLE NEW MODEL	Broken	1,568.60 FL	*1,409.10 FL
10	1		*RADIATOR GRILLE	No such part	1,409.10 FL	*- FL
11	1		*FLAP ASSY ACTIVE AIR UPPER, (RH)	Socket Broken	824.60 FL	*824.60 FL
12	1		*FLAP ASSY ACTIVE WIRE	Not Necessary	765.30 FL	*- FL
13	1		*FRONT NUMBER PLATE GARNISH	Broken	188.00 FL	*188.00 FL
14	1		*FRONT BUMPER COVER	Torn	481.10 FL	*481.10 FL
15	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Broken	186.90 FL	*186.90 FL
17	1		*FRONT BUMPER REINFORCEMENT	Broken	1,136.70 FL	*1,136.70 FL
18	1		*FRONT BUMPER REINFORCEMENT ABSORBER (RH)	Dented	186.50 FL	*186.50 FL
19	1		*FRONT BUMPER TOWING COVER	Serviceable	29.00 FL	*- FL
20	1		*FRONT BUMPER MOULDING CENTRE UPPER	Mtg Broken	368.50 FL	*368.50 FL
21	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
22	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
23	1		*FRONT BUMPER LOWER GRILLE	Deformed	365.30 FL	*365.30 FL
24	1		*FRONT BUMPER LOWER GRILLE MOULDING	Serviceable	127.60 FL	*- FL
25	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
26	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	35.00 FL	*- FL
27	1		*FRONT BUMPER BRACKET (RH)	Not Necessary	28.00 FL	*- FL
28	1		*FRONT BUMPER RETAINER MOUNTING (RH)	Not Necessary	65.30 FL	*- FL
29	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
30	1		*FRONT BUMPER GRILLE (RH)	Cut	186.90 FL	*186.90 FL
31	1		*FRONT BUMPER AIR DUCT (RH)	Not Necessary	153.80 FL	*- FL
32	1		*DAY LIGHT, RH	Mtg Broken	642.50 FL	*642.50 FL
33	1		*DAY LIGHT WIRE	Not Necessary	585.50 FL	*- FL
34	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	1,139.30 FL	*1,139.30 FL
35	1		*HEADLAMP (RH)	Broken	3,987.30 FL	*2,110.30 FL
36	1		*HORN UNIT (RH)	Not Necessary	72.80 FL	*- FL
37	1		*HORN WIRE	Not Necessary	386.70 FL	*- FL
38	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL
39	1		*RADIATOR	Bent	710.50 FL	*710.50 FL
40	1		*RADIATOR FAN BLOWER MOTOR ASSY	Broken	1,459.60 FL	*1,459.60 FL
41	1		*FRONT FENDER (RH)	Dented	490.70 FL	*490.70 FL
42	1		*FRONT FENDER SHIELD (RH)	Serviceable	164.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*AIRCON CONDENSER	Bent	663.60 FL	*663.60 FL
44	1		*AIRCON SUCTION & LIQUID HOSE	Bent	679.60 FL	*679.60 FL
45	1		*AIRCON METAL HOSE - SMALL	Dented	186.50 FL	*186.50 FL
46	1		*AIRCON METAL HOSE - BIG	Dented	352.10 FL	*352.10 FL
47	1		*AIRCON DISCHARGE HOSE	Not Necessary	148.50 FL	*- FL
48	1		*FRONT WINDSCREEN GLASS	Cracked	1,558.10 FL	*1,558.10 FL
49	1		*WIPER CONTAINER ASSY	Deformed	385.40 FL	*385.40 FL
50	1		*ENGINE UNDER COVER	Not Necessary	469.40 FL	*- FL
51	1		*DASHBOARD COMPLETE	Broken	4,724.00 FL	*1,474.00 FL
52	1		*PASSENGER AIR BAG	Activated	2,633.00 FL	*1,951.20 FL
53	1		*STEERING AIRBAG COMPLETE	Activated	1,090.90 FL	*1,090.90 FL
54	1		*AIRBAG CONTROL MODULE	Not Necessary	1,243.70 FL	*- FL
55	1		*CURTAIN AIRBAG MODULE (RH)	Activated	1,344.50 FL	*1,344.50 FL
56	1		*KNEE CONTROL AIRBAG MODULE ASSY	Activated	578.60 FL	*578.60 FL
57	1		*AIR BAG ASSY - PASSENGER	Repeated	1,951.20 FL	*- FL
58	1		*STEERING ANGLE ASSY	Not Necessary	786.90 FL	*- FL
59	1		*SENSOR ASSY IMPACT - FRT INPACT	Not Necessary	643.90 FL	*- FL
60	1		*AIRBAG SENSOR (RH)	Not Necessary	348.10 FL	*- FL
61	1		*AIRBAG FRT SEAT	Activated	1,344.50 FL	*1,344.50 FL
62	1		*ROOF UPHOLSTERY LINING	Serviceable	1,983.30 FL	*- FL
63	1		*FRT SAFETY BELT (ASSY) (RH)	Activated	648.90 FL	*648.90 FL
64	1		*REAR SAFETY BELT (ASSY) (RH)	Activated	513.20 FL	*513.20 FL
65	1		*REAR SAFETY BELT GARNISH COVER (RH)	Serviceable	398.00 FL	*- FL
66	1		*FRONT NUMBER PLATE }	Broken	25.00 FS	*45.00 FS
67	1		*FRONT NO PLATE TRIM COVER }		30.00 FS	*- FS
68	1		*COOLANT	Not Necessary	45.00 FS	*- FS
69	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Not fitted	100.00 FS	*- FS
70	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
71	1		*FRONT ERP STICKER	Necessary	30.00 FS	*30.00 FS
72	1		*AIRCON COMPRESSOR	Not Necessary	4,069.80 FL	*- FL
73	1		*FRONT WINDSCREEN MOULDING	Necessary	157.30 FL	*157.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	51,734.60	28,433.50
-------------------------	------------------	------------------

- List Item Discount on L Items 20.00/20.00% (\$\$)	10,291.72	5,662.50
--	-----------	----------

Total Parts (\$\$)	41,442.88	22,771.00
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	800.00
2	SPRAY PAINTING CHARGE	New	1,800.00	600.00
3	WIRING CHARGE	New	2,000.00	30.00
4	TUFF KOTE	New	300.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	RE-SET FRT ABS SYSTEM	New	200.00	0.00
7	REMOVE/REFIX RADIATOR	New	90.00	50.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
9	REMOVE/REFIX FUSE BOX	New	120.00	0.00
10	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
11	REMOVE/REFIX DASHBOARD	New	550.00	150.00
12	REMOVE/REFIX AIR BAG / FRONT AND REAR SEATBELT }	New	550.00	150.00
13	REMOVE/REFIX ROOF TOP LINING }	New	550.00	0.00
14	RE-PROGRAME AIR BAG & SAFETY BELT SYSTEM }	New	550.00	150.00
15	DIAGNOSTIC & RESETTIG TO ERASE FAULT CODE }	New	550.00	0.00
16	DIAGNOSTIC & RESETTIG ADAS OPTICAL SENSOR }	New	550.00	0.00
Gross Labour Cost (S\$)			10,740.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >