

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401627
INV Date : 02-12-2024

Reference CD/FCI24080411/Rma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SFA 6733C
Insured Veh. SH 6691Z
Claim No. D24007454MFCT/CTPL
Policy No. D-24101861MFCT
Accident Date 22/08/2024
Inspection Date 10/09/2024

Description	Amount
Survey Inspection	300.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD		Ref:	CD/FCI24080411/Rma3q2	
16 RAFFLES QUAY		Date:	02/12/2024	
#42-01 HONG LEONG BUILDING		Code:	FCI2	
SINGAPORE 048581				
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SH 6691Z	Veh. Inspected	SFA 6733C	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24007454MFCT/CTPL	Excess	\$0.00	
Assign From	CHRIS LIM	Assign Date	26/08/2024	
2. Vehicle Details				
Make & Model	B.M.W. I4 EDRIVE35 GRAN COUPE	C.C	-	
Engine No.	HIDDEN	Year of Reg.	25/08/2023	
Chassis No.	WBY42AW000FR14754	Colour	GREEN	
Odometer	35321 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	245/40 R19	MICHELIN	6	
L/H Front Tyre	245/40 R19	MICHELIN	6	
R/H Rear Tyre	245/40 R19	MICHELIN	6	
L/H Rear Tyre	245/40 R19	MICHELIN	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/08/2024	Inspection Date	10/09/2024	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA RD #01-01 PERFORMANCE CENTRE			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SFA 6733C

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$150.00	\$80.00
1	FRT BUMPER PANEL PRIMED (PDC/PMA) (SN)	SCRATCHED	\$1,106.80	\$1,106.80
1	COVER FOR TOWING EYE PRIMER APPLIED (SN)	NOT NECESSARY	\$52.30	\$0.00
1	SET MOUNTING PDC/PMA SENSOR FRT (SN)	SERVICEABLE	\$75.55	\$0.00
1	RH AIR CURTAIN (SN)	SCRATCHED	\$55.50	\$55.50
1	FRT PRESSURE LIP (SN)	SERVICEABLE	\$62.15	\$0.00
1	FRT BUMPER PANEL LOWER SECTION (SN)	SERVICEABLE	\$221.40	\$0.00
1	RH SUPPORT (SN)	SERVICEABLE	\$165.15	\$0.00
1	RH AIR INLET GRILLE PARTLY CLOSED (SN)	SERVICEABLE	\$93.20	\$0.00
1	LH BUMPER BOTTOM GUIDE (SN)	SERVICEABLE	\$57.55	\$0.00
1	RH BUMPER BOTTOM GUIDE (SN)	SERVICEABLE	\$57.55	\$0.00
1	LH BUMPER TOP GUIDE (SN)	SERVICEABLE	\$57.55	\$0.00
1	RH BUMPER TOP GUIDE (SN)	SERVICEABLE	\$57.55	\$0.00
1	FRT SHOCK ABSORBER (SN)	SERVICEABLE	\$127.95	\$0.00
1	FRT BUMPER BOTTOM CARRIER (SN)	SERVICEABLE	\$355.90	\$0.00
1	FRT BUMPER CARRIER (SN)	SERVICEABLE	\$718.20	\$0.00
1	RH CRASH BOX (SN)	SERVICEABLE	\$105.20	\$0.00
1	FRT BOTTOM IMPACT ABSORBER (SN)	SERVICEABLE	\$127.95	\$0.00
1	EMBLEM (RFK/BEV) (SN)	NECESSARY	\$76.55	\$76.55
1	CARRIER PLATE 82MM (SN)	SERVICEABLE	\$94.35	\$0.00
1	PLAQUE 74MM (SN)	NOT NECESSARY	\$76.55	\$0.00
1	RH HEADLIGHT LED TECHNOLOGY (SN)	SCRATCHED	\$3,129.45	\$3,129.45
2	ULTRASONIC (SN)	SERVICEABLE	\$782.10	\$0.00
6	DECOUPLING RING (SN)	NECESSARY	\$33.90	\$33.90
			\$7,840.35	\$4,482.20
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPLACE FRONT BUMPER INCLUDE REMOVE ATTACHMENT ETC AND CARRYOUT NECESSARY REPAIR WORK ON ACCIDENT DAMAGE AREA		\$1,275.00	\$850.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PAINTING FRONT BUMPER		\$1,038.00	\$1,038.00
	TO CHECK ELECTRICAL WIRING SYSTEM OF THE FRONT SECTION FOR PROPER FUNCTION		\$177.00	\$177.00
	TO REPLACE RIGHT HEADLIGHT		\$481.00	\$481.00
			\$2,971.00	\$2,546.00
GRAND TOTAL			\$10,811.35	\$7,028.20
	RECOMMENDED COST OF REPAIRS			\$7,028.20
Report Ref No: CD/FCI24080411/Rma3q2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C




PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C



PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C



PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C



PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C





PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C



PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C



PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C



PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SFA 6733C

