9/11/24, 4:25 PM Adjuster Report

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI24080412/NNH3M4

Singapore 079909 Date: 11/09/2024

**REFERENCE** 

Insured/Claimant: VIDA & PARTNERS PTE LTD Policy No: DMHCSNW00026392301

Date of Loss: 22/08/2024 Nature of Claim: OD Claim No: SNM24D204743/C01/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLN5752P

 Make & Model:
 MERCEDES-BENZ E220D SE, 2.0 (A)
 Engine No:
 65492080083523

 Reg. Date:
 09/05/2017 (Man. Year: 2017)
 Chassis No:
 WDD2130042A185927

Colour: Black Odometer: 0 km

Engine Capacity: 1950 cc

Market Value/New Car Price: \$\$94,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Triangle 8 mm Rear Left Side: Triangle 8 mm
Front Right Side: Triangle 8 mm Rear Right Side: Triangle 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amoun	t (S\$) 0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 26/08/2024

VIN'S MOTOR PTE LTD

Date Inspected: 26/08/2024 Inspected At: 160 SIN MING DRIVE

#03-03 SIN MING AUTO CITY

SINGAPORE 575722

Estimated Period of Repair: 0.0 days

Adjuster: Muhammad Nazril Bin Abdullah Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### TOTAL LOSS ASPECT

Market Value : \$94,000.00 OMV : \$53,429.00 PARF Rebate (1): \$31,903.00 Quota Premium Paid: \$54,000.00 \$14,576.00 COE Rebate (2): Total Rebate (1) + (2) = : \$46,479.00

The total amount incurred will be Market Value \$94,000.00 minus Total Rebate \$46,479.00 = \$47,521.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Adjuster Report

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Sep 2024)

Parts: 143 MERCEDES-BENZ E220D SE 2.0 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN5752P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >