

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080413/APA3Q2**Date:** 10/12/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700018677
Claimant Vehicle No : SMN1232M **Insured Vehicle No :** SLQ965J
 Date of Loss: 07/08/2024 Nature of Claim: TP Claim No: 3676512230SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN1232M**
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 S CVT (A) Engine No: 2ZR2B72503
 Reg. Date: 25/07/2019 (Man. Year: 2018) Chassis No: ZVW508086939
 Colour: Silver Odometer: 320633 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 6 mm Rear Left Side: Davanti 6 mm
 Front Right Side: Davanti 6 mm Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,316.00	1,543.10	9,772.90	86.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	830.00	3,600.00	81.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,746.00	2,373.10	13,372.90	84.93
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	15,746.00	1,900.00	13,846.00	87.93
+ GST 9.00/9.00% (S\$)	1,417.14	171.00	1,246.14	87.93
Nett Amount (S\$)	17,163.14	2,071.00	15,092.14	87.93
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,258.25		

INSPECTION

Date of Assignment: 19/08/2024
 Date Inspected: 19/08/2024 Inspected At: SM Automotive (HQ)
 756 JURONG WEST STREET 74, #12-60
 Singapore 640756
 Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	480.90 FL	*480.90 FL
2	1		*REAR BUMPER LOWER GARNISH	Deformed	470.90 FL	*470.90 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	378.40 FL	*378.40 FL
4	2		*REAR BUMPER SIDE GARNISH RH /LH	Not Necessary	461.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER LH	Not Necessary	380.40 FL	*- FL
6	1		*REAR BUMPER TOW COVER	Not Necessary	61.30 FL	*- FL
7	1		*REAR BUMPER LAMP	N/S Cracked	460.80 FL	*230.40 FL
8	2		*REAR BUMPER LAMP BRACKET	Not Necessary	197.20 FL	*- FL
9	1		*REAR TAILGATE	Not Necessary	1,147.80 FL	*- FL
10	1		*REAR TAILGATE OUTER GARNISH	Repair	689.10 FL	*- FL
11	1		*REAR TAILGATE EMBLEM TOYOTA	Necessary	63.90 FL	*63.90 FL
12	1		*REAR TAILGATE EMBLEM HYBRID	Necessary	612.00 FL	*75.00 FL
13	1		*REAR TAILGATE EMBLEM PRIUS	Necessary	51.30 FL	*51.30 FL
14	1		*REAR TAILGATE LOCK	Not Necessary	578.90 FL	*- FL
15	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	230.40 FL	*- FL
16	1		*REAR WASHER STRIPE	Not Necessary	370.90 FL	*- FL
17	1		*REAR END PANEL	Repair	566.90 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	378.90 FL	*- FL
19	2		*REAR FENDER	Not Necessary	1,963.20 FL	*- FL
20	2		*REAR FENDER INNER SHIELD	Not Necessary	122.20 FL	*- FL
21	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	1,932.80 FL	*- FL
22	2		*REAR TAILLAMP	Not Necessary	940.40 FL	*- FL
23	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	244.60 FL	*- FL
24	2		*REAR TAILLAMP SIDE GARNISH	Not Necessary	343.80 FL	*- FL
25	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
27	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
28	1		*REAR TAILGATE OUTER MOULDING CLIPS	Not Necessary	40.00 FS	*- FS
29	1		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*REAR SPARE TYRE COMPARTMENT INSULATOR	Not Necessary	400.00 FS	*- FS
33	1		*REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
34	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,598.00** **1,980.80**
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,282.00 437.70

Total Parts (\$\$) **11,316.00** **1,543.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,800.00	300.00
2	LABOUR FOR SPRAYPAINTING	New	1,200.00	500.00
3	LABOUR FOR REMOVE & TRANSFER REAR TAILGATE FITTING	New	200.00	0.00
4	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	200.00	0.00
5	WIRING CHECK	New	80.00	30.00
6	LABOUR FOR REMOVE/REPAIR/STRAIGHTEN BOTH REAR CHASSIS FRAME	New	400.00	0.00
7	TO APPLY TUFF COATING RUST PROOF ACCIDENT AREAS	New	300.00	0.00
8	LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY /ROOF LINING CARPET	New	250.00	0.00
Gross Labour Cost (\$\$)			4,430.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >