

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24080415/AUA3Q2
Date: 12/03/2025

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100311918		
Claimant Vehicle No :	SMV2878B	Insured Vehicle No :	SJY2898M		
Date of Loss:	18/08/2024	Nature of Claim:	TP	Claim No:	5973140206SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV2878B		
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FCAH223479
Reg. Date:	30/09/2010 (Man. Year: 2010)	Chassis No:	KNAFW411MA5275632
Colour:	Bronze	Odometer:	190088 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,635.48	7,322.98	7,312.50	49.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,530.00	2,880.00	2,650.00	47.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,165.48	10,202.98	9,962.50	49.40
Approved Total (Overridden) (S\$)		8,150.00		
(S\$)	20,165.48	8,150.00	12,015.48	59.58
+ GST 9.00/9.00% (S\$)	1,814.89	733.50	1,081.39	59.58
Nett Amount (S\$)	21,980.37	8,883.50	13,096.87	59.58
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		9,510.75		
Global Sum Settlement (S\$)		9,500.00		

INSPECTION

Date of Assignment:	20/08/2024	
Date Inspected:	20/08/2024 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	698.00 FL	*698.00 FL
2	5		*REAR BUMPER BRACKET	Not Necessary	110.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	32.00 FL	*16.00 FL
4	1		*REAR BUMPER CENTER GARNISH	Deformed	246.00 FL	*246.00 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET	N/S Dented	144.00 FL	*72.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Cracked	394.00 FL	*394.00 FL
7	1		*REAR BUMPER SPONGE	Cracked	189.00 FL	*189.00 FL
8	1		*TAIL LAMP	N/S Cracked	684.00 FL	*342.00 FL
9	1		*TAIL LAMP PANEL LH	Dented	190.00 FL	*190.00 FL
10	1		*REAR FENDER LH	Distorted	935.00 FL	*935.00 FL
11	1		*REAR FENDER INNER PANEL LH	Repair	912.00 FL	*- FL
12	1		*REAR FENDER AIR VENT LH	Missing	98.20 FL	*98.20 FL
13	1		*REAR FENDER INNER COWLING	N/S Torn	196.00 FL	*98.00 FL
14	1		*REAR FENDER INNER TRIM	N/S Torn	464.00 FL	*232.00 FL
15	1		*REAR WINDSCREEN MOULDING	Necessary	135.00 FL	*135.00 FL
16	1		*REAR DOOR LH	Dented	1,170.00 FL	*1,170.00 FL
17	1		*REAR DOOR INNER LH	Not Necessary	1,170.00 FL	*- FL
18	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	150.00 FL	*- FL
19	1		*REAR DOOR INNER LOCK LH	Not Necessary	360.00 FL	*- FL
20	1		*BOOT LID	Dented	897.00 FL	*897.00 FL
21	1		*BOOT LID MOULDING	Not Necessary	292.00 FL	*- FL
22	1		*BOOT LID LAMP	N/S Cut	452.00 FL	*226.00 FL
23	1		*BOOT LID LOGO	Necessary	65.00 FL	*65.00 FL
24	1		*REAR BUMPER EMBLEM CERATO	Necessary	43.00 FL	*43.00 FL
25	1		*REAR BUMPER EMBLEM FORTE	Necessary	58.00 FL	*58.00 FL
26	2		*BOOT LID STOPPER	Not Necessary	38.00 FL	*- FL
27	2		*BOOT LID HINGE	Not Necessary	136.00 FL	*- FL
28	1		*BOOT LID INSULATOR	Not Necessary	231.00 FL	*- FL
29	1		*BOOT LID WEATHERSTRIP	Cut	148.00 FL	*148.00 FL
30	1		*BOOT LID LOCK	Not Necessary	127.00 FL	*- FL
31	1		*BOOT LID LOWER LOCK	Not Necessary	25.00 FL	*- FL
32	1		*REAR END PANEL	Deformed	382.00 FL	*382.00 FL
33	1		*REAR END PANEL TOP GARNISH	Deformed	143.00 FL	*143.00 FL
34	1		*REAR FLOOR PANEL	Not Necessary	896.00 FL	*- FL
35	1		*REAR FLOOR SIDE PANEL LH	Repair	438.00 FL	*- FL
36	1		*REAR FLOOR PANEL TOP BOARD	Torn	241.00 FL	*241.00 FL
37	2		*REVERSE SENSOR	Damaged	624.00 FL	*624.00 FL
38	4		*REVERSE SENSOR HOLDER	Necessary	208.00 FL	*100.00 FL
39	1		*REVERSE SENSOR WIREHARNESS	Not Necessary	496.00 FL	*- FL
40	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
41	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
42	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
43	1		*SET BOOT LID MOULDING CLIP	Not Necessary	80.00 FS	*- FS
44	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
45	1		*BOOT LID EMBLEM C&C (SPECIAL TYPE)	Necessary	150.00 FS	*45.00 FS
46	1		*REAR DOOR LH SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*SET REAR DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
48	1		*REAR FENDER LH SEALANT	Necessary	150.00 FS	*60.00 FS
49	1		*SET REAR FENDER INNER COWLING CLIP	Necessary	80.00 FS	*20.00 FS
50	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
51	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
52	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
53	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
54	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
55	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REVERSE SENSOR	Repeated	220.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					16,057.20	8,097.20
- List Item Discount on L Items 10.00/10.00% (S\$)					1,421.72	774.22
Total Parts (S\$)					14,635.48	7,322.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,WELDING ,GRAZING CUT JOINT STRAIGHTEN ALL AFFECTED PARTS	New	2,200.00	1,300.00
2	TO PUTTY POLISH SPRAY PAINT WAX ALL AFFECTED PANELS	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	120.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
6	TRANSFER REAR DOOR MECHANISM	New	80.00	60.00
7	REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
9	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	REMOVE AND REFIX FUEL TANK TO FACILITATE REPLACEMENT	New	80.00	60.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,530.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >