

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080417/APA3Q2**Date:** 17/03/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230124327
Claimant Vehicle No : SNL4782X **Insured Vehicle No :** SNN6773Z
 Date of Loss: 16/08/2024 Nature of Claim: TP Claim No: 9120882303SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNL4782X**
 Make & Model: TOYOTA YARIS CROSS, 1.5 HYBRID G CVT (A) Engine No: M15AY122005
 Reg. Date: 09/08/2021 (Man. Year: 2021) Chassis No: MXPJ103008263
 Colour: White Odometer: 94568 km
 Engine Capacity: 1490 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,107.07	5,338.35	6,768.72	55.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,460.00	1,900.00	3,560.00	65.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,567.07	7,238.35	10,328.72	58.80
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	17,567.07	5,700.00	11,867.07	67.55
+ GST 9.00/9.00% (S\$)	1,581.04	513.00	1,068.04	67.55
Nett Amount (S\$)	19,148.11	6,213.00	12,935.11	67.55
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,660.25		
Global Sum Settlement (S\$)		6,650.00		

INSPECTION

Date of Assignment: 20/08/2024
 Date Inspected: 20/08/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Deformed	485.40 FL	*485.40 FL
2	1		*REAR BUMPER (LOWER)	Deformed	498.10 FL	*498.10 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	220.60 FL	*- FL
4	1		*REAR BUMPER LOWER CENTER COVER	Torn	498.00 FL	*310.00 FL
5	2		*REAR BUMPER SIDE RETAINER	Not Necessary	196.60 FL	*- FL
6	1		*TAILGATE	Dented	1,280.10 FL	*1,280.10 FL
7	2		*TAILGATE REFLECTOR	Not Necessary	393.40 FL	*- FL
8	2		*TAILGATE LAMP	Not Necessary	663.20 FL	*- FL
9	2		*TAILGATE DAMPER	Not Necessary	423.00 FL	*- FL
10	1		*TAILGATE INNER HOLDER	Not Necessary	69.30 FL	*- FL
11	1		*TAILGATE LOGO	Not Necessary	81.70 FL	*- FL
12	1		*TAILGATE EMBLEM YARIS	Necessary	98.70 FL	*98.70 FL
13	1		*TAILGATE EMBLEM CROSS	Necessary	93.30 FL	*93.30 FL
14	2		*TAILGATE STOPPER	Not Necessary	76.20 FL	*- FL
15	1		*TAILGATE TOP LOCK	Damaged	268.10 FL	*268.10 FL
16	1		*TAILGATE LOWER LOCK	Not Necessary	68.00 FL	*- FL
17	1		*TAILGATE INNER TRIM	Cracked	651.30 FL	*651.30 FL
18	1		*TAILGATE WEATHERSTRIP	Cut	285.70 FL	*285.70 FL
19	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	191.30 FL	*191.30 FL
20	1		*TAIL LAMP	O/S Cracked	990.60 FL	*495.30 FL
21	2		*TAIL LAMP LOWER BRACKET	Not Necessary	96.60 FL	*- FL
22	1		*REAR FENDER INNER TRIM	O/S Cracked	1,022.60 FL	*511.30 FL
23	2		*REAR FENDER COWLING	Not Necessary	253.40 FL	*- FL
24	2		*REAR FENDER ARCED GARNISH	Not Necessary	563.20 FL	*- FL
25	1		*REAR END PANEL	Dented	516.40 FL	*516.40 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	516.40 FL	*298.00 FL
27	1		*REAR FLOOR PANEL	Repair	865.70 FL	*- FL
28	1		*REAR FLOOR PANEL CENTRE SPONGE	Not Necessary	217.60 FL	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Deformed	317.60 FL	*317.60 FL
30	2		*REAR TOOLS SPONGE	Not Necessary	334.80 FL	*- FL
31	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	894.40 FL	*447.20 FL
32	4		*REVERSE SENSOR HOLDER	Necessary (2 PCS ONLY)	268.00 FL	*50.00 FL
33	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	476.80 FL	*- FL
34	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
36	1		*REAR BUMPER LOWER CENTRE GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
37	1		*SET REAR BUMPER REFLECTOR GARNISH CLIP	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR SPOILER CLIP	Not Necessary	80.00 FS	*- FS
39	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
40	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
41	1		*SET TAILGATE OUTER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
42	1		*SET TAILGATE INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
43	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
45	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
46	1		*SET REAR FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
47	1		*SET REAR FENDER ARCED GARNISH CLIP	Not Necessary	50.00 FS	*- FS
48	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
49	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
50	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
51	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,576.10 7,037.80
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,469.03 1,699.45

Total Parts (\$\$) 12,107.07 5,338.35

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	700.00
3	TUFF COAT	New	350.00	60.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	180.00	0.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
9	TRANSFER TAILGATE MECHANISM	New	150.00	60.00
10	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	120.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	250.00	0.00
Gross Labour Cost (\$\$)			5,460.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >