

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080418/AMA3Q2**Date:** 30/01/2026REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800042710
Claimant Vehicle No :	GBF8473K	Insured Vehicle No :	SJN64Z
Date of Loss:	14/08/2024	Nature of Claim:	TP
		Claim No:	8469535251SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF8473K	Engine No:	1KD2682298
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR MT (M)	Chassis No:	JTFHT02P400215389
Reg. Date:	28/03/2017 (Man. Year: 2016)	Odometer:	212155 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,314.05	6,395.97	10,918.08	63.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,170.00	2,000.00	5,170.00	72.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,484.05	8,395.97	16,088.08	65.71
Approved Total (Overridden) (S\$)		6,650.00		
Nett Amount (S\$)	24,484.05	6,650.00	17,834.05	72.84
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	21/08/2024	
Date Inspected:	21/08/2024	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	495.70 FL	*495.70 FL
2	1		*FRONT BUMPER LOWER SIDE GRILLE	Not Necessary	195.40 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	238.10 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER	N/S Cracked	360.00 FL	*180.00 FL
5	1		*HEADLAMP	N/S Cracked	1,516.00 FL	*758.00 FL
6	1		*FRONT CORNER PANEL LH	Not Necessary	389.70 FL	*- FL
7	1		*FRONT CENTRE GRILLE BASE	Not Necessary	894.20 FL	*- FL
8	1		*FRONT CENTRE GRILLE GARNISH (UPPER)	Not Necessary	249.50 FL	*- FL
9	1		*FRONT CENTRE GRILLE GARNISH (LOWER)	Not Necessary	429.50 FL	*- FL
10	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FL	*- FL
11	1		*FRONT DOOR PILLAR (OUTER)LH	Dented	984.90 FL	*984.90 FL
12	1		*FRONT DOOR PILLAR (INNER)LH	Repair	896.20 FL	*- FL
13	1		*FRONT DOOR STEP PANEL GARNISH LH	Cut	198.10 FL	*198.10 FL
14	1		*FRONT DOOR STEP PANEL LH	Dented	235.00 FL	*235.00 FL
15	1		*FRONT DOOR LH	Dented	1,983.70 FL	*1,580.00 FL
16	1		*FRONT DOOR INNER LOCK LH	Not Necessary	469.80 FL	*- FL
17	1		*FRONT DOOR INNER TRIM LH	Cracked	847.90 FL	*687.00 FL
18	1		*FRONT DOOR LOCK CATCHER LH	Not Necessary	25.20 FL	*- FL
19	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	164.60 FL	*- FL
20	1		*FRONT DOOR OUTER STRIP LH	Not Necessary	137.40 FL	*- FL
21	1		*FRONT DOOR ARCED RUBBER LH	Not Necessary	136.80 FL	*- FL
22	1		*FRONT WIRE ADAPTOR HOLDER LH	Cracked	94.60 FL	*94.60 FL
23	1		*FRONT MUDFLAP LH	Not Necessary	159.60 FL	*- FL
24	1		*FRONT WHEEL ARCH RUBBER LH	Not Necessary	92.20 FL	*- FL
25	1		*FRONT WHEEL CAP LH	Cut	213.80 FL	*213.80 FL
26	1		*FRONT LOWER ARM LH	Not Necessary	497.40 FL	*- FL
27	1		*FRONT UPPER ARM LH	Bent	464.30 FL	*464.30 FL
28	1		*FRONT KNUCKLE ARM LH	Damaged	672.10 FL	*672.10 FL
29	1		*FRONT WHEEL HUB LH	Damaged	349.70 FL	*349.70 FL
30	1		*FRONT WHEEL BEARING LH	Damaged	268.10 FL	*268.10 FL
31	1		*FRONT SHOCK ABSORBER LH	Not Necessary	379.80 FL	*- FL
32	1		*FRONT STABILIZER LINKAGE LH	Not Necessary	160.00 FL	*- FL
33	1		*CENTER PILLAR (OUTER)RH	Repair	692.00 FL	*- FL
34	1		*SLIDING DOOR LH	Repair	2,290.60 FL	*- FL
35	1		*SLIDING DOOR INNER LOCK (BACK) LH	Not Necessary	499.30 FL	*- FL
36	2		*SET SLIDING DOOR STOPPER	Not Necessary	124.20 FL	*- FL
37	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
38	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
39	1		*FRONT DOOR SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*SET FRONT DOOR INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
41	1		*FRONT DOOR COMPANY STICKER (SPECAIL TYPE)	Necessary	550.00 FS	*200.00 FS
42	1		*FRONT DOOR SIDE LINING (SPECAIL TYPE)	Necessary	200.00 FS	*60.00 FS
43	1		*FRONT DOOR LTA STICKER LH	Necessary	80.00 FS	*30.00 FS
44	1		*WHEEL TYRE LH	Not Necessary	380.00 FS	*- FS
45	1		*WHEEL RIM LH	Not Necessary	550.00 FS	*- FS
46	1		*FRONT WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
47	1		*FRONT WINDSCREEN INNER SHIELD	Not Necessary	120.00 FS	*- FS
48	1		*SLIDING DOOR COMPANY STICKER	Necessary	1,200.00 FS	*600.00 FS
49	1		*SET DOOR VISOR	Necessary	350.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,795.40	8,191.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,481.35	1,795.33
Total Parts (\$\$)	17,314.05	6,395.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	2,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	2,000.00	700.00
3	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
4	TUFF COAT	New	450.00	80.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	150.00	0.00
7	REMOVE AND REFIX DASHBOARD	New	650.00	0.00
8	RESET RADIO SYSTEM	New	150.00	0.00
9	TRANFER FRONT DOOR MECHANISM	New	80.00	40.00
10	REMOVE AND REFIX FRONT DOOR WINDOW GLASS	New	120.00	40.00
11	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	680.00	200.00
12	TO PREE FRONT WHEEL BEARING	New	80.00	0.00
13	FOUR WHEEL ALIGNMENT	New	120.00	80.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (\$\$)	7,170.00
				2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >