

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080421/AMA3Q2**Date:** 15/08/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900105142
Claimant Vehicle No : SKJ1919K **Insured Vehicle No :** SLT471B
 Date of Loss: 19/08/2024 Nature of Claim: TP Claim No: 9222458653SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ1919K**
 Make & Model: MERCEDES-BENZ A200, 1.3 AMG LINE Engine No: 28291480234083
 SALOON AUTO (A)
 Reg. Date: 17/01/2020 (Man. Year: 2019) Chassis No: WDD1771872J130665
 Colour: Grey Odometer: 97111 km
 Engine Capacity: 1332 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R19 Rear Tyre Size: 225/40 R19
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	67,942.20	42,783.40	25,158.80	37.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,700.00	5,060.00	6,640.00	56.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	79,642.20	47,843.40	31,798.80	39.93
Approved Total (Overridden) (S\$)		38,200.00		
(S\$)	79,642.20	38,200.00	41,442.20	52.04
+ GST 9.00/9.00% (S\$)	7,167.80	3,438.00	3,729.80	52.04
Nett Amount (S\$)	86,810.00	41,638.00	45,172.00	52.04
+ Car Rental (20.0 x S\$100.00/day) (S\$)		2,000.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		43,765.25		
Global Sum Settlement (S\$)		43,700.00		

INSPECTION

Date of Assignment: 21/08/2024
 Date Inspected: 21/08/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 16.0 days

Adjuster: ADRIAN LING

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,809.00 FL	*1,510.00 FL
2	1		*FRONT BUMPER LOGO	Necessary	98.00 FL	*98.00 FL
3	2		*FRONT BUMPER SIDE GRILLE	Not Necessary	396.00 FL	*- FL
4	2		*FRONT BUMPER SIDE AIR DUCT	Not Necessary	398.00 FL	*- FL
5	1		*FRONT BUMPER RADAR SENSOR	Cracked	1,532.00 FL	*1,532.00 FL
6	1		*FRONT BUMPER RADAR SENSOR HOLDER	Cracked	86.00 FL	*86.00 FL
7	1		*FRONT BUMPER RADAR SENSOR WIRE HARNESS	Not Necessary	253.00 FL	*- FL
8	1		*FRONT BUMPER UPPER BEAM	Cracked	229.00 FL	*229.00 FL
9	1		*FRONT BUMPER UPPER BEAM SIDE SUPPORT	N/S Cracked	278.00 FL	*139.00 FL
10	1		*FRONT BUMPER LOWER GRILLE	Cracked	343.00 FL	*343.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	572.00 FL	*572.00 FL
12	2		*FRONT BUMPER REINFORCEMENT ABSORB PANEL	Not Necessary	394.00 FL	*- FL
13	2		*FRONT BUMPER IMPACT SENSOR	Not Necessary	568.00 FL	*- FL
14	1		*FRONT BUMPER SPONGE	Cracked	325.00 FL	*325.00 FL
15	1		*FRONT BUMPER TOP RUBBER	Not Necessary	48.00 FL	*- FL
16	1		*FRONT BUMPER BOTTOM COVER GARNISH	Cracked	799.00 FL	*799.00 FL
17	1		*FRONT NUMBER PLATE GARNISH	Deformed	149.00 FL	*149.00 FL
18	2		*FRONT HEADLAMP (LED)	Cracked	7,728.00 FL	*7,728.00 FL
19	2		*FRONT HEADLAMP RING GARNISH	Damaged	196.00 FL	*196.00 FL
20	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	272.00 FL	*- FL
21	1		*FRONT GRILLE WITH CHROME	Missing	1,754.00 FL	*1,419.00 FL
22	1		*FRONT GRILLE LOGO	Missing	238.00 FL	*238.00 FL
23	1		*FRONT INNER AIR GUARD	Cracked	196.00 FL	*196.00 FL
24	2		*FRONT INNER AIR GUARD	Not Necessary	392.00 FL	*- FL
25	1		*BONNET	Dented	1,975.00 FL	*1,975.00 FL
26	2		*BONNET HINGE	Not Necessary	270.00 FL	*- FL
27	1		*BONNET BOTTOM LOCK	Damaged	271.00 FL	*271.00 FL
28	4		*BONNET STOPPER	Not Necessary	256.00 FL	*- FL
29	1		*BONNET PUSH-UP SPRING	Activated	328.00 FL	*328.00 FL
30	1		*FRONT RADIATOR TOP PANEL	Cracked	983.00 FL	*983.00 FL
31	1		*FRONT RADIATOR SUPPORT BRACKET	Cracked	138.00 FL	*138.00 FL
32	1		*FRONT RADIATOR TOP PANEL GARNISH	Deformed	486.00 FL	*486.00 FL
33	2		*FRONT RADIATOR SUPPORT STAND PANEL	Not Necessary	1,384.00 FL	*- FL
34	1		*FRONT RADIATOR SUPPORT PANEL FRONT AIR DUCT	Cracked	155.00 FL	*155.00 FL
35	1		*RADIATOR	Dented	1,695.00 FL	*1,695.00 FL
36	1		*RADIATOR FAN MOTOR	Not Necessary	1,371.00 FL	*- FL
37	1		*RADIATOR FAN BLADE	Not Necessary	652.00 FL	*- FL
38	1		*RADIATOR FAN COWLING	Cracked	966.00 FL	*490.00 FL
39	1		*RADIATOR HOSE (TOP)	Not Necessary	192.00 FL	*- FL
40	1		*RADIATOR HOSE (LOWER)	Not Necessary	186.00 FL	*- FL
41	1		*RADIATOR SPARE TANK	Not Necessary	328.00 FL	*- FL
42	2		*RADIATOR SPARE TANK HASE	Not Necessary	170.00 FL	*- FL
43	1		*FRONT AIR GUARD (UPPER)	Cracked	268.00 FL	*268.00 FL
44	1		*FRONT AIR GUARD (LOWER)	Cracked	235.00 FL	*235.00 FL
45	1		*FRONT UPPER WIND SHUTTLE (AUTOR)	Cracked	658.00 FL	*658.00 FL
46	1		*FRONT LOWER WIND SHUTTLE (AUTOR)	Cracked	462.00 FL	*462.00 FL
47	1		*RADIATOR	Repeated	1,695.00 FL	*- FL
48	4		*RADIATOR MOUNTING	Not Necessary	152.00 FL	*- FL
49	1		*AIRCON CONDENSER	Dented	1,533.00 FL	*1,533.00 FL
50	1		*AIRCON PIPE	Not Necessary	436.00 FL	*- FL
51	1		*INTERCOOLER	Bent	1,870.00 FL	*1,870.00 FL
52	2		*INTERCOOLER PIPE	Not Necessary	968.00 FL	*- FL
53	1		*FRONT AIR CLEANER	Cracked	595.00 FL	*595.00 FL
54	1		*FRONT AIR CLEANER INLET AIR DUCT	Not Necessary	553.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*WASHER TANK	Not Necessary	328.00 FL	*- FL
56	1		*ALTERNATOR	Cracked	3,910.00 FL	*3,910.00 FL
57	1		*FAN BELT TENSIONER	Not Necessary	348.00 FL	*- FL
58	1		*ENGINE CONTROL MODULE (ECU)	Cracked	2,983.00 FL	*2,983.00 FL
59	2		*HORN	Not Necessary	570.00 FL	*- FL
60	1		*OUTSIDE TEMPERATURE SENSOR	Not Necessary	96.00 FL	*- FL
61	1		*FRONT FENDER	N/S Distorted	1,910.00 FL	*955.00 FL
62	2		*FRONT FENDER SUPPORT BRACKET	Not Necessary	192.00 FL	*- FL
63	2		*FRONT FENDER COWLING EXTEND GARNISH	Not Necessary	168.00 FL	*- FL
64	2		*FRONT FENDER COWLING (FRONT)	Not Necessary	698.00 FL	*- FL
65	1		*REAR BUMPER	Distorted	1,985.00 FL	*1,770.00 FL
66	2		*REAR BUMPER REFLECTOR	N/S Missing / O/S Cracked	192.00 FL	*192.00 FL
67	1		*REAR BUMPER CENTRE FRAME	Cracked	236.00 FL	*236.00 FL
68	1		*REAR BUMPER TOWING COVER	Deformed	113.00 FL	*113.00 FL
69	2		*REAR BUMPER EXHAUST CHROME RING	Cracked	692.00 FL	*692.00 FL
70	1		*REAR BUMPER BOTTOM CENTER GARNISH	Not Necessary	178.00 FL	*- FL
71	1		*REAR BUMPER LOWER GARNISH	Deformed	698.00 FL	*698.00 FL
72	1		*REAR BUMPER LOWER GARNISH CHROME	Necessary	439.00 FL	*439.00 FL
73	2		*REAR BUMPER UPPER CORNER BRACKET	Not Necessary	444.00 FL	*- FL
74	2		*REAR BUMPER SIDE RETAINER	Not Necessary	450.00 FL	*- FL
75	1		*REAR BUMPER REINFORCEMENT	Dented	763.00 FL	*763.00 FL
76	2		*REAR BUMPER LOWER CENTER BRACKET	Cracked	170.00 FL	*170.00 FL
77	2		*REAR BUMPER LOWER SIDE BRACKET	Not Necessary	464.00 FL	*- FL
78	3		*REAR BUMPER BOTTOM GARNISH SUPPORT	Not Necessary	339.00 FL	*- FL
79	2		*REAR FENDER COWLING	Not Necessary	376.00 FL	*- FL
80	2		*REAR FENDER INNER TRIM	Not Necessary	876.00 FL	*- FL
81	2		*REAR FENDER DRAIN GARNISH	Not Necessary	570.00 FL	*- FL
82	2		*TAILLAMP	Cracked	1,572.00 FL	*1,572.00 FL
83	1		*BOOTLID	Dented	3,195.00 FL	*2,510.00 FL
84	1		*BOOTLID LOGO	Necessary	97.00 FL	*97.00 FL
85	1		*BOOTLID TOP LOCK	Damaged	135.00 FL	*135.00 FL
86	1		*BOOTLID LOWER LOCK	Not Necessary	452.00 FL	*- FL
87	1		*BOOTLID INNER TRIM	Not Necessary	373.00 FL	*- FL
88	1		*BOOTLID WEATHERSTRIP	Cut	258.00 FL	*258.00 FL
89	1		*BOOTLID LAMP	O/S Cracked	1,068.00 FL	*534.00 FL
90	1		*REVERSE CAMERA	Not Necessary	1,150.00 FL	*- FL
91	1		*REAR END PANEL	Dented	1,321.00 FL	*1,209.00 FL
92	1		*REAR END PANEL TOP GARNISH	Cracked	189.00 FL	*189.00 FL
93	1		*REAR EXHAUST BOX	Not Necessary	1,896.00 FL	*- FL
94	2		*REAR EXHAUST MOUNTING	Not Necessary	150.00 FL	*- FL
95	1		*REAR EXHAUST GASKET	Not Necessary	88.00 FL	*- FL
96	1		*REAR EXHAUST INSULATOR	Not Necessary	342.00 FL	*- FL
97	1		*FRONT NUMBER PLATE	Missing	50.00 FS	*50.00 FS
98	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*50.00 FS
99	1		*SET FRONT BUMPER SIDE GRILLE CLIP	Not Necessary	50.00 FS	*- FS
100	1		*SET FRONT BUMPER BOTTOM COVER GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
101	1		*SET FRONT NUMBER PLATE GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
102	1		*SET SUPPORT PANEL UNDER COVER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
103	1		*SET FRONT FENDER COWLING (FRONT) CLIP	Not Necessary	50.00 FS	*- FS
104	1		*SET FRONT FENDER COWLING (BACK) CLIP	Not Necessary	50.00 FS	*- FS
105	1		*COOLANT	Necessary	180.00 FS	*40.00 FS
106	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
107	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
108	1		*SET REAR BUMPER BOTTOM CENTER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
109	1		*SET REAR BUMPER LOWER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
110	1		*BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
111	1		*BOOTLID SPOILER (SPECIL TYPE)	Not Necessary	850.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
112	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
113	1		*BOOTLID CENTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
114	1		*SET BOOTLID NUMBER PLATE LAMP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
115	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
116	1		*SET REAR FENDER DRAIN GARNISH CLIP	Not Necessary	80.00 FS	*- FS
117	1		*SET REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
118	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
119	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
120	1		*SET REAR END PANEL INNER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **75,218.00** **47,496.00**
- List Item Discount on L Items 10.00/10.00% (\$\$) 7,275.80 4,712.60

Total Parts (\$\$) **67,942.20** **42,783.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	50.00
4	REFOCUS HEADLAMP BEAM	New	80.00	0.00
5	WIRING CHECK	New	650.00	100.00
6	REMOVE AND REFIX RADAR SENSOR AND REPROGRAMMING	New	850.00	550.00
7	REMOVE AND REFIX AIR COOLER	New	120.00	60.00
8	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
9	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
10	REMOVE AND REFIX ECU AND REPROGRAMMING	New	750.00	400.00
11	REMOVE AND REFIX ALTERNATOR	New	180.00	120.00
12	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	800.00
13	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
14	TUFF COAT	New	350.00	60.00
15	WIRING CHECK	New	180.00	30.00
16	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	380.00	60.00
17	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
18	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
19	REMOVE AND REFIX REVERSE CAMERA	New	80.00	50.00
20	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	650.00	200.00
Gross Labour Cost (\$\$)			11,700.00	5,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >