

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To In: _____ Vehicle No: _____
 at W: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vek: _____
 (Policy Condition)

N/S	O/S

Remark: There had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKJ1919K Regn: 2020/ Jan.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes Benz Aro 1332
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 19111 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD1771872J1.30665
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/40R19
 R: 225/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 21/08/24
 Survey held at HD Perfect

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP AIG</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes C</u>
	<u>1st Survey : No C</u>
	<u>MV : 120K</u>
	<u>PV : 43.8K</u>
	<u>Nett : 76.2K</u>
	<u>720A</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)

Survey Fee:

Transportation:

3 - RS \$1

Photos


Others

Report Form: _____

Report Form: _____

Company Reg No: 202136904Z

E-mail: hdperfectautowork@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

DATE : 20.08.2024

TO	: AIG MOTOR CLAIMS DEPTS
VEHICLE NO	: SKJ1919K
MODEL	: MERCEDES A200
DATE OF ACCIDENT	: 19.08.2024
TIME OF ACCIDENT	: 19:15 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Deleted</i>	1	\$ -	\$ -
2	FRONT BUMPER LOGO <i>in</i>	1	\$ -	\$ -
3	FRONT BUMPER SIDE GRILLE <i>new</i>	2	\$ -	\$ -
4	FRONT BUMPER SIDE AIR DUCT <i>new</i>	2	\$ -	\$ -
5	FRONT BUMPER RADAR SENSOR <i>could</i>	1	\$ -	\$ -
6	FRONT BUMPER RADAR SENSOR HOLDER <i>could</i>	1	\$ -	\$ -
7	FRONT BUMPER RADAR SENSOR WIRE HARNESS <i>in</i>	1	\$ -	\$ -
8	FRONT BUMPER UPPER BEAM <i>could</i>	1	\$ -	\$ -
9	FRONT BUMPER UPPER BEAM SIDE SUPPORT <i>List could</i>	2	\$ -	\$ -
10	FRONT BUMPER LOWER GRILLE <i>could</i>	1	\$ -	\$ -
11	FRONT BUMPER REINFORCEMENT <i>Deleted</i>	1	\$ -	\$ -
12	FRONT BUMPER REINFORCEMENT ABSORB PANEL <i>in</i>	2	\$ -	\$ -
13	FRONT BUMPER IMPACT SENSOR <i>new</i>	2	\$ -	\$ -
14	FRONT BUMPER SPONGE <i>could</i>	1	\$ -	\$ -
15	FRONT BUMPER TOP RUBBER <i>new</i>	1	\$ -	\$ -
16	FRONT BUMPER BOTTOM COVER GARNISH <i>could</i>	1	\$ -	\$ -
17	FRONT NUMBER PLATE GARNISH <i>Deleted</i>	1	\$ -	\$ -
18	FRONT HEADLAMP (LED) <i>could</i>	2	\$ -	\$ -
19	FRONT HEADLAMP RING GARNISH <i>new</i>	2	\$ -	\$ -
20	FRONT HEADLAMP LOWER BRACKET <i>new</i>	2	\$ -	\$ -
21	FRONT GRILLE WITH CHROME <i>Missing</i>	1	\$ -	\$ -

VEHICLE NO	: SKJ1919K
MODEL	: MERCEDES A200
DATE OF ACCIDENT	: 19.08.2024
TIME OF ACCIDENT	: 19:15 HOURS

22	FRONT GRILLE LOGO <i>Missing</i>	1	\$	-	\$	-
23	FRONT INNER AIR GUARD <i>3/4" curled</i>	1	\$	-	\$	-
24	FRONT INNER AIR GUARD <i>3/4" curled</i>	2	\$	-	\$	-
25	BONNET <i>Deleted</i>	1	\$	-	\$	-
26	BONNET HINGE <i>New</i>	2	\$	-	\$	-
27	BONNET BOTTOM LOCK <i>End</i>	1	\$	-	\$	-
28	BONNET STOPPER <i>New</i>	4	\$	-	\$	-
29	BONNET PUSH-UP SPRING <i>Adapted</i>	1	\$	-	\$	-
30	FRONT RADIATOR TOP PANEL <i>Curled</i>	1	\$	-	\$	-
31	FRONT RADIATOR SUPPORT BRACKET <i>Curled</i>	1	\$	-	\$	-
32	FRONT RADIATOR TOP PANEL GARNISH <i>Deleted</i>	1	\$	-	\$	-
33	FRONT RADIATOR SUPPORT STAND PANEL <i>New</i>	2	\$	-	\$	-
34	FRONT RADIATOR SUPPORT PANEL FRONT AIR DUCT <i>Curled</i>	1	\$	-	\$	-
35	RADIATOR <i>Deleted</i>	1	\$	-	\$	-
36	RADIATOR FAN MOTOR <i>New</i>	1	\$	-	\$	-
37	RADIATOR FAN BLADE <i>New</i>	1	\$	-	\$	-
38	RADIATOR FAN COWLING <i>Curled</i>	1	\$	-	\$	-
39	RADIATOR HOSE (TOP) <i>3/4"</i>	1	\$	-	\$	-
40	RADIATOR HOSE (LOWER) <i>3/4"</i>	1	\$	-	\$	-
41	RADIATOR SPARE TANK <i>3/4"</i>	1	\$	-	\$	-
42	RADIATOR SPARE TANK HASE <i>3/4"</i>	2	\$	-	\$	-
43	FRONT AIR GUARD (UPPER) <i>3/4"</i>	1	\$	-	\$	-
44	FRONT AIR GUARD (LOWER) <i>3/4"</i>	1	\$	-	\$	-
45	FRONT UPPER WIND SHUTTLE (AUTOR) <i>3/4"</i>	1	\$	-	\$	-
46	FRONT LOWER WIND SHUTTLE (AUTOR) <i>3/4"</i>	1	\$	-	\$	-
47	RADIATOR <i>Replaced</i>	1	\$	-	\$	-
48	RADIATOR MOUNTING <i>New</i>	4	\$	-	\$	-
49	AIRCON CONDENSER <i>Deleted</i>	1	\$	-	\$	-
50	AIRCON PIPE <i>New</i>	1	\$	-	\$	-
51	INTERCOOLER <i>Buy</i>	1	\$	-	\$	-
52	INTERCOOLER PIPE <i>New</i>	2	\$	-	\$	-
53	FRONT AIR CLEANER <i>Curled</i>	1	\$	-	\$	-
54	FRONT AIR CLEANER INLET AIR DUCT <i>New</i>	1	\$	-	\$	-
55	WASHER TANK <i>New</i>	1	\$	-	\$	-

VEHICLE NO : SKJ1919K
 MODEL : MERCEDES A200
 DATE OF ACCIDENT : 19.08.2024
 TIME OF ACCIDENT : 19:15 HOURS

56	ALTERNATOR	could	1	\$	-	\$	-
57	FAN BELT TENSIONER	new	1	\$	-	\$	-
58	ENGINE CONTROL MODULE (ECU)	could	1	\$	-	\$	-
59	HORN	new	2	\$	-	\$	-
60	OUTSIDE TEMPERATURE SENSOR	new	1	\$	-	\$	-
61	FRONT FENDER	CH Dishd	2	\$	-	\$	-
62	FRONT FENDER SUPPORT BRACKET	gap	2	\$	-	\$	-
63	FRONT FENDER COWLING EXTEND GARNISH	gap	2	\$	-	\$	-
64	FRONT FENDER COWLING (FRONT)		2	\$	-	\$	-
65	REAR BUMPER	Dishd	1	\$	-	\$	-
66	REAR BUMPER REFLECTOR	LH Missy, RH could	2	\$	-	\$	-
67	REAR BUMPER CENTRE FRAME	could	1	\$	-	\$	-
68	REAR BUMPER TOWING COVER	Dishd	1	\$	-	\$	-
69	REAR BUMPER EXHAUST CHROME RING	could	2	\$	-	\$	-
70	REAR BUMPER BOTTOM CENTER GARNISH	new	1	\$	-	\$	-
71	REAR BUMPER LOWER GARNISH	Dishd	1	\$	-	\$	-
72	REAR BUMPER LOWER GARNISH CHROME	new	1	\$	-	\$	-
73	REAR BUMPER UPPER CORNER BRACKET	new	2	\$	-	\$	-
74	REAR BUMPER SIDE RETAINER	new	2	\$	-	\$	-
75	REAR BUMPER REINFORCEMENT	Dishd	1	\$	-	\$	-
76	REAR BUMPER LOWER CENTER BRACKET	could	2	\$	-	\$	-
77	REAR BUMPER LOWER SIDE BRACKET	new	2	\$	-	\$	-
78	REAR BUMPER BOTTOM GARNISH SUPPORT	new	3	\$	-	\$	-
79	REAR FENDER COWLING	new	2	\$	-	\$	-
80	REAR FENDER INNER TRIM	new	2	\$	-	\$	-
81	REAR FENDER DRAIN GARNISH	new	2	\$	-	\$	-
82	TAILLAMP	could	2	\$	-	\$	-
83	BOOTLID	Dishd	1	\$	-	\$	-
84	BOOTLID LOGO	new	1	\$	-	\$	-
85	BOOTLID TOP LOCK	new	1	\$	-	\$	-
86	BOOTLID LOWER LOCK	new	1	\$	-	\$	-
87	BOOTLID INNER TRIM	new	1	\$	-	\$	-
88	BOOTLID WEATHER STRIP	new	1	\$	-	\$	-
89	BOOTLID LAMP	RH could	2	\$	-	\$	-

Handwritten notes and calculations on the right margin:

- Vertical list of '+' signs corresponding to rows 56 through 89.
- Number '2' written next to row 61.
- Number '2' written at the bottom right.

VEHICLE NO : **SKJ1919K**
 MODEL : **MERCEDES A200**
 DATE OF ACCIDENT : 19.08.2024
 TIME OF ACCIDENT : 19:15 HOURS

90	REVERSE CAMERA <i>new</i>	1	\$	-	\$	-
91	REAR END PANEL <i>Broken</i>	1	\$	-	\$	-
92	REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$	-	\$	-
93	REAR EXHAUST BOX	1	\$	-	\$	-
94	REAR EXHAUST MOUNTING <i>2 HP</i>	2	\$	-	\$	-
95	REAR EXHAUST GASKET <i>new</i>	1	\$	-	\$	-
96	REAR EXHAUST INSULATOR	1	\$	-	\$	-

TOTAL PRICE \$ -
 LESS 10% \$ -
 SUB TOTAL PRICE \$ -

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Missing</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
3	FRONT BUMPER SIDE GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	FRONT BUMPER BOTTOM COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	FRONT NUMBER PLATE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	SUPPORT PANEL UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	FRONT FENDER COWLING (FRONT) CLIP (SET) <i>2 HP</i>	1	\$ 50.00	\$ 50.00
8	FRONT FENDER COWLING (BACK) CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
9	COOLANT <i>new</i>	1	\$ 180.00	\$ 180.00
10	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
11	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
12	REAR BUMPER BOTTOM CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
13	REAR BUMPER LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
14	BOOTLID SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
15	BOOTLID SPOILER (SPECAIL TYPE) <i>new</i>	1	\$ 850.00	\$ 850.00
15	BOOTLID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
16	BOOTLID CENTER MOULDING CLIP <i>new</i>	1	\$ 50.00	\$ 50.00
17	BOOTLID NUMBER PLATE LAMP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
18	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
19	REAR FENDER DRAIN GARNISH CLIP (SET) <i>2 HP</i>	1	\$ 80.00	\$ 80.00
20	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
21	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00

VEHICLE NO : **SKJ1919K**
 MODEL : **MERCEDES A200**
 DATE OF ACCIDENT : 19.08.2024
 TIME OF ACCIDENT : 19:15 HOURS

22	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$	150.00	\$	150.00 <i>60</i>
23	REAR END PANEL INNER GARNISH CLIP (SET) <i>New</i>	1	\$	50.00	\$	50.00 <i>20</i>

TOTAL \$ 2,510.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>1000</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>50</i>
4	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>X</i>
5	WIRING CHECK	\$ 650.00	<i>400</i>
6	REMOVE AND REFIX RADAR SENSOR AND REPROGRAMMING	\$ 850.00	<i>550</i>
7	REMOVE AND REFIX AIR COOLER	\$ 120.00	<i>60</i>
8	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
9	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>60</i>
10	REMOVE AND REFIX ECU AND REPROGRAMMING	\$ 750.00	<i>400</i>
11	REMOVE AND REFIX ALTERNATOR	\$ 180.00	<i>120</i>

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

VEHICLE NO : SKJ1919K
MODEL : MERCEDES A200
DATE OF ACCIDENT : 19.08.2024
TIME OF ACCIDENT : 19:15 HOURS

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 350.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	60
6	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
8	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	200

TOTAL \$ 11,700.00

TOTAL PARTS COST : \$ 2,510.00
TOTAL LABOUR COST : \$ 11,700.00
TOTAL REPAIR COST : \$ 14,210.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
2/s 21/08/24.
16 Days