

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24080422/UMA3Q2**Date:** 15/10/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000461_03
Claimant Vehicle No :	SMW7271M	Insured Vehicle No :	XE1460M
Date of Loss:	26/08/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW7271M		
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Engine No:	A684J805N13B16A
Reg. Date:	03/06/2015 (Man. Year: 2014)	Chassis No:	WBA3A16090NS38355
Colour:	Black/White	Odometer:	153449 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,295.85	4,239.09	11,056.76	72.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	1,430.00	3,010.00	67.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,735.85	5,669.09	14,066.76	71.28
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	19,735.85	4,500.00	15,235.85	77.20
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	27/08/2024		
Date Inspected:	27/08/2024	Inspected At:	SPEEDWERKZ PTE LTD (Autobay) (HQ) 1 KAKI BUKIT AVENUE 6 #01-73 Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW7271M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	1,266.80 FL	*1,266.80 FL
2	1		*BOOTLID LOGO	Necessary	75.10 FL	*75.10 FL
3	1		*BOOTLID LAMP L/R	N/S Not Necessary/O/SScratched	605.60 FL	*290.00 FL
4	1		*BOOTLID INNER TRIM	Not Necessary	123.70 FL	*- FL
5	2		*BOOTLID HINGE L/R	Not Necessary	196.80 FL	*- FL
6	1		*BOOTLID INNER LOCK	Twisted	514.20 FL	*285.00 FL
7	1		*BOOTLID LOCK STRIKER	Not Necessary	67.30 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Not Necessary	103.90 FL	*- FL
9	2		*BOOTLID LICENSE PLATE LAMP L/R	Not Necessary	78.80 FL	*- FL
10	1		*TAIL LAMP O/S	Cracked	844.60 FL	*602.00 FL
11	1		*REAR BUMPER	Dented	1,521.30 FL	*1,218.30 FL
12	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	131.20 FL	*- FL
13	1		*REAR BUMPER CENTRE BRACKET	Cracked	68.40 FL	*68.40 FL
14	1		*REAR BUMPER CENTRE GUIDE	Cracked	133.50 FL	*133.50 FL
15	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	100.10 FL	*- FL
16	4		*REAR BUMPER REVERSE SENSOR	Not Necessary	1,198.80 FL	*- FL
17	1		*SET REAR BUMPER REVERSE SENSOR BRACKET	Not Necessary	56.40 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Dented	611.20 FL	*481.00 FL
19	1		*END PANEL	Repair	951.60 FL	*- FL
20	1		*END PANEL GARNISH	Not Necessary	89.60 FL	*- FL
21	2		*REAR FENDER INNER TRIM L/R	Not Necessary	462.80 FL	*- FL
22	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	286.90 FL	*- FL
23	1		*SPARE TYRE PANEL COMPARTMENT BOARD	Not Necessary	211.30 FL	*- FL
24	1		*SPARE TYRE PANEL	Not Necessary	688.40 FL	*- FL
25	2		*REAR EXHAUST RUBBER HANGER	Not Necessary	112.60 FL	*- FL
26	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
27	1		*REAR BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*REAR BOOTLID CARBON FIBRE SPOILER (KIV)	Cracked	1,200.00 FS	*- FS
29	1		*END PANEL GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
30	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
31	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*REAR FENDER TRIM L/R CLIPS	Not Necessary	160.00 FS	*- FS
33	1		*REAR NUMBER PLATE WITH GARNISH	Not Necessary	70.00 FS	*- FS
34	1		*EXHAUST SYSTEM	Not Necessary	3,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,820.90	4,460.10
- List Item Discount on L Items 5.00/5.00% (\$\$)	525.05	221.01
Total Parts (\$\$)	15,295.85	4,239.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING	New	50.00	20.00
2	TO REPLACE REAR REVERSE SENSOR	New	80.00	30.00
3	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	100.00	0.00
4	TO REMOVE AND TRANSFER BOOTLID FITTINGS TO NEW	New	100.00	50.00
5	TO REMOVE AND REFIT REAR INTERIOR TRIMS	New	160.00	0.00
6	TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	New	150.00	0.00
7	TO RESET AND PROGRAMMING AND SETTING	New	250.00	0.00
8	TO PROVIDE LABOUR WORKMANSHIP	New	1,400.00	500.00
9	TO SPRAY PAINT ON AFFECTED PANELS (SATIN BLACK)	New	2,000.00	800.00
10	RUST PROOFING	New	150.00	30.00
Gross Labour Cost (\$\$)			4,440.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >