

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080425/RUA3Q2  
Date: 05/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0002324\_02  
Claimant Vehicle No : SME148C Insured Vehicle No : SLE9164H  
Date of Loss: 13/08/2024 Nature of Claim: TP Claim No: MFL2024D0009456

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME148C  
Make & Model: BMW I4, EDRIIVE35 GRAN COUPE (A) Engine No: HIDDEN  
Reg. Date: 17/08/2023 (Man. Year: 2023) Chassis No: WBY42AW030FR18782  
Colour: Grey Odometer: 6411 km  
Engine Capacity: 0 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R19 Rear Tyre Size: 255/40 R19  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,665.95	5,653.05	8,012.90	58.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,229.00	11,683.00	1,546.00	11.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,894.95	17,336.05	9,558.90	35.54
+ GST 9.00/9.00% (S\$)	2,420.55	1,560.24	860.31	35.54
Nett Amount (S\$)	29,315.50	18,896.29	10,419.21	35.54
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
Nett Liability (S\$)		19,896.29		

INSPECTION

Date of Assignment: 27/08/2024  
Date Inspected: 27/08/2024 Inspected At: Performance Motors Limited (HQ)  
303 Alexandra Road, Singapore  
Singapore 159941  
Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Nov 2024)	
Parts:	N/A	BMW I4 EDRIVE35 GRAN COUPE (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME148C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*25540R19 MICHELIN	Not Necessary	570.00 FS	*- FS
3	1		*DISC WHEEL I	Scratched	1,554.10 FS	*1,554.10 FS
4	5		*INSERT 1	Not Necessary	216.00 FS	*- FS
5	1		*HUB CAP WITH BLUE RING (BMW 1)	Not Necessary	37.05 FS	*- FS
6	1		*FRT RH SIDE PANEL	Repair	887.15 FS	*- FS
7	1		*FRTF RH DOOR	Bent	1,462.10 FS	*1,462.10 FS
8	1		*REAR RH DOOR	Bent	1,462.10 FS	*1,462.10 FS
9	1		*RH UPPER FRONT DOOR HINGE	Not Necessary	67.45 FS	*- FS
10	1		*RH LOWER FRT DOOR HINGE	Not Necessary	67.45 FS	*- FS
11	1		*RH LOWER REAR DOOR HINGE	Not Necessary	67.45 FS	*- FS
12	1		*RH UPPER REAR DOOR HINGE	Not Necessary	67.45 FS	*- FS
13	1		*FRONT DOOR B	Not Necessary	91.70 FS	*- FS
14	1		*REAR DOOR B	Not Necessary	91.70 FS	*- FS
15	1		*RH B PILLAR TRIM PANEL SEAL	Not Necessary	43.55 FS	*- FS
16	1		*SEAL C-PILLA	Not Necessary	36.30 FS	*- FS
17	1		*RH SILL TRIM PRIMED	Scratched	309.40 FS	*309.40 FS
18	1		*ADAPTER FOR	Not Necessary	24.10 FS	*- FS
19	1		*OUTSIDE DOOR	Not Necessary	297.25 FS	*- FS
20	1		*RH SYSTEM LATCH	Not Necessary	316.15 FS	*- FS
21	1		*STRIKER WITH	Not Necessary	27.00 FS	*- FS
22	1		*REAR RH WINDOW LIFTER W/O MOTOR	Not Necessary	448.00 FS	*- FS
23	1		*FRT RH DOOR OUTER SHAFT COVER (SCHW)	Not Necessary	98.70 FS	*- FS
24	1		*RH OUTER MIRROR SHAFT COVER (SCHWAR)	Not Necessary	53.90 FS	*- FS
25	1		*CHANNEL SEAL	Not Necessary	246.65 FS	*- FS
26	1		*FINISHER SI	Not Necessary	265.15 FS	*- FS
27	1		*SEAL OUTER	Not Necessary	22.85 FS	*- FS
28	1		*FRT RH WINDOW LIFTER W/O MOTOR	Not Necessary	448.00 FS	*- FS
29	1		*REAR RH DOOR OUTER CHANNEL COVER (S)	Not Necessary	98.70 FS	*- FS
30	1		*WINDOW WELL	Not Necessary	201.85 FS	*- FS
31	1		*FRT DOOR EDGE PROTECTION	Not Necessary	201.40 FS	*- FS
32	1		*EDGE PROTECT	Not Necessary	195.50 FS	*- FS
33	1		*(S/L) DOOR WEATHERSTRIP	Necessary	178.85 FS	*357.70 FS
34	1		*(S/L) DOOR WEATHERSTRIP	Necessary	178.85 FS	*- FS
35	1		*RH DOOR SILL TRIM PANEL UPPER SECTI	Not Necessary	663.00 FS	*- FS
36	1		*RH SILL TRIM LOWER SECTION	Cracked	353.65 FS	*353.65 FS
37	1		*MOUNT STRIP	Not Necessary	92.45 FS	*- FS
38	1		*MOUNT STRIP	Not Necessary	60.10 FS	*- FS
39	1		*SUPPORT STRI	Not Necessary	92.45 FS	*- FS
40	1		*FRT RH WINDOW LIFTER DRIVE	Not Necessary	362.35 FS	*- FS
41	1		*C CLIP NUT	Necessary	4.00 FS	*4.00 FS
42	1		*ALLOY RIM 9JX19 GUNMETAL GREY	Serviceable	1,554.10 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 13,665.95 5,653.05

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE RH SECTION FOR PROPER FUNCTION	New	177.00	177.00
2	REPLACE RIGHT BOTH SIDE DOOR ,RIGHT FRONT SIDE FENDER RIGHT LOWER SIDE SKIRTING INCLUDING REMOVE ATTACHMENT ETC AND CARRY REPAIRING ACCIDENT WORK ON RIGHT REAR SIDE FENDER WITH INCLUDE NECESSARY DAMAGE	New	5,100.00	3,825.00
3	PAINTING RIGHT REAR SIDE FENDER ,FRONT RIGHT SIDE FENDER ,BOTH RIGHT DOOR RIGHT SIDE ROOF FRAME ,RIGHT REAR DOOR ENTRANCE AND LOWER SIDE SILL PANEL	New	5,640.00	5,640.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (3 PANEL)	New	354.00	354.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (2 DOORS)	New	1,062.00	1,062.00
6	TO REMOVE AND INSTALL REAR BOOT COMPARTMENT INTERIOR CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	0.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE TO BMW SPECIFICATIONS	New	531.00	531.00
8	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X) RIGHT REAR	New	94.00	94.00
<b>Gross Labour Cost (\$\$)</b>			<b>13,229.00</b>	<b>11,683.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >