

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24080426/KVP3E2
Date: 05/09/2024

REFERENCE				
Insured/Claimant:	SHEE HUI JIN, VANESSA	Policy No:	MPC24B00054800	
Date of Loss:	16/08/2024	Nature of Claim:	OD	Claim No: DMPC2401073H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS8110R		
Make & Model:	TOYOTA RAV4, 2.0 PREMIUM SUV (2WD) (A)	Engine No:	M20AV028469
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	JTMY43FV80D502940
Colour:	Metallic Red	Odometer:	80882 km
Engine Capacity:	1987 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,478.00	5,478.00	0.00	0.00
Miscellaneous Items	305.00	165.00	140.00	45.90
Labour	1,800.00	650.00	1,150.00	63.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,583.00	6,293.00	1,290.00	17.01
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	7,583.00	5,043.00	2,540.00	33.50
+ GST 9.00/9.00% (S\$)	682.47	453.87	228.60	33.50
Nett Amount (S\$)	8,265.47	5,496.87	2,768.60	33.50

INSPECTION

Date of Assignment:	23/08/2024	Present Location:	Optima Werkz Pte Ltd (HQ) Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047
Date Inspected:	27/08/2024	Inspected At:	
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2024)
Parts:	M1-SUV	TOYOTA RAV4 2.0 PREMIUM SUV (2WD) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS8110R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Bumper, front (WCP)	Cracked	260.00 F	*260.00 F
2	1		Fender LH, front (WCP) (NPA)	Repair	-	*- F
3	1		Headlamp LH (WCP)	Mtg Cracked	1,800.00 F	*1,800.00 F
4	1		Radiator grille (WCP)	Mtg Cracked	240.00 F	*240.00 F
5	1		Radiator grille bracket (WCP)	Cracked	220.00 F	*220.00 F
6	1		Radiator grille emblem (WCP)	Cracked	400.00 F	*400.00 F
7	1		*Radiator Grille Lower No.2 (WCP)	Cracked	170.00 F	*170.00 F
8	1		*Front Bumper Guard (WCP)	Dented	260.00 F	*260.00 F
9	1		*Front Bumper Outer Moulding (WCP)	Dented	280.00 F	*280.00 F
10	1		*Front Radar Sensor (WCP)	Dented	850.00 F	*850.00 F
11	1		*Front LH Bumper Retainer (WCP)	Distorted	70.00 F	*70.00 F
12	1		*Front Bumper Energy Absorber (WCP)	Cracked	70.00 F	*70.00 F
13	1		*Front Bumper Reinforcement (WCP)	Buckled	300.00 F	*300.00 F
14	1		*Front Bumper Licence Plate Mounting Bracket (WCP)	Dented	60.00 F	*60.00 F
F=Franchise part.						
Sub Total (\$\$)					4,980.00	4,980.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					498.00	498.00
Total Parts (\$\$)					5,478.00	5,478.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front Bumper Clips (NECESSARY)	50.00	50.00
2	1	Front Bumper Lower Guard Clips (NOT NECESSARY)	50.00	0.00
3	1	Front Fender Liner Clips (NOT NECESSARY)	50.00	0.00
4	1	Front Fender Outer Garnish Clips (NECESSARY)	50.00	20.00
5	1	Front Licence Plate Number with Frame (DENTED)	55.00	45.00
6	1	Radiator Grille Clips (NECESSARY)	50.00	50.00
Sub Total (\$\$)			305.00	165.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To Straighten and Panel Beat of Accident Affected Areas	New	600.00	250.00
2	To Furnish Material, Supply and Spray Paint at Front Bumper, Front LH Fender Panel, Etc	New	700.00	200.00
3	To Readjust and Realign Headlamp Aim	New	100.00	0.00
4	To Recalibrate and Reset Radar Sensor	New	300.00	180.00
5	To Check Wiring and Electrical System	New	100.00	20.00
Gross Labour Cost (\$\$)			1,800.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >