

Optima Werkz Pte Ltd (Co.Reg.No:201212455W)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Singapore 568047
Tel: 6481 1522

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24B00054800	Date of Loss:	16/08/2024
Vehicle Reg. No.:	SDS8110R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SHEE HUI JIN, VANESSA		
Make/Model:	TOYOTA RAV4, 2.0 PREMIUM SUV (2WD) (A)	Vehicle Reg. Date:	30/04/2019
Vehicle Colour:	RED		
Engine No:	M20AV028469	Chassis No:	JTMV43FV80D502940
Odometer:	80357 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3 days		
Present Location:	OPTIMA WERKZ PTE LTD (HQ)		

*Not authorized
Running by pain
Ex \$1250h
\$8293.00*

COST OF CLAIMS

	Amount
Parts	5,478.00
Miscellaneous Items	305.00
Labour	1,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,583.00
+ GST 9.00% (S\$)	682.47
Nett Amount (S\$)	8,265.47

This claim is handled by: LOONG GHIE YEE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Aug 2024)

Parts: M1-SUV TOYOTA RAV4 2.0 PREMIUM SUV (2WD) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDS8110R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		Bumper, front	CM 0.00	0.00	*260.00 F	✓
2	1		Fender LH, front	0.00	0.00	-	
3	1		Headlamp LH	my CM 0.00	0.00	*1,800.00 F	2
4	1		Radiator grille	my CM 0.00	0.00	*240.00 F	2
5	1		Radiator grille bracket	CM 0.00	0.00	*220.00 F	2
6	1		Radiator grille emblem	0.00	0.00	CM *400.00 F	✓
7	1		*Radiator Grille Lower No.2	CM 0.00	0.00	*170.00 F	2
8	1		*Front Bumper Guard	0.00	0.00	nd *260.00 F	✓
9	1		*Front Bumper Outer Moulding	nd 0.00	0.00	*280.00 F	2
10	1		*Front Radar Sensor	nd 0.00	0.00	*850.00 F	2
11	1		*Front LH Bumper Retainer	0.00	0.00	nd *70.00 F	✓
12	1		*Front Bumper Energy Absorber	CM 0.00	0.00	*70.00 F	2
13	1		*Front Bumper Reinforcement	Bu 0.00	0.00	*300.00 F	2
14	1		*Front Bumper Licence Plate Mounting Bracket	0.00	0.00	nd *60.00 F	✓

F=Franchise part.

Sub Total (\$\$)	4,980.00
+ Margin on L,N Items 10.00% (\$\$)	498.00
Total Parts (\$\$)	5,478.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Front Bumper Clips	50.00
2	1	Front Bumper Lower Guard Clips	50.00
3	1	Front Fender Liner Clips	50.00
4	1	Front Fender Outer Garnish Clips	50.00
5	1	Front Licence Plate Number with Frame	55.00
6	1	Radiator Grille Clips	50.00
Sub Total (\$\$)			305.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To Straighten and Panel Beat of Accident Affected Areas	New	600.00
2	To Furnish Material, Supply and Spray Paint at Front Bumper, Front LH Fender Panel, Etc	New	700.00
3	To Readjust and Realign Headlamp Aim	New	100.00
4	To Recalibrate and Reset Radar Sensor	New	300.00
5	To Check Wiring and Electrical System	New	100.00
Gross Labour Cost (\$\$)			1,800.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: