

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24060126/APA3Q2**Date:** 14/01/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240085784
Claimant Vehicle No : SLW8552H **Insured Vehicle No :** SLZ5195J
 Date of Loss: 15/06/2024 Nature of Claim: TP Claim No: 6111286235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW8552H**
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5966402
 Reg. Date: 06/03/2018 (Man. Year: 2017) Chassis No: RU31266383
 Colour: Black Odometer: 176890 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,747.72	5,053.60	6,694.12	56.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	2,080.00	2,330.00	52.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,157.72	7,133.60	9,024.12	55.85
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	16,157.72	5,700.00	10,457.72	64.72
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,527.25		

INSPECTION

Date of Assignment: 19/06/2024
 Date Inspected: 19/06/2024 Inspected At: Fong Motors (HQ)
 1 Kaki Bukit Ave 6 #01-45, Autobay@ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	880.00 FL	*880.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	47.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Cracked	282.20 FL	*282.20 FL
5	2		*REAR SIDE BUMPER	Repair	390.00 FL	*- FL
6	1		*REAR END PANEL	Dented	585.00 FL	*585.00 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	98.40 FL	*98.40 FL
8	2		*TAILLAMP	Not Necessary	949.20 FL	*- FL
9	2		*TAILLAMP PANEL	Not Necessary	271.00 FL	*- FL
10	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
11	1		*TAILGATE LOCK	Damaged	182.50 FL	*182.50 FL
12	1		*TAILGATE LOCK STRIKER	Not Necessary	24.70 FL	*- FL
13	1		*TAILGATE WEATHERSTRIPE	Cut	189.10 FL	*189.10 FL
14	2		*TAILGATE LAMP	Not Necessary	826.40 FL	*- FL
15	2		*TAILGATE LAMP RUBBER GASKET	Not Necessary	77.00 FL	*- FL
16	2		*TAILGATE DAMPER	Not Necessary	365.40 FL	*- FL
17	2		*TAILGATE HINGE	Not Necessary	116.00 FL	*- FL
18	1		*TAILGATE OUTER GARNISH	Not Necessary	325.00 FL	*- FL
19	1		*TAILGATE INNER TRIM BOARD	Cut	285.60 FL	*285.60 FL
20	1		*TAILGATE BUZZER SENSOR	Cracked	85.20 FL	*85.20 FL
21	1		*TAILGATE ANTENNA SENSOR	Not Necessary	60.10 FL	*- FL
22	1		*TAILGATE OPENER SWITCH SENSOR	Not Necessary	125.50 FL	*- FL
23	1		*TAILGATE INNER HANDLE POCKET	Not fitted	27.50 FL	*- FL
24	1		*TAILGATE GLASS MOULDING	Necessary	120.00 FL	*120.00 FL
25	1		*HONDA LOGO	Not Necessary	30.40 FL	*- FL
26	1		*VEZEL EMBLEM	Necessary	45.90 FL	*45.90 FL
27	1		*HYUNDAI EMBLEM	Necessary	58.50 FL	*58.50 FL
28	1		*SPARE TYRE PANEL	Repair	1,130.00 FL	*- FL
29	1		*SPARE TYRE PANEL TOP COVER	Deformed	306.60 FL	*306.60 FL
30	1		*SPARE TYRE PANEL UTILITY TRAY	Cracked	285.40 FL	*285.40 FL
31	1		*SPARE TYRE PANEL UNDERCOVER	Deformed	225.10 FL	*225.10 FL
32	1		*REAR EXHAUST PIPE	Not Necessary	598.60 FL	*- FL
33	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	38.90 FL	*- FL
34	1		*REAR EXHAUST PIPE GASKET	Not Necessary	35.20 FL	*- FL
35	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	124.10 FL	*- FL
36	2		*REAR FENDER ARC GARNISH	Not Necessary	392.00 FL	*- FL
37	2		*REAR FENDER INNER SHIELD	Not Necessary	295.00 FL	*- FL
38	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	610.40 FL	*- FL
39	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
40	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
41	1		*REAR BUMPER LOWER SPOILER	Deformed	1,000.00 FS	*900.00 FS
42	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
43	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
44	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	25.00 FS	*- FS
45	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
46	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
47	1		*SET SPARE TYRE PANEL UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
48	1		*SPARE TYRE PANEL INSULATION PAD	Not Necessary	250.00 FS	*- FS
49	2		*SET REAR FENDER ARC GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
50	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
51	2		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
52	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,080.90** **5,999.50**
- List Item Discount on L Items 20.00/20.00% (\$\$) **2,333.18** **945.90**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	11,747.72
						5,053.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,600.00	800.00
2	SPARAY PAINTING TO AFFECTED AREA	New	1,400.00	800.00
3	WIRING CHECK	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE VIDEO RECORDER	New	100.00	50.00
7	TO REMOVE UPHOLSTERY AND REAR SEAT	New	380.00	60.00
8	TO SPRAY TUFF COAT	New	150.00	60.00
9	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
10	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
11	TO REPLACE TAILGATE GLASS	New	180.00	120.00
Gross Labour Cost (\$\$)			4,410.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >