

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24080433/UVP3E2
Date: 11/09/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001433008
Claimant Vehicle No :	SLM8500K	Insured Vehicle No :	SLR1705G
Date of Loss:	23/08/2024	Nature of Claim:	TP
		Claim No:	371329

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM8500K	Engine No:	K24W71011800
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Chassis No:	JHMRC1890FC203888
Reg. Date:	09/10/2015 (Man. Year: 2015)	Odometer:	395881 km
Colour:	White		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55Z R17	Rear Tyre Size:	215/55Z R17
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,729.68	4,052.80	6,676.88	62.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,380.00	2,100.00	60.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,209.68	5,432.80	8,776.88	61.77
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	14,209.68	4,300.00	9,909.68	69.74
+ GST 9.00/9.00% (S\$)	1,278.87	387.00	891.87	69.74
Nett Amount (S\$)	15,488.55	4,687.00	10,801.55	69.74

INSPECTION

Date of Assignment:	27/08/2024	
Date Inspected:	26/08/2024	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2024)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM8500K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,422.10 FL	*- FL
2	1		*FRONT BUMPER	Distorted	1,220.10 FL	*764.30 FL
3	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	221.10 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	70.00 FL	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
6	1		*FRONT BUMPER BEAM	Dented	322.10 FL	*288.50 FL
7	1		*FRONT GRILLE	Not Necessary	645.10 FL	*- FL
8	1		*FRONT FOG LAMP N/S	Cracked	390.00 FL	*366.50 FL
9	1		*FRONT FOG LAMP GARNISH N/S	Grazed	185.00 FL	*185.00 FL
10	1		*FRONT BUMPER LOWER GARNISH N/S	Twisted	338.20 FL	*290.00 FL
11	1		*FRONT BUMPER LOWER UNDER COVER	Not Necessary	455.20 FL	*- FL
12	2		*FRONT BUMPER PDC SENSORS	Not fitted	420.00 FL	*- FL
13	1		*HEADLAMP N/S	Cracked	3,200.00 FL	*2,566.30 FL
14	1		*HEADLAMP LOWER BRACKET N/S	Cracked	150.00 FL	*86.50 FL
15	1		*FRONT SUPPORT PANEL	Repair	620.80 FL	*- FL
16	1		*FRONT FENDER N/S	Repair	1,640.00 FL	*- FL
17	1		*FRONT FENDER INNER SHIELD N/S	Torn	188.90 FL	*175.40 FL
18	1		*AIR RESONATOR BOX ASSY	Cracked	298.50 FL	*298.50 FL
19	1		*FRONT SPORT RIM N/S	Repair	880.00 FL	*- FL
20	1		*FRONT KNUCKLE ARM N/S	Not Necessary	450.00 FL	*- FL
21	1		*FRONT KNUCKLE BEARING N/S	Not Necessary	250.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,412.10	5,066.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,682.42	1,013.20
Total Parts (\$\$)	10,729.68	4,052.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	100.00	20.00
2	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	0.00
3	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	500.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	100.00	0.00
6	TO REFILL AIR CON GAS	New	100.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	500.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,480.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >