

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #09-16 Singapore 079120 T: (65) 6419 3000 www.aig.sg

Claim No: 8317133585SG Date of Survey: 18/01/2024

Repairer: TAN CHONG MOTOR SALES PTE LTD

REFERENCE

Insured: Policy No:

Date of Loss: 14/01/2024 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SMT578R

Make & Model: NISSAN SERENA, 1.2 L Reg. Date: 26/03/2020

HIGHWAY STAR PREMIUM

E-POWER (A)

Engine No: HR12130449K Chassis No: JN1EBAC27Z0000402

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable): Yes Engine Modification: No

Handbrake (Serviceable): Yes Steering (Serviceable): Yes Pre-accident Condition: Good

TOTAL OFFER

Offer Authorized By: LAU, JASON on 28 Feb 2024 12:20
Offer Initiated By: LAU, JASON on 19 Feb 2024 12:00

Subrogation: Yes

Rep. Gross Total: \$\$17,407.86 [Diff: \$\$5,926.00, 34.04%]

Approved Gross Total: S\$11,481.86

- Excess: S\$0.00, [Waived: S\$800.00] [Remarks: Not Applicable

S\$11.481.86

+ GST (9.00%): S\$1,033.37

Approved Nett Amount: \$\$12,515.23

(No Betterment/Depreciation)

0.00	
0.00 0.00	34.04
	H81.86 5.926.00

Nett Amount (S\$)	18.974.57	12.515.23	6.459.34	34.04
+ GST 9.00/9.00% (S\$)	1,566.71	1,033.37	533.34	34.04

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"
Estimated repair period : 12.0 days
Authorised Repair : Yes

Inspection conducted by : Lau, Jason (AIG Claims Dept)

Signature :

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PULL HANDLER	Distorted	21.80 FN	*21.80 FN
2	1		*CARPET FLOOR	Distorted	607.40 FN	*607.40 FN
3	1		*BOX LUGGAGE FINISHER	Deformed	311.40 FN	*311.40 FN
4	1		*GASKET-EXHAUST END		4.90 FS	Reuse
5	1		*MOUNTING EXHAUST END		12.50 FS	Reuse
6	1		*MOUNTING EXHAUST END		27.60 FS	Reuse
7	1		*MUFFLER ASSY END *HARNESS-CORNER REAR BUMPER SENSOR	Damagad	892.80 FS	Repair
8	1		*COVER LH REAR BUMPER CORNER SENSOR	Damaged Broken	216.60 FN 107.10 FS	*216.60 FN *107.10 FS
9 10	1		*SENSOR ASSY REAR BUMPER	ыокеп	774.60 FS	Reuse
11	2		*COVER SENSOR REAR BUMPER LH/RH) CENTER		161.40 FS	Reuse
12	2		*GROMET C/LAMP		101.40 FS	Reuse
13	2		*GROMET A/CLMP		10.80 FN	Reuse
14	1		*LAMP COMB RR,RH		623.90 FN	Reuse
15	1		*LAMP COMB RR,LH		623.90 FN	Reuse
16	1		*FLOOR REAR S/TYRE HOUSING		514.90 FN	Repair
17	1		*MEMBER ASSY-RR END PANEL (TOP)	Bent	270.00 FS	*270.00 FS
18	1		*RR PANEL-LOWER END PANEL	Bent	239.60 FN	*239.60 FN
19	1		*COVER LH REAR WHEELHOUSE LOWER (INNER COVER)	Deformed	28.00 FN	*28.00 FN
20	1		*FINISHER ASSY LH REAR WHEELHOUSE (LOWER)	Deformed	710.10 FN	*710.10 FN
21	1		*BOARD ASSY S/TYRE	Deformed	587.70 FN	*587.70 FN
22	1		*END PANEL GARNISH	Distorted	58.30 FN	*58.30 FN
23	2		*GROMET BUMPER	Necessary	3.60 FN	*3.60 FN
24	8		*GROMMET BUMPER	Necessary	24.00 FN	*24.00 FN
25	2		*CLIP BUMPER	Necessary	3.00 FN	*3.00 FN
26	1		*BRACKET-BUMPER LH REAR	Necessary	36.20 FN	*36.20 FN
27	1		*BRKT ASSY-RR BUMPER LH	Bent	29.00 FN	*29.00 FN
28	1		*BRACKET-BUMPER LH REAR	Bent	36.20 FN	*36.20 FN
29	1		*SHIELD LH REAR SIDE	Deformed	428.90 FN	*428.90 FN
30	1		*MOUL-RR BUMPER LH "L"""	Bent	400.80 FN	*400.80 FN
31	1		*FACE-RR BUMPER	Deformed	1,574.40 FN	
32	1		*A FIN BACK DOOR (SERENE)	Broken	887.30 FN	*887.30 FN
33	1		*WEATHER STRIP TAILGATE (LOWER)	Distorted		*118.50 FN
34	1		*DOOR BACK	Bent		*1,938.80 FN
35	1		*A LOCK LIFT TAILGATE (LOWER)	Jammed	222.30 FN	*222.30 FN
36	1		*STRIKER-TAIL GATE (LOWER)		38.70 FN	Reuse
37	1		*GARNISH ASSY TAILGATE (TOP)		214.80 FN	Reuse
38	1		*FINISHER TAILGATE LOWER CENTER) INNDER	D: 1 1 1	208.70 FN	Reuse
39 40	1		*FINISHER (TAILGATE LOWER) INNER *EMBLEM-REAR	Distorted	331.60 FN	*331.60 FN
40	1			Necessary	105.00 FN	*105.00 FN
41 42	1		*EMBLEM-REAR *SUNDRIES	Necessary Necessary	56.70 FN	*56.70 FN
42 43	1			Bent	30.00 FS	*20.00 FS
			*REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP	Delit	60.00 FS	*60.00 FS
F=Fra	nchise	part. S=Sp	pcNett. N=NettItemDisc.	ا ub Total (S\$)	12 564 60	9,434.30

Sub Total (S\$) 13,564.60 9,434.30 - Nett Item Discount on N Items 20.00/20.00% (S\$) 2,244.74 1,795.44

> **Total Parts (S\$)** 11,319.86 7,638.86

AIG Asia Pacific Insurance Pte. Ltd./SMT578R/28/02/2024 12:20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lak	oour Items			
1	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	New	240.00	240.00
2	PULL/STRAIGHTEN CHASSIS	New	350.00	-
3	REMOVE/INSTALL EXHAUST MUFFLER ASSY	New	120.00	-
4	REMOVE/INSTALL SEAT & CUSHION CARPET (PARTIAL) 3 ROW	New	120.00	120.00
5	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	New	120.00	120.00
6	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 04	New	480.00	240.00
7	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	New	300.00	200.00
8	REPAIR LH/RH REAR FENDER AND RENEW TAILGATE,REAR BUMPER,S/TYRE HOUSING	New	1,960.00	1,225.00
9	S/PAINT REAR BUMPER,LH/RH REAR FENDER,LH REAR FENDER SHIELD,TAILGATE,S/TYRE HOUSING,CHASSI FRAME END PANEL	New	1,800.00	1,100.00
10	TRANSFER TAILGATE MECHNICAL PARTS TO NEW DOOR	New	80.00	80.00
11	R/I LH/RH REAR WHEELHOUSE FINISHER TO ASSIST REPAIR \$120/SIDE X 02	. New	240.00	240.00
12	CHECK LIGHTING	New	48.00	48.00
13	R/I AND RENEW REAR BUMPER SENSOR	New	110.00	110.00
14	RENEW WIRE HARDNESS REAR BUMPER	New	120.00	120.00
	Gross Labou	r Cost (S\$)	6,088.00	3,843.00
	AIG Asia Pacific Insurance Pte. Ltd./SMT578R/28/02/2	2024 12:20		

< END OF REPORT >