



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060127/Unp3
16 RAFFLES QUAY	Date:	05/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4140L	Veh. Inspected	FBR 53D
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005281MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	18/06/2024

### 2. Vehicle Details

Make & Model	YAMAHA CZD 300 A XMAX 300	C.C	292
Engine No.	H345E0129331	Year of Reg.	22/02/2024
Chassis No.	MH3SH228000002003	Colour	BLACK
Odometer	4322 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	120/70-15	BRIDGESTONE	8
L/H Front Tyre			
R/H Rear Tyre	140-70-14	BRIDGESTONE	8
L/H Rear Tyre			

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	12/06/2024	Inspection Date	19/06/2024
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		

### 5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.  
B)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days