



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 1848X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSHIELD	CUT	250.00	250.00
1	HEADLAMP	CRACKED	685.00	685.00
1	HEADLAMP BRACKET	BENT	295.00	295.00
1	HEADLAMP COWLING	CUT	198.00	198.00
1	HEADLAMP COWLING TOP GARNISH	CRACKED	115.00	115.00
1	HEADLAMP COWLING CENTRE GARNISH	CUT	210.00	210.00
2	HEADLAMP SIDE COWLING (WHITE) @\$225.00	O/S CRACKED	450.00	225.00
1	FRONT FENDER	NOT NECESSARY	145.00	-
2	FRONT FENDER SIDE GARNISH @\$90.00	NOT NECESSARY	180.00	-
1	FRONT FORK ASSY	BENT	910.00	710.00
1	FRONT FORK UNDER BRACKET	BENT	280.00	280.00
1	FRONT BRAKE DISC	NOT NECESSARY	180.00	-
2	FRONT SIGNAL LAMP @\$105.00	O/S CRACKED	210.00	105.00
2	FRONT SIGNAL LAMP GARNISH (BLACK) @\$258.00	O/S CRACKED	516.00	258.00
2	FRONT WING MIRROR @\$58.00	N/S CUT	116.00	58.00
1	BALANCER	CUT	50.00	50.00
1	HANDLE BAR	NOT NECESSARY	195.00	-
1	HANDLE LEVER	CUT	48.00	48.00
1	FOOTREST BOARD	CUT	184.00	184.00
1	FOOTREST BOARD COVER	NOT NECESSARY	35.00	-
1	FOOTREST BOARD TOP GARNISH	NOT NECESSARY	215.00	-
1	FOOTREST BOARD LOWER GARNISH (WHITE)	CUT	78.00	78.00
1	REAR FOOTREST	NOT NECESSARY	45.00	-
1	REAR SIDE COWLING (WHITE)	TO REPAIR SEE LABOUR	178.00	-
1	REAR SIDE COWLING HANDLE	NOT NECESSARY	140.00	-
1	TAILLAMP	NOT NECESSARY	277.00	-
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	687.00	-
1	REAR EXHAUST PIPE PROTECTOR	CUT	92.00	92.00

Report Ref No. CS/INC24080437/Avh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-696.40	-384.10
			6,267.60	3,456.90
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE STICKER (SN)	NECESSARY	20.00	20.00
1	FRONT CAMERA (SN)	NOT NECESSARY	300.00	-
1	FRONT FORK OIL (SN)	NECESSARY	50.00	50.00
1	FRONT FORK OIL SEAL (SN)	NECESSARY	55.00	55.00
1	STEERING CONE & BEARING (SN)	NECESSARY	120.00	90.00
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	500.00	-
			1,045.00	215.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR SIDE COWLING (WHITE) AND REAR EXHAUST PIPE.		400.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		400.00	200.00
	WIRING CHECK.		50.00	30.00
	TO REMOVE FRONT CAMERA.		100.00	50.00
	TO REPAIR & STRAIGHTEN BODY CHASSIS.	NOT NECESSARY	200.00	-
	TO REMOVE REAR EXHAUST PIPE.		100.00	60.00
	TOWING FEES.		40.00	40.00
			1,290.00	580.00
GRAND TOTAL			8,602.60	4,251.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,400.00

Report Ref No. CS/INC24080437/Avh3m4(N)

TOTAL FOR SPARE PARTS: \$ 7,312.60 \$ 3,671.90

TOTAL FOR LABOUR : \$ 1,290.00 \$ 580.00

TOTAL REPAIR COST: \$ 8,602.60 \$ 4,251.90

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.