



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD		Ref:		CS/LPC24080440/Uqh3e2
300 BEACH ROAD		Date:		04/09/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555		Code:		LPC2
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XE 7892K	Veh. Inspected	XE 6375T	
Policy No.	-	Coverage	0	
Claim No.	23/24/24/VC00/029760	Excess	\$0.00	
Assign From	ERIC	Assign Date	27/08/2024	
<b>2. Vehicle Details</b>				
Make & Model	MITSUBISHI FUSO FV51	C.C	11967	
Engine No.	OM457LA457972C0326097	Year of Reg.	25/05/2016	
Chassis No.	FV51SSA20025	Colour	WHITE/BLUE	
Odometer	145364 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: NIL			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance (mm)	
R/H Front Tyre	295/80R22.5	HINO	6	
L/H Front Tyre	295/80R22.5	HINO	6	
R/H Rear Tyre	295/80R22.5 (D/D)	HINO	6/6/6/6	
L/H Rear Tyre	295/80R22.5 (D/D)	HINO	6/6/6/6	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND FRONT WINDSCREEN CRACKED.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/08/2024	Inspection Date	29/08/2024	
Survey held at	HUP LIAN HUAT ENGINEERING WORKS - 38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE, SINGAPORE 539278			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				