

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

*not Authorized
 in
 motor
 29/8/24
 d/s # 8000/
 4 hrs.
 unph...ing.*

M/S : Lonpac Insurance Bhd
 300 Beach Road
 #17-04/07 The Concourse ,
 Singapore 199555

TEL: 6250 7388 (ext: 254) FAX: 6296 2706
 ATTN: Motor Claim Department \ 6546 5886

Estimate No: ES1602146
Date: 25 Aug 2024
Policy No: DMCG24008447
Veh Reg No: XE6375T
Make/Model: MITSUBISHI FUSO
 FV51SS3VDEA
Chassis No: FV51SSA20025
Engine No: OM457LA457972C032609
Reg. Date: 25/05/2016

Your Ref No: FELICITY ENG PL
Claim Type: Third Party
Accident Date: 25/08/2024
TP Veh Reg No: XE7892K

Estimate Repair Cost to Vehicle No :XE6375T

Description	U/Price	Quantity	List Price	Amount
				SS
List Price				
1 Front Windscreen Glass	1,680.05	1 PC <i>one</i>	1,680.05	—
2 Front Windscreen Glass Rubber Seal	670.89	1 PC <i>one</i>	670.89	—
3 Wiper Blade	66.74	1 PC <i>17</i>	66.74	X
4 Front Corner Panel -LH	468.21	1 PC <i>17</i>	468.21	X
5 Front Corner Panel Bracket -LH	107.00	1 PC <i>17</i>	107.00	X
6 Front Corner Panel Lower Bracket -LH	32.78	1 PC <i>17</i>	32.78	X
7 Front Corner Panel Signal Lamp -LH	195.03	1 PC <i>17</i>	195.03	X
8 Front Corner Panel Bottom Rubber Seal -LH	84.23	1 PC <i>17</i>	84.23	X
9 Front Bumper	2,259.31	1 PC <i>Dis</i>	2,259.31	—
10 Front Bumper Cover -LH	305.89	1 PC <i>Dis</i>	305.89	—
11 Front Bumper Side -LH	140.29	1 PC <i>Dis</i>	140.29	—
12 Front Bumper Step Garnish	217.26	1 PC <i>Dis</i>	217.26	—
13 Front Bumper Lower Stay	169.07	1 PC <i>3rd</i>	169.07	—
14 Front Bumper Bracket	37.30	1 PC <i>Dis</i>	37.30	—
15 Front Bumper Side Air Dust -LH	96.70	1 PC <i>Dis</i>	96.70	—
16 Front Top Bumper	273.12	1 PC <i>17</i>	273.12	X
17 Front Top Bumper Reinforcement	884.79	1 PC <i>Dis</i>	884.79	—
18 Front Top Bumper -LH	193.04	1 PC <i>Dis</i>	193.04	—
19 Front Top Bumper Reinforcement -LH	226.06	1 PC <i>Dis</i>	226.06	—
20 Front Headlamp Assy -LH	1,286.45	1 PC <i>one</i>	1,286.45	—
21 Front Headlamp Rim -LH	181.18	1 PC <i>one</i>	181.18	—
22 Front Headlamp Aluminium Bracket -LH	947.63	1 PC <i>one</i>	947.63	—
23 Front Fog Lamp Assy -LH	293.25	1 PC <i>17</i>	293.25	X
24 Front Fog Lamp Rim -LH	186.05	1 PC <i>one</i>	186.05	—
25 Front Door Assy -LH	5,542.30	1 PC <i>17</i>	5,542.30	X
26 Side Mirror Stay Upper -LH	316.31	1 PC <i>17</i>	316.31	X
27 Side Mirror Stay Upper Bracket -LH	128.30	1 PC <i>17</i>	128.30	X
28 Side Mirror Stay Bar Lower -LH	108.94	1 PC <i>17</i>	108.94	X
29 Side Mirror Stay Bar Lower Bracket -LH	130.16	1 PC <i>17</i>	130.16	X
30 Side Mirror Lower Stay Bar -LH	140.16	1 PC <i>17</i>	140.16	X
31 Side Mirror Stay -LH	817.09	1 PC <i>3rd</i>	817.09	—
32 Side Mirror Stay Bracket -LH	354.12	1 PC <i>3rd</i>	354.12	—
33 Side Mirror (Big) -LH	177.68	1 PC <i>17</i>	177.68	X
34 Side Mirror (Square) -LH	159.83	1 PC <i>one</i>	159.83	—
35 Side Mirror (Round) -LH	107.24	1 PC <i>17</i>	107.24	X

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9 , Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : Lonpac Insurance Bhd
 300 Beach Road
 #17-04/07 The Concourse ,
 Singapore 199555

TEL: 6250 7388 (ext: 254) FAX: 6296 2706
 ATTN: Motor Claim Department \ 6546 5886

Your Ref No: FELICITY ENG PL
 Claim Type: Third Party
 Accident Date: 25/08/2024
 TP Veh Reg No: XE7892K

Estimate No: ES1602146
Date: 25 Aug 2024
Policy No: DMC24008447
Veh Reg No: XE6375T
Make/Model: MITSUBISHI FUSO
 FV51SS3VDEA
Chassis No: FV51SSA20025
Engine No: OM457LA457972C032609
Reg. Date: 25/05/2016

Estimate Repair Cost to Vehicle No :XE6375T

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			18,984.45	
		Less 25%	4,746.11	14,238.39
Labour				
36 To remove & refit front windscreen glass ,rubber seal , iu bracket .	200.00	1 -	200.00 ✓	
37 To remove & refit front LH door & realightment ,etc .	280.00	1 -	280.00 X	
38 To remove & refit headlamp cable ,system & check wiring & refocus all light .	230.00	1 -	230.00 30	
39 Labour charge to cut & weld & dismantle & remove & refit all above parts .	2,500.00	1 -	2,500.00 1000	
40 To spray & painting all accident affected arera .	2,300.00	1 -	2,300.00 800	
			5,510.00	5,510.00
			Total	SS 19,748.39
			Add GST @ 9%	1,777.36
			Total Amount Payable	SS 21,525.75

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND FIVE HUNDRED TWENTY FIVE AND CENTS SEVENTY FIVE ONLY

For HUP LIAN HUAT ENGINEERING WORKS

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-10 M3
 252
 8109.75
 1930
 10039.75
 22
 8000