

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24080443/UQP3E2
Date: 10/09/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SKA8416X	Insured Vehicle No :	SMW865X
Date of Loss:	25/08/2024	Nature of Claim:	TP
		Claim No:	DMPC2401120H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA8416X	Engine No:	1ZR083837
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104115230
Reg. Date:	07/04/2011 (Man. Year: 2011)	Odometer:	185813 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,218.61	6,496.68	8,721.93	57.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	3,530.00	1,160.00	24.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,908.61	10,026.68	9,881.93	49.64
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	19,908.61	8,000.00	11,908.61	59.82

INSPECTION

Date of Assignment:	26/08/2024	JC Motor Consultancy (Kaki Bukit)
Date Inspected:	27/08/2024	Inspected At: 1 Kaki Bukit Ave 6, #01-96 Autobay @Kaki Bukit
Estimated Period of Repair:	8.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2024)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA8416X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Torn	769.60 FL	*769.60 FL
2	1		*FRONT BUMPER LOGO	Necessary	89.95 FL	*89.95 FL
3	1		*FRONT BUMPER LOGO GRILLE	Not Necessary	181.20 FL	*- FL
4	1		*FRONT BUMPER TOP SEAL	Necessary	89.60 FL	*89.60 FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	140.63 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	515.60 FL	*515.60 FL
7	1		*FRONT BUMPER FOG LAMP - LH	Cracked	361.55 FL	*361.55 FL
8	1		*FRONT BUMPER FOG LAMP COVER	Torn	110.25 FL	*110.25 FL
9	1		*FRONT FENDER - LH	Repair	781.66 FL	*- FL
10	1		*FRONT GRILLE ASSY	Not Necessary	631.52 FL	*- FL
11	1		*FRONT HEADLAMPS - L/R (O/S Not Necessary)	N/S Holder Cracked	2,521.00 FL	*1,260.50 FL
12	1		*FRONT SUPPORT PANEL	Repair	991.60 FL	*- FL
13	1		*FRONT BRACE PANEL	Not Necessary	110.45 FL	*- FL
14	1		*AIR CON CONDENSER	Not Necessary	1,011.35 FL	*- FL
15	1		*AIR CLEANER INTAKE DUCT	Not Necessary	241.50 FL	*- FL
16	1		*AIR CLEANER RESONATOR	Not Necessary	310.60 FL	*- FL
17	1		*HORN	Not Necessary	86.60 FL	*- FL
18	1		*REAR BOOT LID	Repair	1,053.60 FL	*- FL
19	1		*REAR BOOT LOGO	Not Necessary	89.95 FL	*- FL
20	1		*REAR BOOT CHROME MOULDING	Not Necessary	299.61 FL	*- FL
21	1		*REAR BOOT LAMPS - L/R	O/S Broken / N/S Not Necessary	463.20 FL	*231.60 FL
22	1		*REAR BOOT INNER LOCK	Not Necessary	281.63 FL	*- FL
23	1		*REAR BOOT W/STRIP	Not Necessary	261.92 FL	*- FL
24	1		*REAR BUMPER	Torn	799.60 FL	*799.60 FL
25	1		*REAR BUMPER REFLECTOR	Missing	89.95 FL	*89.95 FL
26	1		*REAR BUMPER BRACKET - RH	Bent	110.25 FL	*110.25 FL
27	1		*REAR BUMPER FOAM	Not Necessary	160.93 FL	*- FL
28	1		*REAR BUMPER SIDE RETAINERS - L/R	O/S Cracked	230.40 FL	*115.20 FL
29	1		*REAR BUMPER SIDE BRACKET - RH	Cracked	89.55 FL	*89.55 FL
30	1		*REAR END PANEL	Badly Dented	781.10 FL	*781.10 FL
31	1		*REAR END PANEL GARNISH	Not Necessary	211.43 FL	*- FL
32	1		*REAR EXHAUST SILENCER	Dented / Bent	822.62 FL	*822.62 FL
33	1		*REAR EXHAUST INSULATOR	Not Necessary	130.20 FL	*- FL
34	2		*REAR EXHAUST MOUNTINGS	Torn	57.20 FL	*57.20 FL
35	1		*REAR EXHAUST PIPE - CTR	Not Necessary	1,055.90 FL	*- FL
36	1		*REAR FENDER - RH	Badly Dented	1,257.60 FL	*1,257.60 FL
37	1		*REAR FENDER INNER SHIELD - RH	Torn	114.71 FL	*114.71 FL
38	1		*REAR FENDER AIR VENT	Twisted	121.63 FL	*121.63 FL
39	1		*REAR FENDER INNER TRIM	Not Necessary	481.66 FL	*- FL
40	1		*REAR TAILLAMP - RH	Broken	561.21 FL	*561.21 FL
41	1		*REAR TAILLAMP PANEL - RH	Repair	299.61 FL	*- FL
Report was unsubmitted during this print-out.						

9/10/24, 2:39 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR TAILLAMP LOWER BRACKET - RH	Not Necessary	86.50 FL	*- FL
43	1		*REAR WINDSCREEN MOULDING	Necessary	126.30 FL	*126.30 FL
44	1		*SIDE SILL PANEL GARNISH - RH	Not Necessary	581.90 FL	*- FL
45	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
46	1		*SET FRONT NUMBER PLATE WITH HOLDER	Bent	65.00 FS	*40.00 FS
47	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
48	1		*REAR REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
49	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					20,109.82	8,615.57
- List Item Discount on L Items 25.00/25.00% (S\$)					4,891.21	2,118.89
Total Parts (S\$)					15,218.61	6,496.68
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT / REAR ELECTRICAL WIRING	New	80.00	20.00
2	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
3	TO REMOVE, REFIX REAR WINDSCREEN	New	180.00	120.00
4	TO REMOVE, REFIX REAR REVERSE SENSOR	New	60.00	30.00
5	TO REMOVE, REFIX REAR EXHAUST	New	120.00	60.00
6	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS	New	180.00	0.00
7	TO RESPRAY UNDERCOATING	New	150.00	60.00
8	TO RESPRAY PAINTING AND ETC	New	1,800.00	1,600.00
9	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	2,000.00	1,580.00
Gross Labour Cost (S\$)			4,690.00	3,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >