

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24080449/ANP3E2
Date: 30/12/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLG6771P	Insured Vehicle No :	SMM2172B
Date of Loss:	24/08/2024	Nature of Claim:	TP
		Claim No:	DMPC2401113H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6771P	Engine No:	G4LCGU676734
Make & Model:	HYUNDAI ACCENT (RB), 1.4 CVT (A)	Chassis No:	KMHCT41BTHU214070
Reg. Date:	11/10/2016 (Man. Year: 2016)	Odometer:	94185 km
Colour:	Blue		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,836.40	2,844.80	1,991.60	41.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,660.00	1,600.00	49.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,096.40	4,504.80	3,591.60	44.36
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	8,096.40	3,600.00	4,496.40	55.54
+ GST 9.00/9.00% (\$\$)	728.68	324.00	404.68	55.54
Nett Amount (\$\$)	8,825.08	3,924.00	4,901.08	55.54

INSPECTION

Date of Assignment:	26/08/2024	
Date Inspected:	27/08/2024	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2024)
Parts:	143	HYUNDAI ACCENT (RB) 1.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG6771P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	1,389.00 FL	*1,180.00 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	33.00 FL	*33.00 FL
3	1		*BOOTLID ACCENT EMBLEM	Necessary	36.00 FL	*36.00 FL
4	1		*BOOTLID LOCK	Not Necessary	143.00 FL	*- FL
5	1		*BOOTLID RH HINGE	Not Necessary	119.00 FL	*- FL
6	1		*BOOTLID LH HINGE	Not Necessary	119.00 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Not Necessary	101.00 FL	*- FL
8	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	70.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	546.00 FL	*546.00 FL
10	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	344.00 FL	*- FL
12	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	46.00 FL	*- FL
13	1		*REAR BUMPER LH SIDE RETAINER	Cracked	46.00 FL	*46.00 FL
14	1		*REAR BUMPER LH REFLECTOR	Not Necessary	58.00 FL	*- FL
15	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Damaged	248.00 FL	*248.00 FL
16	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Not Necessary	248.00 FL	*- FL
17	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	368.00 FL	*- FL
18	1		*END PANEL	Dented	578.00 FL	*578.00 FL
19	1		*END PANEL INNER GARNISH	Deformed	118.00 FL	*118.00 FL
20	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	50.00 FL	*20.00 FL
21	1		*REAR FENDER LH INNER TRIM	Torn	202.00 FL	*202.00 FL
22	1		*SET REAR FENDER LH INNER TRIM CLIPS	Necessary	60.00 FL	*30.00 FL
23	1		*REAR FENDER LH SPLASH SHIELD	Not Necessary	93.00 FL	*- FL
24	1		*SET REAR FENDER LH SPLASH SHIELD CLIPS	Not Necessary	40.00 FL	*- FL
25	1		*SPARE TYRE PANEL UPPER BOARD	Not Necessary	299.00 FL	*- FL
26	1		*LH TAILLAMP ASSY	Cracked	414.00 FL	*414.00 FL
27	1		*LH TAILLAMP PANEL	Repair	72.00 FL	*- FL
28	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	21.00 FL	*- FL
29	1		*LH TAILLAMP GASKET	Not Necessary	27.00 FL	*- FL
30	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,028.00	3,541.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,191.60	696.20
Total Parts (S\$)	4,836.40	2,844.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	60.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	60.00
5	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	120.00	60.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	80.00	50.00
7	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND COVERS TO ASSIST REPAIR	New	320.00	60.00
Gross Labour Cost (\$\$)			3,260.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >