

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080453/APA3Q2
Date: 14/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: DM24MCV0005979
Claimant Vehicle No : SGF8322D Insured Vehicle No : GBD9175A
Date of Loss: 30/07/2024 Nature of Claim: TP Claim No: MCV2024D0009416

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGF8322D
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4029736
Reg. Date: 28/04/2016 (Man. Year: 2015) Chassis No: RU11109733
Colour: Red Odometer: 165180 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,419.76	2,366.96	2,052.80	46.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,120.00	1,600.00	58.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,139.76	3,486.96	3,652.80	51.16
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	7,139.76	2,700.00	4,439.76	62.18
+ GST 9.00/9.00% (S\$)	642.58	243.00	399.58	62.18
Nett Amount (S\$)	7,782.34	2,943.00	4,839.34	62.18
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		3,574.00		

INSPECTION

Date of Assignment: 27/08/2024
Date Inspected: 27/08/2024 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF8322D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	910.20 FL	*910.20 FL
2	1		*FRONT RH DOOR BLACK TAPE	Necessary	26.40 FL	*26.40 FL
3	1		*FRONT RH DOOR GLASS OUTER MOULDING	Not Necessary	28.60 FL	*- FL
4	1		*FRONT RH DOOR MECHANISM LOCK	Not Necessary	221.70 FL	*- FL
5	1		*REAR LH FENDER	Repair	790.20 FL	*- FL
6	1		*REAR LH FENDER ARCH GARNISH	Cut	195.00 FL	*195.00 FL
7	1		*REAR RH DOOR	Dented	883.40 FL	*883.40 FL
8	1		*REAR RH DOOR BLACK TAPE	Necessary	29.80 FL	*29.80 FL
9	1		*REAR RH DOOR CHECKER	Not Necessary	50.40 FL	*- FL
10	1		*REAR RH DOOR GLASS OUTER MOULDING	Not Necessary	30.40 FL	*- FL
11	1		*REAR RH DOOR GLASS REGULATOR WITH MOTOR	Not Necessary	412.50 FL	*- FL
12	1		*REAR RH DOOR HINGE (LOWER)	Not Necessary	49.20 FL	*- FL
13	1		*REAR RH DOOR HINGE (TOP)	Not Necessary	49.20 FL	*- FL
14	1		*REAR RH DOOR INNER TRIM BOARD	Cracked	499.80 FL	*499.80 FL
15	1		*REAR RH DOOR LOCK STRIKER	Not Necessary	39.80 FL	*- FL
16	1		*REAR RH DOOR MECHANISM LOCK	Damaged	299.70 FL	*299.70 FL
17	1		*REAR RH DOOR OUTER HANDLE	Not Necessary	93.70 FL	*- FL
18	1		*REAR RH DOOR WEATHERSTRIP	Not Necessary	149.20 FL	*- FL
19	1		*REAR RH DOOR WEATHER STRIP (LOWER)	Not Necessary	29.20 FL	*- FL
20	1		*REAR RH DOOR WEATHER STRIP (VERTICAL)	Cut	39.40 FL	*39.40 FL
21	1		*ROCKER GARNISH RH	Not Necessary	471.90 FL	*- FL
22	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*SET REAR RH FENDER ARCH GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
25	1		*SET ROCKER GARNISH RH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,479.70	2,943.70
- List Item Discount on L Items 20.00/20.00% (\$)	1,059.94	576.74
Total Parts (\$)	4,419.76	2,366.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	0.00
2	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	140.00	120.00
3	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
4	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00
5	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	0.00
Gross Labour Cost (\$\$)			2,720.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >