



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PD 126K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT/DEFORMED	\$720.00	\$720.00
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	\$162.00	\$0.00
10	FRONT BUMPER CLIPS	NECESSARY	\$50.00	\$50.00
1	FRONT CORNER PANEL RH	TO REPAIR SEE LABOUR	\$306.00	\$0.00
1	FRONT WINDSCREEN PILLAR RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	HEADLAMP RH	SCRATCHED	\$850.00	\$850.00
1	WING MIRROR ASSY RH	BROKEN	\$680.00	\$680.00
1	FRONT DOOR RH	DENTED/BENT	\$1,630.00	\$1,630.00
1	FRONT DOOR CHECKER RH	TWISTED	\$153.00	\$153.00
1	FRONT DOOR WEATHERSTRIP RH	NECESSARY	\$245.00	\$245.00
1	FRONT DOOR STEP GARNISH RH	TORN	\$187.00	\$187.00
1	FRONT WHEEL HUB CAP RH	CRACKED	\$180.00	\$180.00
1	FRONT MUDFLAP RH	DISTORTED	\$165.00	\$165.00
1	B PILLAR RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	TAILLAMP RH	NOT NECESSARY	\$330.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,414.50)	(\$1,215.00)
			\$4,243.50	\$3,645.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	ADVERTISEMENT STICKER RH (SN)	NECESSARY	\$300.00	\$300.00
			\$300.00	\$300.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL RH, FRONT WINDSCREEN PILLAR RH, B PILLAR RH, REAR FENDER RH AND REAR BUMPER		\$1,200.00	\$1,000.00
	TO RESPRAY AFFECTED AREAS		\$1,200.00	\$1,200.00
	TO REMOVE AND TRANSFER DOOR COMPONENTS		\$150.00	\$60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS		\$30.00	\$20.00
	RUST PROOFING		\$100.00	\$50.00
			\$2,680.00	\$2,330.00
GRAND TOTAL			\$7,223.50	\$6,275.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,000.00
Report Ref No: CS/TP24080460/Uqp3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.