

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24080461/ANP3E2
Date: 23/10/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBF4531C	Insured Vehicle No :	GBE5055J
Date of Loss:	26/08/2024	Nature of Claim:	TP
		Claim No:	DMCV2400169H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4531C	Engine No:	1KD2592929
Make & Model:	TOYOTA HIACE, 3.0 D 3.0 (M)	Chassis No:	KDH2010190610
Reg. Date:	27/10/2016 (Man. Year: 2015)	Odometer:	286452 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,238.05	9,732.42	12,505.63	56.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,150.00	2,840.00	3,310.00	53.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,388.05	12,572.42	15,815.63	55.71
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	28,388.05	10,000.00	18,388.05	64.77
+ GST 9.00/9.00% (S\$)	2,554.92	900.00	1,654.92	64.77
Nett Amount (S\$)	30,942.97	10,900.00	20,042.97	64.77

INSPECTION

Date of Assignment:	27/08/2024	
Date Inspected:	27/08/2024 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Oct 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 D 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4531C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*AIRCON BLOWER ASSY	Cracked	1,053.40 FL	*1,053.40 FL
2	1	*AIRCON COOLING COIL ASSY	Not Necessary	3,837.80 FL	*- FL
3	1	*FRONT BONNET	Dented	1,082.50 FL	*866.00 FL
4	1	*FRONT BONNET LOGO EMBLEM	Necessary	59.60 FL	*59.60 FL
5	2	*FRONT BONNET HINGES L/R	Not Necessary	124.60 FL	*- FL
6	2	*FRONT BONNET INNER RUBBER STOPPER L/R	Not Necessary	36.80 FL	*- FL
7	1	*FRONT BONNET MECHANISM LOCK	Not Necessary	99.80 FL	*- FL
8	1	*FRONT BUMPER	Distorted	573.60 FL	*573.60 FL
9	2	*FRONT BUMPER FOGLAMP GARNISH L/R	Not Necessary	212.00 FL	*- FL
10	1	*FRONT BUMPER INNER REINFORCEMENT VERTICAL BRACKET LH	Not Necessary	157.00 FL	*- FL
11	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	188.70 FL	*- FL
12	1	*FRONT BUMPER REINFORCEMENT	Dented	379.40 FL	*379.40 FL
13	1	*FRONT BUMPER REINFORCEMENT BRACKET LH	Not Necessary	120.70 FL	*- FL
14	1	*FRONT BUMPER SIDE RETAINER L/R	N/S Smashed	303.60 FL	*151.80 FL
15	2	*FRONT BUMPER TOW HOOK COVER L/R	Not Necessary	60.20 FL	*- FL
16	1	*FRONT DASH PANEL	Repair	909.20 FL	*- FL
17	1	*FRONT DASH PANEL INSULATOR	Not Necessary	281.00 FL	*- FL
18	1	*FRONT DASHBOARD	Not Necessary	1,028.50 FL	*- FL
19	1	*FRONT DASHBOARD REINFORCEMENT	Not Necessary	805.40 FL	*- FL
20	1	*FRONT FLOOR PANEL	Repair	1,270.60 FL	*- FL
21	1	*FRONT FLOOR PANEL WIRE HARNESS	Not Necessary	526.70 FL	*- FL
22	1	*FRONT FLOOR PANEL WIRE HARNESS COVER	Cracked	174.50 FL	*174.50 FL
23	1	*FRONT FUSE BOX	Not Necessary	651.70 FL	*- FL
24	1	*FRONT GRILLE BASE	Missing	602.60 FL	*602.60 FL
25	1	*FRONT GRILLE LOWER OUTER COVER	Missing	406.70 FL	*406.70 FL
26	1	*FRONT GRILLE TOP OUTER COVER	Missing	235.00 FL	*235.00 FL
27	2	*FRONT HEADLAMP L/R	Cracked	7,959.00 FL	*5,138.20 FL
28	1	*FRONT LH CORNER PANEL	Dented	284.60 FL	*284.60 FL
29	1	*FRONT LH CORNER PANEL BRACKET	Not Necessary	60.10 FL	*- FL
30	1	*FRONT LH DOOR	Dented	2,245.20 FL	*1,815.00 FL
31	1	*FRONT LH DOOR CHECKER	Not Necessary	96.50 FL	*- FL
32	1	*FRONT LH DOOR HINGE (LOWER)	Not Necessary	199.40 FL	*- FL
33	1	*FRONT LH DOOR INNER ARCH SEAL	Not Necessary	67.10 FL	*- FL
34	1	*FRONT LH DOOR PILLAR (CENTER)	Repair	573.70 FL	*- FL
35	1	*FRONT LH DOOR PILLAR (OUTER)	Dented	587.20 FL	*587.20 FL
36	1	*FRONT LH DOOR WIRE HARNESS	Not Necessary	526.70 FL	*- FL
37	1	*FRONT LH DOOR WIRE HARNESS COVER	Cracked	948.10 FL	*268.00 FL
38	1	*FRONT LH STEP GARNISH	Cracked	175.40 FL	*175.40 FL
39	1	*FRONT LH STEP PANEL	Buckled	78.90 FL	*78.90 FL
40	1	*FRONT SUPPORT PANEL (TOP PANEL)	Not Necessary	433.90 FL	*- FL
41	1	*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
42	1	*SET FRONT GRILLE CLIPS	Necessary	40.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT LH DOOR COMPANY STICKER	Necessary	25.00 FS	*25.00 FS
44	1		*SET FRONT LH STEP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$)	29,592.40	12,944.90
				- List Item Discount on L Items 25.00/25.00% (\$)	7,354.35	3,212.48
				Total Parts (\$)	22,238.05	9,732.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)	New	80.00	30.00
2	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	80.00	60.00
3	TO REMOVE, CHANGE DASHBOARD FASCIA AND TRANSFER WHERE NECESSARY	New	450.00	250.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	2,600.00	1,000.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,800.00	1,400.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	140.00	100.00
Gross Labour Cost (S\$)			6,150.00	2,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >