

REF: CS/ICS24080461/Anp3 (GBF 4531C)

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: ~~Estim~~ \_\_\_\_\_OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MVTo In ~~Vehicle~~ No: \_\_\_\_\_at W ~~Of~~ / m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBF4531C Yr Regt: 2016, Oct.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.D. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 286452 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDH2010190610

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15CR: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 27/08/24Survey held at Twin Car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ECUSCOE ExpiryEstimate given during: Yes (✓)  
1st Survey: No ( )

MV:

PV:

Nett:

Adrian confirmed lump sum \$10000 and 9 days  
(red, \$13605.9, 57%)081 B.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 9

1)

☐

Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format:

Report Form 1, 2, 3, 4, 5, 6, 7, 8, 9, 10

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS  
92 COMMONWEALTH DRIVE #01-716  
COMMONWEALTH 16  
SINGAPORE 140092

Contact : 96391418

## TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

### Parts and Labour Assessment

| Description of part                                             | Qty | Unit Price | Amount     |
|-----------------------------------------------------------------|-----|------------|------------|
| AIRCON BLOWER ASSY <i>cracked</i>                               | 1   | 1053.40    | 1,053.40 ✓ |
| AIRCON COOLING COIL ASSY <i>new</i>                             | 1   | 3837.80    | 3,837.80 + |
| FRONT BONNET <i>Dented</i>                                      | 1   | 1082.50    | 1,082.50 ✓ |
| FRONT BONNET 'LOGO' EMBLEM <i>new</i>                           | 1   | 59.60      | 59.60 ✓    |
| FRONT BONNET HINGES L/R <i>new</i>                              | 2   | 62.30      | 124.60 +   |
| FRONT BONNET INNER RUBBER STOPPER L/R <i>new</i>                | 2   | 18.40      | 36.80 +    |
| FRONT BONNET MECHANISM LOCK <i>new</i>                          | 1   | 99.80      | 99.80 +    |
| FRONT BUMPER <i>Distorted</i>                                   | 1   | 573.60     | 573.60 ✓   |
| FRONT BUMPER FOGLAMP GARNISH L/R <i>new</i>                     | 2   | 106.00     | 212.00 +   |
| FRONT BUMPER INNER REINFORCEMENT VERTICAL BRACKET LH <i>new</i> | 1   | 157.00     | 157.00 +   |
| FRONT BUMPER LOWER GRILLE <i>new</i>                            | 1   | 188.70     | 188.70 +   |
| FRONT BUMPER REINFORCEMENT <i>Dented</i>                        | 1   | 379.40     | 379.40 ✓   |
| FRONT BUMPER REINFORCEMENT BRACKET LH <i>new</i>                | 1   | 120.70     | 120.70 +   |
| FRONT BUMPER SIDE RETAINER L/R <i>LH smashed</i>                | 2   | 151.80     | 303.60 ✓   |
| FRONT BUMPER TOW HOOK COVER L/R <i>new</i>                      | 2   | 30.10      | 60.20 +    |
| FRONT DASH PANEL <i>Reis</i>                                    | 1   | 909.20     | 909.20 +   |
| FRONT DASH PANEL INSULATOR <i>new</i>                           | 1   | 281.00     | 281.00 +   |
| FRONT DASHBOARD <i>new</i>                                      | 1   | 1028.50    | 1,028.50 + |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS  
 92 COMMONWEALTH DRIVE #01-716  
 COMMONWEALTH 16  
 SINGAPORE 140092

Contact : 96391418

## TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

|                                      |           |   |         |          |   |
|--------------------------------------|-----------|---|---------|----------|---|
| FRONT DASHBOARD REINFORCEMENT        | asc in    | 1 | 805.40  | 805.40   | + |
| FRONT FLOOR PANEL                    | Repair    | 1 | 1270.60 | 1,270.60 | + |
| FRONT FLOOR PANEL WIRE HARNESS       | asc in    | 1 | 526.70  | 526.70   | + |
| FRONT FLOOR PANEL WIRE HARNESS COVER | changed   | 1 | 174.50  | 174.50   | ✓ |
| FRONT FUSE BOX                       | asc in    | 1 | 651.70  | 651.70   | + |
| FRONT GRILLE BASE                    | } Missing | 1 | 602.60  | 602.60   | ✓ |
| FRONT GRILLE LOWER OUTER COVER       |           | 1 | 406.70  | 406.70   | ✓ |
| FRONT GRILLE TOP OUTER COVER         |           | 1 | 235.00  | 235.00   | ✓ |
| FRONT HEADLAMP L/R                   | changed   | 2 | 3979.50 | 7959.00  | ✓ |
| FRONT LH CORNER PANEL                | Dented    | 1 | 284.60  | 284.60   | ✓ |
| FRONT LH CORNER PANEL BRACKET        | asc in    | 1 | 60.10   | 60.10    | + |
| FRONT LH DOOR                        | Dented    | 1 | 2245.20 | 2,245.20 | ✓ |
| FRONT LH DOOR CHECKER                | 3 for     | 1 | 96.50   | 96.50    | + |
| FRONT LH DOOR HINGE (LOWER)          | for       | 1 | 199.40  | 199.40   | + |
| FRONT LH DOOR INNER ARCH SEAL        | asc in    | 1 | 67.10   | 67.10    | + |
| FRONT LH DOOR PILLAR (CENTER)        | Repair    | 1 | 573.70  | 573.70   | + |
| FRONT LH DOOR PILLAR (OUTER)         | Dented    | 1 | 587.20  | 587.20   | ✓ |
| FRONT LH DOOR WIRE HARNESS           | asc in    | 1 | 526.70  | 526.70   | + |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS  
 92 COMMONWEALTH DRIVE #01-716  
 COMMONWEALTH 16  
 SINGAPORE 140092

Contact : 96391418

## TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

|                                               |   |        |                   |
|-----------------------------------------------|---|--------|-------------------|
| FRONT LH DOOR WIRE HARNESS COVER <i>could</i> | 1 | 948.10 | 948.10 <i>218</i> |
| FRONT LH STEP GARNISH <i>could</i>            | 1 | 175.40 | 175.40 ✓          |
| FRONT LH STEP PANEL <i>Buckled</i>            | 1 | 78.90  | 78.90 ✓           |
| FRONT SUPPORT PANEL (TOP PANEL) <i>near</i>   | 1 | 433.90 | 433.90 ✓          |
| Subtotal before discount                      |   |        | 23,041.20         |
| Percentage discount 25%                       |   |        | 5,760.30          |
| <b>Sub-total 1</b>                            |   |        | 17,280.90         |
| FRONT BUMPER CLIPS - SET <i>3</i>             | 1 | 80.00  | 80.00 <i>30</i>   |
| FRONT GRILLE CLIPS - SET <i>3</i>             | 1 | 40.00  | 40.00 <i>30</i>   |
| FRONT LH DOOR COMPANY STICKER <i>new</i>      | 1 | 25.00  | 25.00 ✓           |
| FRONT LH STEP GARNISH CLIPS - SET <i>new</i>  | 1 | 30.00  | 30.00 <i>10</i>   |
| Subtotal before discount                      |   |        | 175.00            |
| Percentage discount 0%                        |   |        | 0.00              |
| <b>Sub-total 2</b>                            |   |        | 175.00            |
| <b>Parts-total</b>                            |   |        | 17,455.90         |

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

80.00 *30*

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80.00 *60*

To remove, change dashboard fascia and transfer where necessary.

450.00 *250*

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS  
92 COMMONWEALTH DRIVE #01-716  
COMMONWEALTH 16  
SINGAPORE 140092

Contact : 96391418

## TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

2,600.00 1000

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

2,800.00 10400

To apply anti-rust chemical on repaired and replaced panel.

140.00 100

**Labour Total**

**6,150.00**

**Parts & Labour Total**

**23,605.90**

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 4

Adrian C  
H/S 29/08/24  
09 Days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: